



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/11/20
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2015	Site #:	CK-2015	Road Name:	CANTELON CREEK	Inspection Date:	2013/10/31
KM:	9.00	User km:	9.00	Crossing Name:	Not Known	Next Inspection Date:	2015/10/31
Project File ID #:	8124	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right):	Crib, Log or Untreated Timber		
Total Length (metres):	9.1	# Spans:	1	Span Length(s) (metres):	0		
UTM Zone:	10	UTM Easting:	610706	UTM Northing:	5452533		
Inspector Name:	T. Miller			Year Built:	1991		
Access:	Helicopter or ATV Coordinates updated by M.Kirk, Onsite Engineering Ltd, Jan 2011						

ABUTMENTS

Bearings	Poor	crushing timber sill
Bracing	Not Applicable	
Ballast Wall	Fair	logs
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	rotten, crushing timbers
Fill	Fair	
Hardware	Not Applicable	
Log/Timber Cribs	Fair	
Piles or Posts	Not Applicable	
Riprap	Fair	
Tie-backs	Fair	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left	2	
Delineator Missing Right	2	
Fender Condition	Poor	old rotten logs
Posted Load Rating	not	not posted
Road Surface	Poor	potholes

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	rotten
------------------------	------	--------



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/11/20
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2015	Site #:	CK-2015	Road Name:	CANTELON CREEK	Inspection Date:	2013/10/31			
Deck to Girder Bolts	Poor	loose								
Hardware	Poor	loose rail								
Hand Rails/Walkouts	Not Applicable									
Nails	Poor	protruding								
Overall Deck Condition	Poor	replace								
Running Planks	Not Applicable									
Sub Deck	Poor	rotten								
Ties	Poor	rotten								
SUPERSTRUCTURE										
Span 1										
Bracing	Poor	due to twist								
Diaphragms	Poor	due to twist								
Girders	Poor	4 steel I beams, painted and slightly twisting								
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.4	Estimated Present Water Level Width:	4.0						
	Estimated High Water Level Clearance:	0.5								
HAZARDS	High Water:	Yes	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Recommended	High	\$1.00	replace entire structure with industrial activity					
	2	Recommended	High	\$1.00	post load rating sign					
MONITORS	#	Description								
GENERAL	Professional Inspection Required?	No	Regional Review Date:	2013/11/19	P. Eng Reviewer Name:	Tyson Miller				
	Replacement Date for full log haul traffic (year):	2006	Replacement Date for light vehicle traffic (year):	2011						
	Current Load Rating GVW (tonnes):	2	Design Load GVW (tonnes):	54	Design Vehicle Config.:	L60				
	Inspector's Estimated Full Log Haul Replacement (year):									
	Inspector's Comment:									
Corporate Bridge Register (CBR)										



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/11/20
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2015	Site #:	CK-2015	Road Name:	CANTELON CREEK	Inspection Date:	2013/10/31
PEng Reviewer's Comment:	Present load rating of 2 tonnes to continue. Please post.						
District Staff Comment:	 						

Nov 20 / 2013





