



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2013/11/13
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2255	Site #:	CK-2255	Road Name:	SQUEAH	Inspection Date:	2013/11/06
KM:	7.90	User km:	8.60	Crossing Name:	not known	Next Inspection Date:	2013/10/04
Project File ID #:	6092	Br.	01	Forest District:	Chilliwack Forest District		
Deck Type:	Gravel			Running Surface:	Gravel		
Superstructure	Log Stringers			Abutments (Left/Right):	Crib, Log or Untreated Timber		
Total Length (metres):	15.5	# Spans:	1	Span Length(s) (metres):	0		
UTM Zone:	10	UTM Easting:	615180	UTM Northing:	5479162		
Inspector Name:	T. Miller			Year Built:	1992		
Access:	Updated by M.Kirk, Onsite Engineering Ltd, Feb 2011						

ABUTMENTS

Bearings	Fair	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Poor	see crib notes
Fill	Fair	
Hardware	Poor	loose lashing
Log/Timber Crib	Poor	old and rotting
Piles or Posts	Not Applicable	
Riprap	Poor	scout left D/S
Tie-backs	Poor	rotten
Wing Wall	Not Applicable	

APPROACHES

Alignment	Poor	very tight HC at both approaches
Bridge Ahead Signs Missing	2	
Brushing Required	Yes	
Delineator Missing Left	1	
Delineator Missing Right	1	
Fender Condition	None	
Posted Load Rating	not	not posted
Road Surface	Fair	

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	logs, too low
------------------------	------	---------------



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2013/11/13
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2255	Site #:	CK-2255	Road Name:	SQUEAH	Inspection Date:	2013/11/06			
Gravel Deck Depth (metres)	0.4									
Gravel Surface	Fair	0.4								
Hardware	Poor	gut lashed but logs rotten								
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Poor	replace								
STRINGERS										
Span 1										
Stringer #	Diameter or Width X Depth	Peeled	Rot Depth (Bottom)	Rot Depth (Side)	Rot Depth (Top)	Wood Species	Comments			
1	650	No	150			Fd	conk			
2	650	No	100			Fd	pocket rot noted			
3	670	No	60			Fd				
4	820	No	140			Fd				
5	720	No	150			Fd				
6	1100	No	150			Fd	200mm rot, conk			
7	780	No	150			Fd	200mm rot, conk			
8	760	No	150			Fd	300mm rot, conk			
Log Curbs	Poor	rotten								
Needle Beam(s) and Shims	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.4	Estimated Present Water Level Width:		7.0					
	Estimated High Water Level Clearance:	3.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Recommended	High	\$1.00	Post and block access.					
MONITORS	#	Description								
	1	for failure								
GENERAL	Professional Inspection Required?	No	Regional Review Date:	2013/11/06	P. Eng Reviewer Name:	Tyson Miller				
	Replacement Date for full log haul traffic (year):	2008	Replacement Date for light vehicle traffic (year):	2013						
	Current Load Rating GVW (tonnes):	0	Design Load GVW (tonnes):	68	Design Vehicle Config.:	L75				
	Inspector's Estimated Full Log Haul Replacement (year):									
	Inspector's Comment:									
Corporate Bridge Register (CBR)										



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2013/11/13
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B

Structure #:	CK-2255	Site #:	CK-2255	Road Name:	SQUEAH	Inspection Date:	2013/11/06
PEng Reviewer's Comment:	Structure condemned, 0 tonnes load rating. Please post and block access.						
District Staff Comment:							

[Handwritten signature]
Nov 13/2013







