

CK-2022

CHEHALIS 15.2km

2014 Inspection

CBR iPad Offline Ver 0.17

CBR Data

Latitude Longitude
49°20'48.09" -122°1'26.8"

Road Name CHEHALIS
User km 15.2
Current Load Rating (tonnes) 91
Structure Class Temporary Bridge
Portable N
Superstructure Steel I-beam
Deck Type Timber - Untreated
Abutment Left Concrete Precast
Abutment Right Concrete Precast
Spans 1
Total Length (m) 37.6
Deck Width (m) 4.8

Updated Data

Latitude Longitude
°0'0" -122°1'26.8"
HD Diff. (m) 5493248.8 Accuracy (m)
Chehalis
15.2
L100 or 91 tonnes
Temporary Bridge
N
Steel I-beam
Timber – Untreated
Concrete Cast in Place
Concrete Lock Blocks
1
36.9
4.9

Inspection

Date of Inspection 2014-09-09 10:08:14 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspection Comments

P.Eng Comments

The deck is nearing the end of its industrial life - appears to be 7-8 years old and replaced at the time the town (right) abutment work was completed. The running planks are in poor shape, especially in the truck wheel path location. The woods (left) abutment requires periodic inspection, especially when active, noting upstream scour and CIP condition. Short term repair is to replace worn planks and place wear strips on top or a complete replacement of the existing planks. Replace missing delineators and replace left approach fenders with larger diameter logs. Monitor left abutment. The present load rating of L100 or 91 tonnes can continue with the deck repairs noted.



CK-2022

CHEHALIS 15.2km

2014 Inspection

CBR iPad Offline Ver 0.17

Approach

Alignment Good

 Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

 Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2

 Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Fair

left approach fenders low - consider replacing with larger diameter logs

Posted Load Rating 91

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Fair

old CIP left side, newer lock blocks right side - 4 rows with CIP levelling pad

Caps or Sills Fair

log left side, concrete right side

Piles or Posts N/A

Ballast Wall Fair

logs left, concrete right

Wing Wall Fair

old logs left side, lock blocks downstream right bank

Bracing N/A

Hardware Fair

Geogrid between each row of blocks on right side

Fill Fair

Riprap Fair

Bearings Fair

rubber pads on right bearing have slight bulging

CK-2022

CHEHALIS 15.2km

2014 Inspection

CBR iPad Offline Ver 0.17

Corrosion Protection N/A

Deck

Running Surface N/A

Running Planks Fair - poor fair in middle and on sides but fair to poor on wheel path - wearing through and holes starting to show

Sub Deck N/A

Ties Fair

Nails Fair poor on wheel path as they are protruding in spots

Deck to Girder Bolts

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts N/A

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

CK-2022

CHEHALIS 15.2km

2014 Inspection

CBR iPad Offline Ver 0.17

Steel/Concrete

Girders	Fair	painted and spliced
Diaphragms	Fair	6 bays, welded - left end delaminating
Bracing	Fair	welded
Under Trussing	N/A	
Hardware	Fair	
Welded/grouted shear connectors	N/A	

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m) Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Comment
-----------------	---------	--------	---------------	----------------	---------

CK-2022

CHEHALIS 15.2km

2014 Inspection

CBR iPad Offline Ver 0.17

Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	13.	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

The deck appears to have been replaced in 2007 when the town abutment work was completed.

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	replace missing delineators
2	High	replace sinking fenders on left approach
3	High	replace rotting and worn decking on wheel path and place a wear deck top or complete replacement of existing planks

Monitor Item

Monitor Description

Monitoring Frequency

1	left abutment	Anually
2		
3		

Sketch
(Select Signature)

CK-2022

CHEHALIS 15.2km

2014 Inspection



Approach from Right Bank when facing downstream



Deck



nails starting to protrude



Deck

CK-2022

CHEHALIS 15.2km

2014 Inspection



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



superstructure



Deck

CK-2022

CHEHALIS 15.2km

2014 Inspection



Downstream Profile



Left Bank Abutment when facing downstream