

CK-2072

BENCH 5.2km

2015 Inspection



CBR iPad Offline Ver 0.20

CBR Data

Latitude	Longitude
49°5'9.89"	-121°42'9.5"
Crossing Name	Wells Ranch Creek
FSR #	5127
Branch #	10
Road Name	BENCH
User km	5.2
Current Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	12.2
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°5'10.18"	-121°42'9.5"
HD Diff. (m)	64.7
Accuracy (m)	10

Concrete Removable

Inspection

Date of Inspection 2015-06-24 12:40:56 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace guardrail, risers and blocks. Repair damaged deck panels. Present load rating of L75 or 68 tonnes to continue.

T. W. Miller
Nov 18/2015



P.Eng Seal

CK-2072

BENCH 5.2km

2015 Inspection



CBR iPad Offline Ver 0.20

Approach

Alignment Fair

VC at both approaches

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y minor

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 68040

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall N/A

Bracing Good

Hardware Poor loose rail bolts

Fill Good

Riprap Good

Bearings Good

Corrosion Protection N/A

CK-2072

BENCH 5.2km

2015 Inspection



CBR iPad Offline Ver 0.20

Deck

Running Surface	Fair	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	Good	
Concrete Deck	Fair	panel 1 on left approach has damage on ballast wall side where rebar is exposed and rusting - same for right approach
Grout Pockets	Fair	
Deck Joints	Good	compression seals all in place
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	rotting risers and blocks
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Poor	due to rail
Gravel Depth (mm)		

CK-2072

BENCH 5.2km

2015 Inspection



CBR iPad Offline Ver 0.20

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good

Bracing Good

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2072

BENCH 5.2km

2015 Inspection



CBR iPad Offline Ver 0.20

Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	4.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Medium	replace guardrail, risers, and blocks
---	--------	---------------------------------------

2	Medium	repair damaged deck panels
---	--------	----------------------------

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1	panel 1 on both approaches - exposed rebar	Routine Inspection
---	--	--------------------

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)

CK-2072

BENCH 5.2km

2015 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



deck attachment

CK-2072

BENCH 5.2km

2015 Inspection



small panel damage



spalling concrete



small panel damage



left abutment panel damage

CK-2072

BENCH 5.2km

2015 Inspection



panel 1 on right bank damage



Right Bank Abutment when facing downstream



superstructure and left abutment



Structure ID