



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 5
Date Printed: 2016/01/06
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A
File:

Structure #:	CK-2213	Site #:	CK-2213	Road Name:	PEERS CREEK	Inspection Date:	2015/10/22
KM:	0.20	User km:	0.20	Crossing Name:	Coquihalla River	Next Inspection Date:	2018/10/22
Project File ID #:	8126	Br.	01	Forest District:	Chilliwack Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Concrete Cast in Place		
Total Length (metres):	100.0	# Spans:	3	Span Length(s) (metres):	15.4, 38.9, 45.7		
UTM Zone:	10	UTM Easting:	622149	UTM Northing:	5471689		
Inspector Name:	T. Miller			Year Superstructure Installed:	1988		
Access:	Driving East from Hope on Highway #5, turn right on Peers Creek FSR.						

ABUTMENTS

Bearings	Good	minor deformation on the woods end with corrosion noted on plates
Bracing	Not Applicable	
Ballast Wall	Fair	
Concrete Cast in Place	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Unrated	no cap or sill
Fill	Fair	material loss under woods end wall
Hardware	Good	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Fair	T jct at camp end and HC on woods end
Bridge Ahead Signs Missing	1	
Brushing Required	Yes	woods end
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	missing woods approach fenders
Posted Load Rating	not	not posted
Road Surface	Fair	camp end paved, woods gravel

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 5
Date Printed: 2016/01/06
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A
File:

Structure #:	CK-2213	Site #:	CK-2213	Road Name:	PEERS CREEK	Inspection Date:	2015/10/22
--------------	---------	---------	---------	------------	-------------	------------------	------------

DECK

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	combination of concrete and timber risers
Deck Joints	Fair	water getting through some joints
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Good	

Span 2

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Fair	combination of concrete and timber risers - minor deterioration noted on 1 concrete riser
Deck Joints	Fair	water getting through some joints
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Good	

Span 3

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Good	combination of concrete and timber risers
Deck Joints	Fair	water getting through some joints
Grout Pockets	Good	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	
Running Surface	Good	

PIERS

Pier 1

Bearings	Good	
Bracing or Sheathing	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 5
Date Printed: 2016/01/06
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A
File:

Structure #:	CK-2213	Site #:	CK-2213	Road Name:	PEERS CREEK	Inspection Date:	2015/10/22
--------------	---------	---------	---------	------------	-------------	------------------	------------

Caps	Fair	minor spalling around the corners
Cribs	Not Applicable	
Dolphins	Not Applicable	
Hardware	Not Applicable	
Overall	Fair	
Piles or Posts	Good	
Riprap	Not Applicable	
Wall	Not Applicable	

Pier 2

Bearings	Fair	bearings appear fair, however the concrete cap is in poor condition
Bracing or Sheathing	Fair	
Caps	Poor	concrete below girder 2 failing
Cribs	Not Applicable	
Dolphins	Not Applicable	
Hardware	Not Applicable	
Overall	Fair	
Piles or Posts	Good	channel degradation has lead to debris accumulations under bottom concrete diaphragm
Riprap	Not Applicable	
Wall	Not Applicable	

SUPERSTRUCTURE

Span 1

Bracing	Not Applicable	
Diaphragms	Good	
Girders	Good	painted steel
Hardware	Good	
Under Trussing	Not Applicable	

Span 2

Bracing	Not Applicable	
Diaphragms	Fair	concrete diaphragm at pier 2 is delaminating on woods end face
Girders	Good	concrete girders
Hardware	Not Applicable	
Under Trussing	Not Applicable	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 4 of 5
Date Printed: 2016/01/06
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A
File:

Structure #:	CK-2213	Site #:	CK-2213	Road Name:	PEERS CREEK	Inspection Date:	2015/10/22
--------------	---------	---------	---------	------------	-------------	------------------	------------

Span 3

Bracing	Good	
Diaphragms	Good	
Girders	Good	outsides are painted
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	22.0
	Estimated High Water Level Clearance:	3.0		

HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	Medium	\$5,000.00	repair the spalling concrete and delamination on the pier 2 cap.
	2	Required	Medium	\$3,000.00	Repair the concrete delamination on the span 2 end diaphragm at pier 2
	3	Required	Medium	\$250.00	replace the missing bridge ahead sign
	4	Required	Medium	\$1,000.00	brush the woods end approach
	5	Required	Medium	\$3,000.00	add concrete no post barriers to the woods end approach
	6	Required	High	\$2,000.00	remove the debris accumulation from under the pier 2 cast in place concrete diaphragm

MONITORS	#	Description

GENERAL	Inspector's Comment:	There is channel degradation under the pier 2 cast in place concrete diaphragm which has lead to debris accumulations between the H-piles.
---------	----------------------	--

GENERAL	PEng's Comment:	Repair the spalling and delaminating concrete on the pier 2 cap. Repair the delaminating concrete on the span 2 end diaphragm. Remove the debris accumulations from under the pier 2 concrete diaphragm. Brush the woods end approach and place concrete no post barriers. Replace the missing bridge ahead sign. Present load rating of L60 or 54 tonnes to continue.
---------	-----------------	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 5 of 5
Date Printed: 2016/01/06
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001A
File:

Structure #:	CK-2213	Site #:	CK-2213	Road Name:	PEERS CREEK	Inspection Date:	2015/10/22		
GENERAL	Replacement Date for full log haul traffic (year):			2048	Replacement Date for light vehicle traffic (year):			2048	
	Current Inspection Load Rating:		54	Design Load GVW (tonnes):		54	Design Vehicle Config.:		L60
	Professional Inspection Required?		No	Report Status:		Reviewed By Tyson Miller on 1/6/2016 9:59:32AM			



06/01/2016

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.

CK-2213

PEERS CREEK 0.2km

2015 Inspection



Approach from Left Bank when facing downstream



span joints



Guard Rail on span 1



Deck 1

CK-2213

PEERS CREEK 0.2km

2015 Inspection



Deck 2



Deck 3



Guardrail on span 2



Guardrail on span 3

CK-2213

PEERS CREEK 0.2km

2015 Inspection



steel separation on span 3 at road surface



right bank upstream girder flare



Approach from Right Bank when facing downstream



right bank upstream girder flare

CK-2213

PEERS CREEK 0.2km

2015 Inspection



right bank main span girder bearing



right bank downstream girder flare



right bank downstream girder flare



Right Bank Abutment when facing downstream

CK-2213

PEERS CREEK 0.2km

2015 Inspection



span 3 upstream profile



pier 2



span 3 splice plates



log under pier 2

CK-2213

PEERS CREEK 0.2km

2016 Inspection



pier 2 spalling concrete



pier 1 and left abutment



log under pier 2



Upstream Profile of span 2

CK-2213

PEERS CREEK 0.2km

2016 Inspection



pier 1



pier 2



Left Bank Abutment when facing downstream



pier 1

CK-2213

PEERS CREEK 0.2km

2016 Inspection



span 2 superstructure, pier 2