



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 4
Date Printed: 2016/01/07
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B
File:

Structure #:	CK-2261	Site #:	CK-2261	Road Name:	STAVE RIVER	Inspection Date:	2015/09/23
KM:	8.50	User km:	8.50	Crossing Name:	Winslow Creek	Next Inspection Date:	2016/09/23
Project File ID #:	8013	Br.	01	Forest District:	Chilliwack Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated Timber		
Total Length (metres):	36.3	# Spans:	2	Span Length(s) (metres):	0, 0		
UTM Zone:	10	UTM Easting:	555324	UTM Northing:	5480782		
Inspector Name:	T. Miller			Year Superstructure Installed:	1986		
Access:	Updated by M.Kirk, Onsite Engineering Ltd, Feb 2011						

ABUTMENTS

Bearings	Poor	top logs crushing
Bracing	Not Applicable	
Ballast Wall	Fair	logs left abutment, concrete right abutment
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	fair to poor
Fill	Fair	
Hardware	Poor	loose lashing
Log/Timber Cribbs	Poor	4x left, 5x right - top logs on both ends are rotting
Piles or Posts	Not Applicable	
Riprap	Poor	very little riprap in front of cribbs
Tie-backs	Fair	fair to poor
Wing Wall	Poor	only left abutment and rotting and slumping

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	2	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Fair	missing downstream right approach - pushed down bank
Posted Load Rating	not	not posted
Road Surface	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 4
Date Printed: 2016/01/07
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B
File:

Structure #:	CK-2261	Site #:	CK-2261	Road Name:	STAVE RIVER	Inspection Date:	2015/09/23
--------------	---------	---------	---------	------------	-------------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Poor	risers and guardrail in poor condition
Deck to Girder Bolts	Fair	
Hardware	Poor	loose rail bolts
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Poor	due to condition of guardrail system
Running Planks	Fair	
Sub Deck	Fair	
Ties	Fair	showing signs of rot

Span 2

Curb Rail/Blocks/Posts	Fair	some risers and guardrail in poor shape
Deck to Girder Bolts	Fair	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Fair	fair to poor as wheel path deck planks are wearing
Sub Deck	Fair	
Ties	Fair	showing signs of rot

PIERS

Pier 1

Bearings	Poor	rotting and crushing logs - approx 80mm difference in deck elevation from upstream to downstream - downstream lower
Bracing or Sheathing	Not Applicable	
Caps	Poor	rotting and crushing
Cribs	Poor	5x and rotting
Dolphins	Not Applicable	
Hardware	Poor	loose lashing
Overall	Poor	top logs in poor condition
Piles or Posts	Fair	short posts on right span (span 2)

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 4
Date Printed: 2016/01/07
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B
File:

Structure #:	CK-2261	Site #:	CK-2261	Road Name:	STAVE RIVER	Inspection Date:	2015/09/23
--------------	---------	---------	---------	------------	-------------	------------------	------------

Riprap	Fair	
Wall	Not Applicable	
SUPERSTRUCTURE		
Span 1		
Bracing	Fair	
Diaphragms	Fair	
Girders	Fair	
Hardware	Not Applicable	
Under Trussing	Not Applicable	
Span 2		
Bracing	Fair	
Diaphragms	Fair	
Girders	Fair	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	1.0	Estimated Present Water Level Width:	12.0
	Estimated High Water Level Clearance:	2.5		

HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	Yes
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Required	High	\$500.00	post load rating sign
	2	Required	Medium	\$1,000.00	replace downstream right approach concrete no post barriers

MONITORS	#	Description

GENERAL	Inspector's Comment:	

--	--	--

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 4 of 4
Date Printed: 2016/01/07
User Id: IDIR\TYSMILLE
Database: PROD
Report Id: CBR001B
File:

Structure #:	CK-2261	Site #:	CK-2261	Road Name:	STAVE RIVER	Inspection Date:	2015/09/23
GENERAL	PEng's Comment:	In general the structure is in relatively poor condition. The top crib logs on both abutments and pier are in poor condition (rotting and crushing). Some ties and deck planks are showing signs of wear (rotting) as well. The debris accumulations at the inlet are at relatively low levels at the time of the inspection but this needs to be monitored continuously. Plan to replace the entire structure soon. Replace the missing concrete no post barriers on the downstream right approach. Present load rating of 30 tonnes to continue. Post load rating sign.					
GENERAL	Replacement Date for full log haul traffic (year):			2015	Replacement Date for light vehicle traffic (year):		2017
	Current Inspection Load Rating:		30	Design Load GVW (tonnes):		Design Vehicle Config.:	
	Professional Inspection Required?		No	Report Status:		Reviewed By Tyson Miller on 1/7/2016 9:18:30AM	



07/01/2016

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.

CK-2261

STAVE RIVER 8.5km

2015 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck - wear noted on right span on wheel path



upstream

CK-2261

STAVE RIVER 8.5km

2015 Inspection



downstream



Guard Rail



Guard Rail



Right Bank Abutment when facing downstream

CK-2261

STAVE RIVER 8.5km

2015 Inspection



Left Bank Abutment when facing downstream



pier



Downstream Profile



debris accumulation at pier

CK-2261

STAVE RIVER 8.5km

2015 Inspection



top crib log in pier