

CK-2263

STAVE RIVER 11.4km

2016 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude
49°29'28.1"	-122°15'21.6"
Crossing Name	Side Creek
FSR #	8013
Branch #	1
Road Name	STAVE RIVER
User km	11.4
Current Load Rating (tonnes)	10
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	11.4
Deck Width (m)	5

Updated Data

Latitude	Longitude
49°29'28.23"	-122°15'22.42"
HD Diff. (m)	17.0
Accuracy (m)	5

Inspection

Date of Inspection 2015-09-22 2:50:10 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

The structure is in relatively poor condition. With rotting and crushing/cracking crib and tieback logs, limit loading to 30 tonnes. Replace the missing curb logs immediately. Replace missing fender logs and post missing bridge ahead signs. Post load rating sign.



07/01/2016

P.Eng Seal

CK-2263

STAVE RIVER 11.4km

2016 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor none

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Cribs Fair but settling

Tie Backs Poor rotting

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware Poor none

Fill Fair

Riprap Poor none

Bearings Fair

Corrosion Protection N/A

CK-2263

STAVE RIVER 11.4km

2016 Inspection

CBR iPad Offline Ver 0.21

**Deck**

Running Surface	N/A	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	Fair	
Curb Rail/Blocks/Posts	Poor	none
Hand Rails/Walkouts	N/A	
Hardware	Poor	loose lashing
Overall Deck Condition	Poor	no guardrail
Gravel Depth (mm)	500	

CK-2263

STAVE RIVER 11.4km

2016 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware N/A NA

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Stringer Number	Needle Beam to Crib (m)		Diameter (mm)	Needle Diameter (mm)			Comment
	Species	Peeled		Rot Depth (mm)	Condition		
1	Cw	Y	800	40	Fair		many large knots
2	Fd	Y	920	30	Fair		
3	Cw	Y	870	60	Fair		many large knots
4	Cw	Y	930	50	Fair		
5	Cw	Y	900	50	Fair		
6	Cw	Y	780	60	Fair		

CK-2263

STAVE RIVER 11.4km

2016 Inspection

CBR iPad Offline Ver 0.21



Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☐	Debris	✕
Estimated Present Water Level Width (m)	4.0	Aggradation	✕	Scour	✕
Estimated High Water Level Clearance (m)	0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	High	replace missing guard log
---	------	---------------------------

2	High	place log curbs
---	------	-----------------

3	High	post load rating sign
---	------	-----------------------

Item	Monitor Description	Frequency
------	---------------------	-----------

1		
---	--	--

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)

CK-2263

STAVE RIVER 11.4km

2015 Inspection



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



no guard log



Approach from Left Bank when facing downstream

CK-2263

STAVE RIVER 11.4km

2015 Inspection



top log on left crib cracking horizontally



Downstream Profile