

CK-2267

STAVE RIVER 19km

2015 Inspection



CBR iPad Offline Ver 0.21

CBR Data

Latitude	Longitude		
49°32'37.89"	-122°17'42.4"		
Crossing Name	Ole Creek		
FSR #	8013	Branch #	1
Road Name	STAVE RIVER		
User km	19		
Current Load Rating (tonnes)	30		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Gravel		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	13.5		
Deck Width (m)	5		

Updated Data

Latitude	Longitude		
49°32'37.85"	-122°17'42.76"		
HD Diff. (m)	7.4	Accuracy (m)	5

Inspection

Date of Inspection 2015-09-22 12:27:19 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

This structure has 2 layers of stringers and only the bottom layer can properly assessed. The top layer were added in 2012 as a temporary measure in order to facilitate works at the time. The entire structure (crib logs, tiebacks and stringers) has further deteriorated since then. Because the top layer of stringers have not been properly inspected the structure remains down-rated. Present load rating of 30 tonnes to continue. Post load rating sign.



13/01/2016

P.Eng Seal

CK-2267

STAVE RIVER 19km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Fair

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor none

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Crib Poor 3x left, 2x right-cracking and splitting top crib log on left bank

Tie Backs Poor rotting

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair

Riprap Poor none

Bearings Poor undermined crib on left bank

Corrosion Protection N/A

CK-2267

STAVE RIVER 19km

2015 Inspection



CBR iPad Offline Ver 0.21

Deck

Running Surface	N/A	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	Fair	
Curb Rail/Blocks/Posts	Fair	
Hand Rails/Walkouts	N/A	
Hardware	Poor	loose lashing
Overall Deck Condition	Fair	
Gravel Depth (mm)	200	

CK-2267

STAVE RIVER 19km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware N/A NA

Welded/grouted
shear connectors**Log**

Log Curbs Fair

Needle Beam Poor loose

Needle Lashing/
Shimming Poor loose

Stringer Number	Needle Beam to Crib (m)		Diameter (mm)	Needle Diameter (mm)			Comment
	Species	Peeled		Rot Depth (mm)	Condition		
1	Cw	Y	760	150	Poor		sap and heart rot
2	Cw	Y	870	60	Fair		sap rot
3	Cw	Y	710	70	Fair		sap rot
4	Cw	Y	750	150	Poor		sap and heart rot
5	Cw	Y	820	100	Poor		sap and pocket rot
6	Cw	Y	770	50	Fair		sap rot
7	Cw	Y	670	60	Fair		sap rot

CK-2267

STAVE RIVER 19km

2015 Inspection



CBR iPad Offline Ver 0.21

Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	3.5	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	0	Ice	☐		
Comments	can not see top stringer logs				

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	dig up gravel deck and properly assess top stringers

2 High post load rating sign

3

Item	Monitor Description	Frequency
1	crib condition	Anually

2

3

Sketch
(Select Signature)

CK-2267

STAVE RIVER 19km

2015 Inspection



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



exposed stringer at left approach



Left Bank Abutment when facing downstream

CK-2267

STAVE RIVER 19km

2015 Inspection



Left Bank Abutment when facing downstream



tiebacks condition



left abutment top crib log cracking vertically and horizontally



needle beam - not functional

CK-2267

STAVE RIVER 19km

2015 Inspection



Right Bank Abutment when facing downstream



Upstream Profile