

CK-2271

STAVE RIVER 26.2km

2015 Inspection

CBR iPad Offline Ver 0.21



CBR Data

Latitude	Longitude		
49°34'21"	-122°22'3"		
Crossing Name	Stave River		
FSR #	8013	Branch #	1
Road Name	STAVE RIVER		
User km	26.2		
Current Load Rating (tonnes)	68		
Structure Class	Permanent Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Timber - Untreated		
Abutment Left	Steel Pipe and Precast Pad		
Abutment Right	Concrete Cast in Place		
Spans	1		
Total Length (m)	24.5		
Deck Width (m)	4.3		

Updated Data

Latitude	Longitude		
49°34'21.27"	-122°22'2.97"		
HD Diff. (m)	8.3	Accuracy (m)	5
Timber – Treated			

Inspection

Date of Inspection 2015-09-22 10:30:14 AM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

The running planks are treated and showing signs of heavy wear. Replace the running deck with an MoF standard treated subdeck and non-treated wear planks. Ensure the 2 non-treated ties that are located on the right approach are also replaced at the same time as they are rotting. Replace the damaged section of guardrail. Post bridge ahead signs. Reduce loading to L45 or 41 tonnes until the repairs are completed. Post load rating sign.



13/01/2016

P.Eng Seal

CK-2271

STAVE RIVER 26.2km

2015 Inspection



CBR iPad Offline Ver 0.21

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Good

CIP right

Caps or Sills Good

concrete

Piles or Posts Good

left bank only

Ballast Wall Good

treated timbers

Wing Wall N/A

Bracing Good

Hardware Fair

Fill Fair

eroding on left approach

Riprap Good

Bearings Good

Corrosion Protection Fair

CK-2271

STAVE RIVER 26.2km

2015 Inspection

CBR iPad Offline Ver 0.21



Deck

Running Surface	N/A	
Running Planks	Fair - Poor	treated planks - wearing on wheel path
Sub Deck	N/A	
Ties	Fair	2 non treated ties have rot - other ties treated and in good shape
Nails	Fair - Poor	fair to poor as some are starting to protrude on worn planks
Deck to Girder Bolts	Good	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Fair	replace damaged section
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2271

STAVE RIVER 26.2km

2015 Inspection



CBR iPad Offline Ver 0.21

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good

Bracing Good

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2271

STAVE RIVER 26.2km

2015 Inspection

CBR iPad Offline Ver 0.21



Hazards

Estimated Present Water Level Depth (m)	2.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	5.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	8.0	Ice	☐		
Comments	dam immediately upstream				

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	replace 2 rotting ties at right end
2	High	replace running planks and ensure non-treated wear planks are installed on top
3	Medium	replace damaged guardrail section

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)

CK-2271

STAVE RIVER 26.2km

2015 Inspection



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



eroding fill on left upstream approach



Deck

CK-2271

STAVE RIVER 26.2km

2015 Inspection



nails starting to protrude



guardrail damage



wheel path decking wearing



2 non-creosoted ties on right approach - replace

CK-2271

STAVE RIVER 26.2km

2015 Inspection



Left Bank Abutment when facing downstream



dam immediately upstream from crossing



Approach from Right Bank when facing downstream