

CK-2284

TSILEUH CREEK 4.4km

2016 Inspection

CBR iPad Offline Ver 0.20



CBR Data

Latitude	Longitude
49°42'40.7"	-121°26'42.3"
Crossing Name	Tikwalus Creek
FSR #	7978
Branch #	1
Road Name	TSILEUH CREEK
User km	4.4
Current Load Rating (tonnes)	10
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Timber - Treated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	10.7
Deck Width (m)	5.7

Updated Data

Latitude	Longitude
49°42'40.97"	-121°26'42.3"
HD Diff. (m)	105.8
Accuracy (m)	5

Timber – Untreated

Inspection

Date of Inspection 2015-06-18 2:06:39 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Recommend complete replacement for industrial activity. Present load rating of 10 tonnes to continue. Post load rating sign.



06/01/2016

P.Eng Seal

CK-2284

TSILEUH CREEK 4.4km

2016 Inspection



CBR iPad Offline Ver 0.20

Approach

Alignment Fair

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor none

Posted Load Rating not posted

Road Surface Poor requires surfacing and grading in various locations

Abutment

Log/Timber Cribs Fair

Tie Backs Fair

Bin Wall N/A

Concrete N/A

Caps or Sills Fair treated timber on right abutment on top of crib

Piles or Posts N/A

Ballast Wall Fair treated timbers

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair failing behind right abutment ballast wall

Riprap Poor none

Bearings Poor scoured crib on left bank

Corrosion Protection N/A

CK-2284

TSILEUH CREEK 4.4km

2016 Inspection

CBR iPad Offline Ver 0.20

**Deck**

Running Surface	N/A	requires surfacing and grading in various locations
Running Planks	Fair	fair to poor - rotting
Sub Deck	N/A	
Ties	Poor	undersized and rotting
Nails	Fair	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	too low
Hand Rails/Walkouts	N/A	
Hardware	Poor	loose lashing
Overall Deck Condition	Poor	due to age and condition
Gravel Depth (mm)		

CK-2284

TSILEUH CREEK 4.4km

2016 Inspection



CBR iPad Offline Ver 0.20

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware N/A na

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Stringer Number	Needle Beam to Crib (m)		Diameter (mm)	Needle Diameter (mm)			Comment
	Species	Peeled		Rot Depth (mm)	Condition		
1	Fd	Y	730	60	Fair		670 x 630 cant - pocket rot
2	Fd	Y	730	60	Fair		670 x 630 cant - pocket rot
3	Fd	Y	610	150	Poor		powder for shavings
4	Fd	Y	720	50	Fair		660 x 620 cant - pocket rot
5	Fd	Y	720	30	Fair		670 x 620 cant
6	Fd	Y	720	70	Fair		670 x 620 cant - pocket rots
7	Fd	Y	720	30	Fair		670 x 620 cant

CK-2284

TSILEUH CREEK 4.4km

2016 Inspection



CBR iPad Offline Ver 0.20

Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	post load rating sign

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)

CK-2284

TSILEUH CREEK 4.4km

2015 Inspection



Approach from Right Bank when facing downstream



failing fill on right approach



Deck



guardrail too low

CK-2284

TSILEUH CREEK 4.4km

2015 Inspection



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Deck



Right Bank Abutment when facing downstream

CK-2284

TSILEUH CREEK 4.4km

2015 Inspection



Stringers