

CK-2478

NAHATLATCH 42.6km

2015 Inspection



CBR iPad Offline Ver 0.20

CBR Data

Latitude	Longitude
49°55'35.79"	-121°57'25.6"
Crossing Name	Unknown
FSR #	6996
Branch #	1
Road Name	NAHATLATCH
User km	42.6
Current Load Rating (tonnes)	5
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	10
Deck Width (m)	4.3

Updated Data

Latitude	Longitude
49°55'35.7"	-121°57'25.6"
HD Diff. (m)	3.5
Accuracy (m)	5

Inspection

Date of Inspection 2015-07-22 12:16:37 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Structure condemned, 0 tonnes load rating. Post load rating sign and block access or remove structure. Due to the ongoing fire fighting efforts in the area a temporary bypass road was constructed immediately upstream of the crossing for machine access (stream is dry). Recommend upgrading this bypass route so vehicles can access while the stream is dry. If the stream starts to flow recommend placing a temporary crossing (bridge) if access is required.



CK-2478

NAHATLATCH 42.6km

2015 Inspection



CBR iPad Offline Ver 0.20

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☒ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Fair

Posted Load Rating 5

Road Surface Fair

Abutment

Log/Timber Cribs Poor scoured right

Tie Backs Fair

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing Poor loosely lashed

Hardware Fair

Fill Fair

Riprap Poor none

Bearings Poor scoured under right crib

Corrosion Protection N/A

CK-2478

NAHATLATCH 42.6km

2015 Inspection

CBR iPad Offline Ver 0.20

**Deck**

Running Surface	N/A	
Running Planks	Fair	
Sub Deck	Poor	rotting
Ties	Poor	rotten
Nails	Poor	protruding
Deck to Girder Bolts	Poor	ties spiked to stringers but ties and stringers rotting
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Fair	
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Poor	rotting
Gravel Depth (mm)		

CK-2478

NAHATLATCH 42.6km

2015 Inspection



CBR iPad Offline Ver 0.20

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Stringer Number	Needle Beam to Crib (m)		Diameter (mm)	Needle Diameter (mm)			Comment
	Species	Peeled		Rot Depth (mm)	Condition		
1	Fd	Y	660	200	Poor		dry rot
2	Fd	Y	660	60	Poor		dry rot - conks
3	Fd	Y	690	300	Poor		rotten
4	Fd	Y	800	300	Poor		rotten
5	Fd	Y	780	300	Fair		rotten

CK-2478

NAHATLATCH 42.6km

2015 Inspection



CBR iPad Offline Ver 0.20

Hazards

Estimated Present Water Level Depth (m)	0.0	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	0	Ice	☐		

Comments stringers are rotten

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

CK-2478

NAHATLATCH 42.6km

2015 Inspection



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Deck



load rating sign

CK-2478

NAHATLATCH 42.6km

2015 Inspection



Right Bank Abutment when facing downstream



Upstream Profile



Left Bank Abutment when facing downstream



machine bypass just upstream