

CK-2085

CHILLIWACK SOUTH 0.1km

2016 Inspection

CBR iPad Offline Ver 0.23



CBR Data

Latitude	Longitude		
49°5'39.99"	-121°34'57.4"		
Crossing Name	Chilliwack River		
FSR #	5127	Branch #	26
Road Name	CHILLIWACK SOUTH		
User km	0.1		
Current Load Rating (tonnes)	81		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Timber - Untreated		
Abutment Left	Concrete Cast in Place		
Abutment Right	Concrete Cast in Place		
Spans	1		
Total Length (m)	34.8		
Deck Width (m)	4.3		

Updated Data

Latitude	Longitude		
49°5'40.61"	-121°34'57.24"		
HD Diff. (m)	19.3	Accuracy (m)	10

Inspection

Date of Inspection 2016-07-27 2:31:36 PM

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace running strips; replace guardrail and risers; brush approaches; replace missing delineators and post bridge ahead signs. The present load rating of L90 or 81 tonnes to continue.



23/01/2017

P.Eng Seal

CK-2085

CHILLIWACK SOUTH 0.1km

2016 Inspection



CBR iPad Offline Ver 0.23

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y minor

Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating not posted

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete Good

Caps or Sills Good

Piles or Posts N/A

Ballast Wall Good

Wing Wall Good

Bracing N/A

Hardware Poor loose rail bolts

Fill Good

Riprap Good

Bearings Good

Corrosion Protection N/A

CK-2085

CHILLIWACK SOUTH 0.1km

2016 Inspection

CBR iPad Offline Ver 0.23

**Deck**

Running Surface	N/A	
Running Planks	Poor	some really rotten
Sub Deck	Good	treated
Ties	Good	treated
Nails	Poor	protruding on planks
Deck to Girder Bolts	Good	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	rotting
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Poor	due to planks and guardrail
Gravel Depth (mm)		

CK-2085

CHILLIWACK SOUTH 0.1km

2016 Inspection



CBR iPad Offline Ver 0.23

Steel/Concrete

Serial/ID Plate

Girders Fair minor corrosion

Diaphragms Fair minor corrosion

Bracing Fair minor corrosion

Under Trussing N/A

Hardware Good galvanized bolts

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

CK-2085

CHILLIWACK SOUTH 0.1km

2016 Inspection

CBR iPad Offline Ver 0.23



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	25.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	replace running planks
2	High	replace guardrail
3	Medium	brush approaches
4	Medium	replace missing delineators and post bridge ahead signs

Item	Monitor Description	Frequency
1	bearing bolt condition	
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Deck



missing block on fender



Deck



Approach from Left Bank when facing downstream



upstream left bank bearing



upstream left bank wing wall



deck from underneath



downstream left bank wing wall



upstream right bank wing wall



conk growing on guardrail



Left Bank Abutment when facing downstream

CK-2085

CHILLIWACK SOUTH 0.1km

2016 Inspection



downstream right bank wing wall