

CK-2218

PITT RIVER 8km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

CBR Data

Latitude	Longitude
49°36'21.7"	-122°37'58.6"
Crossing Name	Fish Hatchery Creek
FSR #	8394
Branch #	1
Road Name	PITT RIVER
User km	8
Current Load Rating (tonnes)	109
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	24.3
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°36'20.95"	-122°37'57.77"
HD Diff. (m)	28.6
Accuracy (m)	10

Inspection

Date of Inspection 2016-08-04 6:17:15 PM

Inspector Name Jamie Rupar Gilliatt

Inspection Company SNT Engineering

Inspector Comments

Guardrail is rotten and requires replacement, otherwise bridge is generally in good condition.

P.Eng Comments

Replace guardrail, risers and blocks. Present load rating of L120 or 109 tonnes to continue.



24/02/2017

P.Eng Seal

CK-2218

PITT RIVER 8km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Approach

Alignment Good

 Bridge Ahead Signs
 Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

 Delineator Missing
 Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
 Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair Concrete no post barriers over grown by moss.

Posted Load Rating No load posting sign in place.

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts Good Pipe risers.

Ballast Wall Good Precast concrete ballast wall.

Wing Wall N/A

Bracing Good Mostly buried.

Hardware Fair

Fill Good

Riprap Good

Bearings Fair 15 mm pads at left abutment are squeezing/bulging. 50 mm pads at right abutment are in good condition.

Corrosion Protection Fair Painted substructure.

CK-2218

PITT RIVER 8km

2016 Inspection

CBR iPad Offline Ver 0.23 SNT

**Deck**

Running Surface	Fair	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	Fair	Wear in wheel tracks. Flare in end deck panels.
Grout Pockets	Unrated	Covered in debris, not visible for inspection.
Deck Joints	Fair	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	Guardrail, risers and blocking rotten with moss growth.
Hand Rails/Walkouts	N/A	
Hardware	Good	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2218

PITT RIVER 8km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Steel/Concrete

Serial/ID Plate Iota

Girders Good

Diaphragms Good 6 diaphragms.

Bracing Good Plan bracing throughout span.

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A**Log**

Log Curbs N/A

Needle Beam N/A

Needle Lashing/
Shimming N/A

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2218

PITT RIVER 8km

2016 Inspection

CBR iPad Offline Ver 0.23 SNT



Hazards

Estimated Present Water Level Depth (m)	1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	10	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments Channel flows into Pitt River immediately downstream of bridge.

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	High	Replace guardrail. Requires 50 m of 250x250 mm guardrail, 24 650x250x250 mm riser 24 900x250x250 mm blocking.
2	Low	Clear debris from deck.
3		

Item	Monitor Description	Frequency
1	Monitor bulging/squeezing bearings at left abutment.	Routine Inspection
2		
3		

Sketch
(Select Signature)



Right Approach Facing Bridge



Looking Upstream



Right Approach Facing Away From Bridge



Looking Downstream



Deck



Left Approach Facing Bridge



Left Approach Facing Away From Bridge



Guardrail



Downstream Elevation



Right Bank Abutment



Left Bank Abutment



Girders



Typical Left Abutment Bearing - Bulging



Left Bank Abutment



Upstream Elevation



Right Bank Abutment



Typical Right Abutment Bearing