

CK-2241

SPUZZUM CREEK 25.4km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

CBR Data

Latitude	Longitude		
49°44'15.79"	-121°41'22.8"		
Crossing Name	not known		
FSR #	8128	Branch #	1
Road Name	SPUZZUM CREEK		
User km	25.4		
Current Load Rating (tonnes)	54		
Structure Class	Permanent Bridge		
Portable	N		
Superstructure	Compo Girders		
Deck Type	Concrete Composite		
Abutment Left	Steel Pipe and Precast Pad		
Abutment Right	Steel Pipe and Precast Pad		
Spans	1		
Total Length (m)	18.2		
Deck Width (m)	4.8		

Updated Data

Latitude	Longitude		
49°44'15.94"	-121°41'22.44"		
HD Diff. (m)	8.5	Accuracy (m)	5

Inspection

Date of Inspection 2016-07-23 10:39:36 AM

Inspector Name Jamie Rupar Gilliatt

Inspection Company SNT Engineering

Inspector Comments

Guardrail, risers and blocking require replacement.

P.Eng Comments

Repair left abutment ballast wall; grade and brush approaches for industrial use; replace guardrail, risers and blocking; install bridge ahead signs; replace missing delineators; replace guide logs and remove debris from deck; all prior to industrial use. Present load rating of L60 or 54 tonnes to continue.



28/02/2017

P.Eng Seal

CK-2241

SPUZZUM CREEK 25.4km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Approach

Alignment Fair

Horizontal curve.

Bridge Ahead Signs
Missing
☐ 0
 ☐ 1
 ☒ 2

Brushing Required Y

Obscuring bridge ends.

Delineator Missing
Left
☒ 0
 ☐ 1
 ☐ 2
Delineator Missing
Right
☐ 0
 ☒ 1
 ☐ 2

Fender Condition Poor

Guide logs totally rotten.

Posted Load Rating

Road Surface Poor

Right approach below level of deck resulting in damage to ballast wall. Potholes and signs of ponding.

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts Good

Ballast Wall Fair

Left Abutment: spall in wheel track with exposed rebar and spall in upstream tapered section of ballast wall.

Wing Wall N/A

Bracing Good

Only visible at left abutment.

Hardware Fair

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

CK-2241

SPUZZUM CREEK 25.4km

2016 Inspection

CBR iPad Offline Ver 0.23 SNT



Deck

Running Surface	Fair	Right approach below level of deck resulting in damage to ballast wall. Potholes and signs of ponding.
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	Fair	Covered in debris, limited inspection.
Grout Pockets	Unrated	Not visible, deck covered in debris.
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	Two risers rotted out, and rot noted in approximately half of blocking. Pockets of rot noted in a few guardrail sections, large checks also noted.
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2241

SPUZZUM CREEK 25.4km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Steel/Concrete

Serial/ID Plate No ID Tag in place

Girders Good Compo girders.

Diaphragms Good

Bracing N/A

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs N/A

Needle Beam N/A

Needle Lashing/
Shimming N/A

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2241

SPUZZUM CREEK 25.4km

2016 Inspection

CBR iPad Offline Ver 0.23 SNT



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	High	Replace guardrail, risers and blocking. 16 900x250x250 mm blocking, 16 700x250x250 mm riser, 4 4800x250x250 mm guardrail and 3500x250x250 mm guardrail. Remove debris from deck.
2	Medium	Install bridge ahead signs, and left abutment upstream delineator. Replace guide logs.
3	Medium	Repair left abutment ballast wall, regrade and brush approaches for industrial use.

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Left Approach Facing Bridge



Left Approach Facing Away From Bridge



Left Abutment Damaged Ballast Wall



Deck



Rotten Guardrail Blocking



Looking Downstream



Looking Upstream



Right Approach Facing Away From Bridge



Right Approach Facing Bridge



Right Bank Abutment



Left Bank Abutment



Upstream Elevation



Downstream Elevation



Girders



Spall in Left Abutment Upstream Section of Ballast Wall



Typical Girder Condition