

CK-2269

STAVE RIVER 21.6km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

CBR Data

Latitude	Longitude		
49°33'16.89"	-122°19'19"		
Crossing Name	Stave River		
FSR #	8013	Branch #	1
Road Name	STAVE RIVER		
User km	21.6		
Current Load Rating (tonnes)	68		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Timber - Untreated		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Sill -Temporary Materials		
Spans	1		
Total Length (m)	19.5		
Deck Width (m)	4.3		

Updated Data

Latitude	Longitude		
49°33'16.97"	-122°19'17.67"		
HD Diff. (m)	26.7	Accuracy (m)	5
20.3			

Inspection

Date of Inspection 2016-07-26 6:36:03 PM

Inspector Name Jamie Rupar Gilliatt

Inspection Company SNT Engineering

Inspector Comments

Steel girders with log crib abutments and modular timber panel deck. Limited access to left abutment. No access to right abutment. Girders and deck sloped 3% to upstream at right abutment. Possibly due to crushing of left abutment crib. No slope at left abutment. Specialist access equipment required for more detailed inspection of abutments. Deck covered in debris. Planks in wheel tracks require replacement. Some sections of guardrail require replacement. Updated user km to 20.3 base on road km markings.

P.Eng Comments

There does not appear to be any change in the abutment condition; however its 30 years old and should be replaced soon - in the meantime monitor its condition. The timber deck was last replaced in 2009 (now 7 years old), therefore plan for a complete deck (ties, planks, guardrail and risers) replacement soon. In the meantime, replace the heavily worn planks and damaged sections of guardrail and risers. Reposition the concrete no post barriers at both approaches, post bridge ahead signs and brush approaches. The present load rating of L75 or 68 tonnes to continue.



13/03/2017

P.Eng Seal

CK-2269

STAVE RIVER 21.6km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Approach

Alignment Poor

Bridge on S curve.

Bridge Ahead Signs
Missing
☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Vegetation obscures sight lines.

Delineator Missing
Left
☒ 0 ☐ 1 ☐ 2
Delineator Missing
Right
☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Embankment at left approach downstream corner. CRB barriers at other corners partially over turned and covered in debris.

Posted Load Rating

No sign in place.

Road Surface Fair

Abutment

Log/Timber Cribs Fair

Left Abutment: Fair to poor. Limited access. Up to 50 mm sap rot. Trees growing out of some logs. No signs of crushing or distress.

Tie Backs Fair

Fair to poor. Limited access. End splits and minor end rot. Trees growing in places. No signs of crushing or distress.

Bin Wall N/A

Concrete N/A

Caps or Sills Fair

Timber sill. Limited access. No signs of crushing or distress.

Piles or Posts N/A

Ballast Wall Fair

Timber plank ballast wall. Limited access.

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair

Riprap Fair

Cribs placed on bedrock. Some riprap at left abutment downstream corner

Bearings N/A

Corrosion Protection N/A

CK-2269

STAVE RIVER 21.6km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Deck

Running Surface	Fair	
Running Planks	Poor	Covered in debris. Moderate wear in wheel tracks with some spots of heavy wear.
Sub Deck	Fair	Limited inspection possible. Drilled 4 locations, one 10 mm pocket of rot noted - file indicates no subdeck??
Ties	Fair	
Nails	Fair	Starting to protrude in wheel tracks.
Deck to Girder Bolts	Fair	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Fair	1 failed riser at L/B U/S corner. 1 split guardrail section. 4 end sections of guardrail have impact damage.
Hand Rails/Walkouts	N/A	
Hardware	Fair	Lashing.
Overall Deck Condition	Fair	
Gravel Depth (mm)		

CK-2269

STAVE RIVER 21.6km

2016 Inspection



CBR iPad Offline Ver 0.23 SNT

Steel/Concrete

Serial/ID Plate No ID Tag.

Girders Fair

4 girders. Light surface corrosion. Girders appear to slope upstream at right abutment.

Diaphragms Fair

Light surface corrosion.

Bracing Fair

Light surface corrosion.

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs N/A

Needle Beam N/A

Needle Lashing/
Shimming N/A

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2269

STAVE RIVER 21.6km

2016 Inspection

CBR iPad Offline Ver 0.23 SNT



Hazards

Estimated Present Water Level Depth (m)		High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	14	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4	Ice	☐		

Comments Bridge spans small gorge.

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	High	Clean bridge deck and replace running planks in wheel tracks. Number of planks required to be determined after cleaning.
2	High	Replace damage/deteriorated guardrail sections. Requires 5 3050x250x250 mm sections and one 770x250x250 mm riser.
3	Medium	Install bridge ahead signs. Reposition right approach fenders and left approach upstream fender.

Item	Monitor Description	Frequency
1	Monitor abutments.	Anually
2	Access right abutment to inspect crib and determine cause bridge to slope to upstream side.	Other
3		

Sketch
(Select Signature)



Left Approach Facing Bridge



Deck



Left Approach Facing Away From Bridge



Looking Downstream



Looking Upstream



Right Approach Facing Bridge



Right Approach Facing Away From Bridge



Left Approach Upstream Fender



Left Abutment Upstream Corner - Damaged Guardrail & Failed Riser



Upstream Elevation



Split Section of Guardrail



Downstream Elevation

CK-2269

STAVE RIVER 21.6km

2016 Inspection



Left Bank Abutment



Left Abutment Downstream Corner



Right Bank Abutment



Left Abutment Downstream Corner

CK-2269

STAVE RIVER 21.6km

2016 Inspection



Girders



Area of Heavy Wear in Running Planks