

CK-2154

JONES-WEST 0.8km

2017 Inspection



CBR iPad Offline Ver 0.26

CBR Data

Latitude	Longitude
49°15'19.8"	-121°36'7.47"
Crossing Name	Wahleach Creek
FSR #	8149
Branch #	3
Road Name	JONES-WEST
User km	0.8
Current Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	21.4
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°15'20.39"	-121°36'8.25"
HD Diff. (m)	24.0
Accuracy (m)	5

Inspection

Date of Inspection 2017-07-21 1:51:02 PM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Repair damage to both ballast walls and to the underneath portion of panel 1 on right bank.
 Replace guardrail, risers and blocks. Brush and grade approaches, and post bridge ahead signs.
 Present load rating of L75 or 68 tonnes to continue.



15/01/2018

P.Eng Seal

CK-2154

JONES-WEST 0.8km

2017 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Fair

VC both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 68040

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Fair Damage noted to both walls, at the surface

Wing Wall

Bracing Good

Hardware

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

CK-2154

JONES-WEST 0.8km

2017 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair Damage noted on right bank panel 1, underneath

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Rotting blocks and risers

Hand Rails/Walkouts

Hardware Poor Loose rail bolts

Overall Deck Condition Poor Due to rotting guardrail

Gravel Depth (mm)

CK-2154

JONES-WEST 0.8km

2017 Inspection



CBR iPad Offline Ver 0.26

Steel/Concrete

Serial/ID Plate

Girders Good

Diaphragms Good 5 bolted bays

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2154

JONES-WEST 0.8km

2017 Inspection

CBR iPad Offline Ver 0.26



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Medium	Repair damage to ballast walls and deck Panels at both approaches and grade approaches
2	Medium	Replace guardrail, risers and blocks
3	Medium	Brush approaches

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Deck damage at right approach



Deck



Ballast wall damage at right approach



Looking upstream from deck




Missing upstream left approach fender - rolled off road



Looking downstream from deck



Approach from Left Bank when facing downstream



Structure ID



Left bank, downstream bearing pad weathering



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream

CK-2154

JONES-WEST 0.8km

2017 Inspection



Superstructure



Right bank, panel 1 from underneath