

CK-2262

STAVE RIVER 9.4km

2017 Inspection

CBR iPad Offline Ver



CBR Data

Latitude	Longitude
49°29'5.3"	-122°15'3.3"
Crossing Name	Side Creek
FSR #	8013 Branch # 1
Road Name	STAVE RIVER
User km	9.4
Current Load Rating (tonnes)	30
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	11
Deck Width (m)	4.5

Updated Data

Latitude	Longitude
49°29'6.46"	-122°15'4.45"
HD Diff. (m)	42.7 Accuracy (m) 5

Inspection

Date of Inspection 2017-09-14 10:54:40 AM

Inspector Name Michael Foster

Inspector Comments

Replace structure. OK for excavators for replacement.
Possible 2nd layer of stringers?

Recommended Next Inspection Year 2018

Inspection Company Onsite Engineering Ltd

P.Eng Comments

Present load rating of 30 tonnes to continue. Post load rating signs and plan for a complete replacement soon.



25/01/2018

P.Eng Seal

CK-2262

STAVE RIVER 9.4km

2017 Inspection



CBR iPad Offline Ver

Approach

Alignment Fair

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor None installed

Posted Load Rating No signs

Road Surface Good

Abutment

Log/Timber Cribs Poor Visibly rotten with age , extensive sap rot

Tie Backs Poor Visibly rotten with age, extensive sap rot

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Fair

Riprap N/A

Bearings N/A

Corrosion Protection N/A

CK-2262

STAVE RIVER 9.4km

2017 Inspection

CBR iPad Offline Ver



Deck

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface Fair

Curb Rail/Blocks/Posts N/A

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Poor Replace bridge for industrial use

Gravel Depth (mm) 1.5

CK-2262

STAVE RIVER 9.4km

2017 Inspection



CBR iPad Offline Ver

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs Poor Rotten

Needle Beam N/A

Needle Lashing/
Shimming N/A

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
1	Cw	Y	650	25	Fair	Sap rot
2	Cw	Y	600	25	Fair	Sap rot
3	Cw	Y	640	25	Fair	Sap rot
4	Cw	Y	600	60	Poor	Rot
5	Cw	Y	540	25	Fair	Sap rot
6	Cw	Y	520	30	Fair	Sap rot
7	Cw	Y	650	25	Fair	Sap rot

CK-2262

STAVE RIVER 9.4km

2017 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	9	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	0.8	Ice	☐		

Comments Beaver dam across stream under upstream end of bridge

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	High	Replace bridge
2	High	Post load rating signs
3		

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Left approach viewed from bridge



Right approach viewed from bridge



Upstream Profile



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream