

CK-2047

CHEHALIS-MYSTERY 11.9km

2018 Inspection

CBR iPad Offline Ver 0.27



CBR Data

Latitude 49°31'11.1" Longitude -121°54'51"

Crossing Name Mystery Creek

FSR # 8241 Branch # 11

Road Name CHEHALIS-MYSTERY

User km 11.9

Current Load Rating (tonnes) 54

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 10.3

Deck Width (m) 4.3

Updated Data

Latitude Longitude

HD Diff. (m) Accuracy (m)

0.2

L60 or 54 tonnes

20.1

Inspection

Date of Inspection 2018-04-10 11:29:54 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2021

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace guardrail, risers and blocks. Replace wrong handed delineator at right approach and post bridge ahead signs. Present load rating of L60 or 54 tonnes to continue.



P.Eng Seal

CK-2047

CHEHALIS-MYSTERY 11.9km

2018 Inspection



CBR iPad Offline Ver 0.27

Approach

Alignment Fair

 Bridge Ahead Signs Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

 Delineator Missing Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Fair

Logs

Posted Load Rating

Not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Fair

Not painted

Ballast Wall Good

Wing Wall

Bracing Good

Only 1 bay at left bank and appears steep

Hardware

Fill Fair

Riprap Good

BR controlled crossing

Bearings Fair

All starting to deform slightly

Corrosion Protection Poor

None

CK-2047

CHEHALIS-MYSTERY 11.9km

2018 Inspection

CBR iPad Offline Ver 0.27



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets Fair Minimal evidence of water getting through pockets to girders

Deck Joints Fair 1 joint has evidence of minimal water getting through

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Cored random blocks and all over 50% rotten - replace all

Hand Rails/Walkouts

Hardware Poor Loose rail bolts and some missing

Overall Deck Condition Poor Due to rail condition

Gravel Depth (mm)

CK-2047

CHEHALIS-MYSTERY 11.9km

2018 Inspection



CBR iPad Offline Ver 0.27

Steel/Concrete

Girders Fair

Diaphragms Fair 3 bolted bays

Bracing NA

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2047

CHEHALIS-MYSTERY 11.9km

2018 Inspection

CBR iPad Offline Ver 0.27



Hazards

Estimated Present Water Level Depth (m)	2.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	10.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Low	Replace 1 right hand delineator at left approach and post bridge ahead signs

2	Medium	Replace guardrail, risers and blocks
---	--------	--------------------------------------

3		
---	--	--

Item	Monitor Description	Frequency
1		

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Looking upstream from bridge deck



Deck



Looking downstream from bridge deck



Missing bolt on guardrail



Approach from Left Bank when facing downstream



Missing riser and only 1 bolt



Missing block bolt and rotting



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream