

CK-2266

STAVE 15.8km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°31'51.6"	-122°16'40.3"		
Crossing Name	Side Creek		
FSR #	8013	Branch #	1
Road Name	STAVE		
User km	15.8		
Current Load Rating (tonnes)	30		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Gravel		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	8		
Deck Width (m)	5		

Updated Data

Latitude	Longitude		
49°31'51.69"	-122°16'40.41"		
HD Diff. (m)	3.5	Accuracy (m)	5
30 tonnes			

Inspection

Date of Inspection 2019-01-15 11:36:13 AM

Recommended Next Inspection Year 2019

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

This structure has 2 layers of stringers. The top layer cannot be inspected as they are blocked from view on the top and bottom.

P.Eng Comments

The current load rating of 30 tonnes can continue. Replace missing delineators. Post load rating signs and plan for a complete replacement soon.



05/02/2019

P.Eng Seal

CK-2266

STAVE 15.8km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

VC limits visibility

Bridge Ahead Signs

Missing

☐ 0☐ 1☒ 2

Brushing Required

N

Delineator Missing

Left

☒ 0☐ 1☐ 2

Delineator Missing

Right

☐ 0☐ 1☒ 2

Fender Condition

Poor

None

Posted Load Rating

Not posted

Road Surface

Good

Abutment

Log/Timber Cribs

Fair

Fair to poor - 2 face logs, open face with up to 50mm sap rot

Tie Backs

Fair

Fair to poor - 3x, end crack/splits

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Poor

Loose lashing

Fill

Fair

Riprap

Poor

None

Bearings

Corrosion Protection

CK-2266

STAVE 15.8km

2018 Inspection

CBR iPad Offline Ver 0.28



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface Poor Stringer visible at the road surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware

Overall Deck Condition Fair

Gravel Depth (mm) 100

CK-2266

STAVE 15.8km

2018 Inspection



CBR iPad Offline Ver 0.28

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

NA

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
1	Fd	Y	480	140	Poor	Fruiting bodies
2	Fd	Y	510	150	Poor	rotten
3	Fd	Y	730	30	Fair	Sap rot
4	Fd	Y	630	50	Fair	Sap rot
5	Fd	Y	500	30	Fair	Sap rot
6	Fd	Y	520	40	Fair	Sap rot
7	Fd	Y	560	30	Fair	Spa rot
8	Fd	Y	730	60	Poor	Fruiting bodies
9	Fd	Y	630	100	Poor	pocket rot detected
10	Fd	Y	600	100	Poor	pocket rot detected
11	Fd	Y	560	180	Poor	Fruiting bodies

Bottom stringers

CK-2266

STAVE 15.8km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance (m)		Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	High	Post load rating sign
---	------	-----------------------

2	Medium	Replace missing delineators
---	--------	-----------------------------

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1		
---	--	--

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Upstream from Crossing



Deck



Downstream from Crossing



Approach from Left Bank when facing downstream




Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Stringers



Stringers



Top layer of stringers visible from surface