

CK-2274

STAVE 29.4km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°35'37.1"	-122°24'6.1"		
Crossing Name	Side Creek		
FSR #	8013	Branch #	1
Road Name	STAVE		
User km	29.4		
Current Load Rating (tonnes)	10		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Gravel		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	7.8		
Deck Width (m)	6.4		

Updated Data

Latitude	Longitude		
49°35'36.91"	-122°24'5.88"		
HD Diff. (m)	7.4	Accuracy (m)	5
10 tonnes			
Log Sill			
Log Sill			
6.7			

Inspection

Date of Inspection 2018-06-07 11:50:07 AM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments Serial/ID Plate

6.7m span

Left abutment scoured 80% length - 300mm gap and only bearing in 3 locations

See stringer information from previous inspection, poor bearing limits loading as opposed to stringer size

P.Eng Comments

The bearing under the log sills continues to erode. The current load rating of 10 tonnes to continue. I recommend a complete replacement of the structure. Monitor for settlement and post bridge ahead signs.



P.Eng Seal

CK-2274

STAVE 29.4km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor None

Posted Load Rating Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills Poor Single log sill left bank - 80% undermined , 2 stacked sills right bank

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Fair

Riprap Poor None in front of sills

Bearings Corrosion

Protection

CK-2274

STAVE 29.4km

2018 Inspection

CBR iPad Offline Ver 0.28



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm) 400

CK-2274

STAVE 29.4km

2018 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs Fair Fabric covering guardrail limited inspection. 250x250 mm guardrail on top of log curb.

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2274

STAVE 29.4km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	7.0	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	0	Ice	☐		

Comments

Left abutment sill log 80% scoured

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	Post load rating signs

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Upstream from Crossing



Deck



Downstream from Crossing



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Upstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream