

CK2479

GRIZZLY 2.1km

2018 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°56'18.39"	-121°54'23.8"		
Crossing Name	Grizzly Creek		
FSR #	6996	Branch #	16
Road Name	GRIZZLY		
User km	2.1		
Current Load Rating (tonnes)	41		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Timber - Treated		
Abutment Left	Steel Pipe and Precast Pad		
Abutment Right	Steel Pipe and Precast Pad		
Spans	1		
Total Length (m)	19.3		
Deck Width (m)	4.9		

Updated Data

Latitude	Longitude		
49°56'19.28"	-121°54'24.21"		
HD Diff. (m)	28.4	Accuracy (m)	5

Inspection

Date of Inspection 2018-06-12 10:50:33 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2020

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace the running planks, guardrail and risers. Add slope protection and fill at right approach, and consider replacing the timber ballast wall on the right bank with longer timbers to help hold the additional fill requirement. Place fenders at both approaches; post missing bridge ahead signs, replace missing delineators and brush approaches. Limit loading to L45 or 41 tonnes until the work has been completed. Post updated load rating sign.



01/10/2018

P.Eng Seal

CK2479

GRIZZLY 2.1km

2018 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

Horizontal curve and vertical curves

Bridge Ahead Signs
Missing
☐ 0
 ☐ 1
 ☒ 2

Brushing Required Y

Delineator Missing
Left
☐ 0
 ☐ 1
 ☒ 2
Delineator Missing
Right
☐ 0
 ☐ 1
 ☒ 2

Fender Condition Poor

None in place

Posted Load Rating

Not posted

Road Surface Poor

Grade below bridge deck and potholes

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Fair

Ballast Wall Fair

Creosote timbers. Consider replacing with longer pieces to hold fill material

Wing Wall

Bracing Fair

Hardware

Fill Poor

Eroding at right approach resulting in a reduced road width

Riprap Fair

Bearings Fair

Corrosion Protection Fair

CK2479

GRIZZLY 2.1km

2018 Inspection

CBR iPad Offline Ver 0.28



Deck

Running Surface

Running Planks	Poor	Rotten sections throughout, especially at approaches
----------------	------	--

Sub Deck	Fair	Creosote
----------	------	----------

Ties	Fair	Creosote
------	------	----------

Nails	Poor	Protruding through planks
-------	------	---------------------------

Deck to Girder Bolts	Good	
----------------------	------	--

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts	Poor	Rotten risers and pocket rot in guardrail
------------------------	------	---

Hand Rails/Walkouts

Hardware	Fair	
----------	------	--

Overall Deck Condition	Poor	Due to timber plank and guardrail condition
------------------------	------	---

Gravel Depth (mm)

CK2479

GRIZZLY 2.1km

2018 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK2479

GRIZZLY 2.1km

2018 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	X
Estimated Present Water Level Width (m)	15.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Signs of debris under bridge

Repairs and Monitoring

Repair		Repair Description
Item	Priority	
1	High	Replace guardrail, running planks, risers and delineators
2	High	Add additional slope protection and fill at right approach
3	Medium	Brush both approaches, add fenders to both approaches and post bridge ahead signs

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)

CK2479

GRIZZLY 2.1km

2018 Inspection



Approach from Left Bank when facing downstream



Upstream from Crossing



Deck



Downstream from Crossing

CK2479

GRIZZLY 2.1km

2018 Inspection



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Loosing fill on road approach to right abutment



Right Bank Abutment when facing downstream

CK2479

GRIZZLY 2.1km

2018 Inspection



Superstructure