

CK-2020

CHEHALIS 6km

2019 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°17'43.19"	-121°58'.06"		
Crossing Name	Pretty Creek		
FSR #	8241	Branch #	1
Road Name	CHEHALIS		
User km	6		
Current Load Rating (tonnes)	150		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Steel I-beam		
Deck Type	Concrete Composite		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	18.9		
Deck Width (m)	4.9		

Updated Data

Latitude	Longitude		
49°17'42.85"	-121°57'59.5"		
HD Diff. (m)	15.5	Accuracy (m)	5

L165 or 150 tonnes

Sill -Temporary Materials

Inspection

Date of Inspection 2019-03-28 9:10:35 AM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company MFLNRO

Inspector Comments

Consideration should be given to replacing the entire structure given the condition of the abutments

P.Eng Comments

The abutments have been rated as fair; however the log sill and timber shims are starting to deteriorate and the log ballast wall is continuously rotting. The left bank log sill has a 30mm wide horizontal crack along the full visible length and the timber shims are starting to crush and needs to be monitored when being used for industrial purposes. The guardrail, risers and blocks are in poor condition and require replacement. The current load rating of L165 or 150 tonnes to continue, however monitor the condition of the abutments and if they deteriorate any further contact the undersigned for another inspection. Given the condition of the entire structure plan for a complete replacement soon.



03/05/2019

P.Eng Seal

CK-2020

CHEHALIS 6km

2019 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Good

 Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair Log fenders, missing upstream left

Posted Load Rating 149700

Road Surface Fair Potholes at approaches

Abutment

Log/Timber Cribs Fair 2x, right bank only with up to 40mm sap rot

Tie Backs Fair 2x with up to 40mm sap rot

Bin Wall

Concrete

Caps or Sills Fair Left bank, 30mm wide horizontal crack full visible length with crushing timber shims - monitor

Piles or Posts

Ballast Wall Fair Rotten logs both abutments but still functional

Wing Wall

Bracing

Hardware

Fill Fair Indications that fill is eroding through to stream side

Riprap Poor None in front of abutments

Bearings Fair Left bank timber shims crushing and girders settling - monitor

Corrosion Protection

CK-2020

CHEHALIS 6km

2019 Inspection

CBR iPad Offline Ver 0.28

**Deck**

Running Surface	Fair	Potholes at approaches
-----------------	------	------------------------

Running Planks		
----------------	--	--

Sub Deck		
----------	--	--

Ties		
------	--	--

Nails		
-------	--	--

Deck to Girder Bolts		
----------------------	--	--

Concrete Deck	Fair	
---------------	------	--

Grout Pockets	Fair	
---------------	------	--

Deck Joints	Fair	
-------------	------	--

Steel Deck Plate		
------------------	--	--

Gravel Surface		
----------------	--	--

Curb Rail/Blocks/Posts	Poor	Rotten and loose
------------------------	------	------------------

Hand Rails/Walkouts		
---------------------	--	--

Hardware	Poor	Loose rail
----------	------	------------

Overall Deck Condition	Poor	Due to rail condition
------------------------	------	-----------------------

Gravel Depth (mm)		
-------------------	--	--

CK-2020

CHEHALIS 6km

2019 Inspection



CBR iPad Offline Ver 0.28

Steel/Concrete

Girders Fair

Painted box beams with minor corrosion

Diaphragms Fair

Painted and only at bearing locations

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2020

CHEHALIS 6km

2019 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	Replace guardrail, risers and blocks

2 Medium Grade approaches

3

Item	Monitor Description	Frequency
1	Abutment condition	While being used
2	Spalling concrete underside of panels 1 and 2 at right bank	Routine Inspection

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Load Rating Sign



Upstream from Crossing



Downstream from Crossing



Approach from Right Bank when facing downstream



Guardrail condition



Upstream Profile



Right Bank Abutment when facing downstream



Indication of water leaking through deck joints and grout pockets



Superstructure



Horizontal crack on left bank log sill; full visible length 30mm gap



Timber shims on left abutment rotting and indications of crush, downstream shim shown here



Left Bank Abutment when facing downstream



Ballast wall condition, left bank



Damage noted to panels 1 and 2 on right approach