

CK-2031

STATLU 1.7km

2019 Inspection



CBR iPad Offline Ver 0.28

CBR Data

Latitude	Longitude
49°20'47.29"	-122°2'51.9"
Crossing Name	Statlu Creek
FSR #	8241
Branch #	2
Road Name	STATLU
User km	1.7
Current Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Untreated
Abutment Left	Concrete Cast in Place
Abutment Right	Concrete Cast in Place
Spans	1
Total Length (m)	20.8
Deck Width (m)	5

Updated Data

Latitude	Longitude
49°20'46.6"	-122°2'53.12"
HD Diff. (m)	32.7
Accuracy (m)	5

L150 or 136 tonnes

Inspection

Date of Inspection 2019-03-28 10:28:11 AM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller


Inspection Company MFLNRO

Inspector Comments

Wingwall condition is in relatively poor condition

P.Eng Comments

Repair failing approach fills and reset the concrete bridge approach barriers; replace left approach load rating sign; grade and brush approaches. Due to age and condition of all wingwalls, monitor their stability and plan for their replacement soon. The current load rating of L150 or 136 tonnes to continue.



P.Eng Seal

CK-2031

STATLU 1.7km

2019 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Fair

HC left approach

 Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Concrete no posts off road at upstream left approach and misaligned others

Posted Load Rating 136090

Road Surface Fair

Potholes

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete Fair

CIP both ends

Caps or Sills Fair

Timbers

Piles or Posts

Ballast Wall Fair

Old logs

Wing Wall Poor

Upstream right bank poor, others are fair to poor

Bracing

Hardware

Fill Fair

Granular fill visible within open face wingwalls

Riprap Poor

None

Bearings Fair

Corrosion Protection

CK-2031

STATLU 1.7km

2019 Inspection

CBR iPad Offline Ver 0.28



Deck

Running Surface

Running Planks

Fair

Wearing at ends

Sub Deck

Fair

Ties

Fair

Treated timbers but inconsistent alignment at right bank, up to 600mm on centers for 2m length

Nails

Fair

Deck to Girder Bolts

Poor

None visible

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Good

Hand Rails/Walkouts

Hardware

Fair

Overall Deck Condition

Fair

Gravel Depth (mm)

CK-2031

STATLU 1.7km

2019 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**

Girders Fair Painted

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2031

STATLU 1.7km

2019 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	3.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	15.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	High	Repair approach fills and realign all concrete no post barriers
2	Low	Grade and brush approaches
3	Low	Reset left approach load rating sign

Item	Monitor Description	Frequency
1	Monitor wingwall condition	Routine Inspection

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Upstream right approach no posts



Load Rating Sign



Downstream right approach no posts



Deck



Tie alignment at right bank not consistent, upstream shown



Tie alignment at right bank not consistent, downstream shown



Upstream from Crossing



Downstream from Crossing



Upstream left approach no posts off road



Approach from Left Bank when facing downstream



Left approach load rating sign



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Superstructure



Tie misalignment



Upstream right bank wingwall condition



Downstream right bank condition



Upstream right bank wingwall condition



Scour under downstream right bank CIP does not appear any worse