

CK-2161

HUNTER 4700 5.8km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°19'34.89"	-121°31'48.4"
Crossing Name	Side Creek
FSR #	6086 Branch # 2
Road Name	HUNTER 4700
User km	5.8
Previous Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	Y
Superstructure	Steel Box Beam
Deck Type	Steel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	12.2
Deck Width (m)	5.6

Updated Data

Latitude	Longitude
49°19'35.13"	-121°31'47.71"
HD Diff. (m)	15.6 Accuracy (m) 5
L75 or 68 tonnes	

Inspection

Date of Inspection 2019-08-14 1:38:46 PM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2021

Inspection Company FLNRORD

Inspector Comments

P.Eng Comments

Watch for falling debris and materials at the town approach, road approach requires cleaning prior to activity. Reconnect the concrete no post barriers at the left approach (left bank). Replace the missing delineator and post bridge ahead signs. Replace the missing timber blocking on steel spacer plate. The riprap is rounded and already scoured, monitor. The current load rating of L75 or 68 tonnes to continue.



2020-01-27

P.Eng Seal

CK-2161

HUNTER 4700 5.8km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Poor

Very tight HC at right approach

Bridge Ahead Signs
Missing
☐ 0
 ☐ 1
 ☒ 2

Brushing Required N

Delineator Missing
Left
☐ 0
 ☒ 1
 ☐ 2
Delineator Missing
Right
☒ 0
 ☐ 1
 ☐ 2

Fender Condition Fair

Lock blocks right approach and unconnected no post barriers left approach

Posted Load Rating

Not posted

Road Surface Fair

Abutment

Log/Timber Cribs Fair

3x face logs, open face - face logs not completely peeled

Tie Backs Fair

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall Poor

Left bank wall not tight to girders leaving gap and sediment falling through, no wall right bank

Wing Wall

Bracing

Hardware Poor

No bolts fastening ASP to crib noted

Fill Fair

Riprap Fair

Scour noted at right bank

Bearings Fair

Top face log not completely flat but sufficient for planned lifespan of structure

Corrosion Protection

CK-2161

HUNTER 4700 5.8km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate Fair Anti skid all but worn off and spacer plate installed for a 5.6m running width

Gravel Surface

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

CK-2161

HUNTER 4700 5.8km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders Fair ASP with spacer plate

Diaphragms Unrated Inside box beam

Bracing Unrated Inside box beam

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2161

HUNTER 4700 5.8km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Stream is aggrading at the inlet

All riprap is rounded, scour already noted at right bank - monitor

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Medium	Clear road prior to operations
2	Medium	Replace missing delineator and bridge ahead signs
3	Medium	Reconnect no post barriers
4	Medium	Replace timber blocking on steel spacer plate

Item	Monitor Description	Frequency
1	Riprap condition as scour is noted	Routine Inspection

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Transition and bullnose not attached upstream left approach



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Right Bank when facing downstream



Ravelling cutbank at right approach



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Bridge guide angle deformed at upstream right bank



Structure ID



Structure ID



Right Bank Abutment when facing downstream, scour noted



No ballast wall at left bank



Face logs were never completely peeled and minor sap rot noted



Spacer plate is constructed in 2 pieces and steel at joint has started to deform, no timber blocking