

CK-2207

MOWHOKAM 15.7km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
50°3'2.48"	-121°26'39.6"
Crossing Name	Mowhokam Creek
FSR #	8019 Branch # 2
Road Name	MOWHOKAM
User km	15.7
Previous Load Rating (tonnes)	0
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	12.1
Deck Width (m)	4.3

Updated Data

Latitude	Longitude
50°3'2.6"	-121°26'40.1"
HD Diff. (m)	10.6 Accuracy (m) 5
0 tonnes	

Inspection

Date of Inspection 2019-08-28 11:10:01 AM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company FLNRORD

Inspector Comments

The timber deck and steel girder structure is supported by a log stringer bridge underneath. All the log stringers are rotten and a risk to failure. Also, the log stringer structure may be affected by high stream flows which puts the steel girder and timber deck bridge at risk.

The site appeared to be recently surveyed as Bench Marks were noted.

P.Eng Comments

Due to the poor condition of the structure I recommend replacing it with a single new structure or blocking access until it's required. The current load rating of 0 tonnes to continue. Please update load rating sign and block access to traffic until all works are completed.



2020-02-10

P.Eng Seal

CK-2207

MOWHOKAM 15.7km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

VC left approach limits visibility, HC right approach

 Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor

Small fender logs on all corners

Posted Load Rating 1

Road Surface Fair

Abutment

Log/Timber Cribs Poor

Log crib supports log stringer structure plus log sills that supports the steel girder structure, 200mm sap rot in bottom crib log, 50mm sap rot in top crib log

Tie Backs Poor

All rotten

Bin Wall

Pier

Concrete

Caps or Sills Fair

Piles or Posts

Ballast Wall Poor

Rotten

Wing Wall

Bracing

Hardware

Fill Fair

Riprap Poor

Scoured with bags of sakrete filling voids and all riprap smaller than what the stream transports

Bearings Fair

Corrosion Protection

CK-2207

MOWHOKAM 15.7km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface

Running Planks Fair Signs of decay starting on underside

Sub Deck

Ties Fair Signs of decay starting on underside

Nails Fair

Deck to Girder Bolts Fair

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

CK-2207

MOWHOKAM 15.7km

2019 Inspection

CBR iPad Offline Ver 0.31

**Steel/Concrete**

Girders Fair

Only a section of a complete girder set

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2207

MOWHOKAM 15.7km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	0	Ice	☐		

Comments

Log stringer bridge may be affected by high flows and affect the stability of the steel girder structure

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	High	Update load rating sign
2	High	Remove existing structures and replace or block access
3		

Item	Monitor Description	Frequency
1	For failure	Annually
2		
3		

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Load Rating Sign



Deck



Upstream from Crossing



Downstream from Crossing



BMs noted



Approach from Right Bank when facing downstream



Ballast wall condition for steel girders



Right Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Needle beam condition



Downstream Profile



Downstream log stringer condition at left bank



Left Bank Abutment when facing downstream



Right bank sill for steel girders



Timber deck condition