

CK-2236

SOWAQUA 9.6km

2019 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude		
49°23'44.59"	-121°11'52"		
Crossing Name	Not Known		
FSR #	7004	Branch #	1
Road Name	SOWAQUA		
User km	9.6		
Previous Load Rating (tonnes)	68		
Structure Class	Temporary Bridge		
Portable	Y		
Superstructure	Steel I-beam		
Deck Type	Timber - Untreated		
Abutment Left	Sill -Temporary Materials		
Abutment Right	Sill -Temporary Materials		
Spans	1		
Total Length (m)	15.2		
Deck Width (m)	4.9		

Updated Data

Latitude	Longitude		
49°23'44.57"	-121°11'51.63"		
HD Diff. (m)	7.5	Accuracy (m)	10
L45 or 41 tonnes			

Inspection

Date of Inspection 2019-04-30 11:38:01 AM

Recommended Next Inspection Year 2021

Inspector Name Tyson Miller


Inspection Company FLNRORD

Inspector Comments

Right bank sub deck in poor condition. Outside wear planks (2 outer strips on both upstream and downstream) in poor condition. Steel not bearing square on log sills. Left bank sill has up to 50mm sap rot. Riprap is round, not well graded or tied into stream banks. Fairly high public use given access to HBC trail, even though road in poor condition.

P.Eng Comments

The wear planks and subdeck are in relatively poor overall condition. The steel girders do not bear squarely on the log sills at either abutment. The left bank log sill has up to 50mm sap rot. The riprap has been rated as fair however it is limited and consists of round pieces that are not well tied together or into the stream banks to provide good protection - this should be monitored following heavy precipitation events. There are a few trees that lay across the stream channel directly above the structure that are a risk to being transported by high flows into the bridge crossing, these should be removed. Given the condition of the entire structure I recommend a complete replacement prior to industrial activity. Limit loading to L45 or 41 tonnes. Post load rating sign.



03/05/2019

P.Eng Seal

CK-2236

SOWAQUA 9.6km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

VC right approach

 Bridge Ahead Signs Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

 Delineator Missing Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Logs right bank, large boulders left bank

Posted Load Rating

Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Fair

Left bank log sill is old with up to 50mm sap rot, right bank log sill appears newer

Piles or Posts

Ballast Wall Poor

Right bank log ballast wall rotten but functional, see attached picture

Wing Wall

Bracing

Hardware Fair

Nails (and approach fill) hold girders on log sills

Fill Fair

Riprap Fair

Some round pieces, not well graded, tied together or into the stream banks

Bearings Fair

Bearing plates not completely on log sills, log sills not cut flat, and not even or square bearing

Corrosion Protection

CK-2236

SOWAQUA 9.6km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface

Running Planks	Poor	Heavily worn, especially on outside 2 strips both upstream and downstream
----------------	------	---

Sub Deck	Poor	The first 4m on right bank in poor condition, remaining in fair condition
----------	------	---

Ties	Fair	
------	------	--

Nails	Poor	Protruding
-------	------	------------

Deck to Girder Bolts	Good	
----------------------	------	--

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts	Fair	
------------------------	------	--

Hand Rails/Walkouts

Hardware	Poor	Due to protruding nails at surface
----------	------	------------------------------------

Overall Deck Condition	Poor	Due to plank, subdeck and hardware condition
------------------------	------	--

Gravel Depth (mm)

Pier Deck

CK-2236

SOWAQUA 9.6km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders Fair

Minor corrosion

Diaphragms Fair

4 welded bays with minor corrosion. Both bottom chords at abutments slightly twisted

Bracing Fair

Minor corrosion

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2236

SOWAQUA 9.6km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	5.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Trees have fell across stream above bridge crossing location and are a risk to being transported into the bridge in high flows

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Low	Post bridge ahead signs
2	High	Remove trees that have sloughed into stream channel upstream of bridge
3	High	Post load rating sign

Item	Monitor Description	Frequency
1	bearing plate deformation	Routine inspection
2	riprap scour	Routine inspection
3		

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Planks




Upstream from Crossing, remove trees that have sloughed into stream



Downstream from Crossing



Approach from Right Bank when facing downstream



Structure ID



Downstream right bank bearing



Upstream right bank bearing



Log ballast wall rotten but still functional



Subdeck condition



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Superstructure



Deck clips



Bottom chord at left bank bent