

CK-2241

SPUZZUM 25.4km

2019 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude		
49°44'15.79"	-121°41'22.8"		
Crossing Name	not known		
FSR #	8128	Branch #	1
Road Name	SPUZZUM		
User km	25.4		
Current Load Rating (tonnes)	54		
Structure Class	Permanent Bridge		
Portable	N		
Superstructure	Compo Girders		
Deck Type	Concrete Composite		
Abutment Left	Steel Pipe and Precast Pad		
Abutment Right	Steel Pipe and Precast Pad		
Spans	1		
Total Length (m)	18.2		
Deck Width (m)	4.8		

Updated Data

Latitude	Longitude		
49°44'15.6"	-121°41'23.23"		
HD Diff. (m)	10.6	Accuracy (m)	12
L60 or 54 tonnes			

Inspection

Date of Inspection 2019-06-27 9:53:29 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2022

Inspection Company MFLNRO

Inspector Comments

P.Eng Comments

Replace the guardrail, risers and blocks; repair the damage to the ballast wall consistent with the Concrete Repair Guide for Concrete Bridge Components written by the Ministry of Forests, Lands and Natural Resource Operations (2017); brush and grade approaches and replace the approach fender logs. Monitor the deck joint condition. The current load rating of L60 or 54 tonnes to continue.



CK-2241

SPUZZUM 25.4km

2019 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor

Old rotten logs

Posted Load Rating

Not posted

Road Surface Fair

Requires material at left approach

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Fair damage noted to top at left bank

Wing Wall

Bracing Good

Hardware

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

CK-2241

SPUZZUM 25.4km

2019 Inspection

CBR iPad Offline Ver 0.28

**Deck**

Running Surface	Good	Requires material at left approach
-----------------	------	------------------------------------

Running Planks		
----------------	--	--

Sub Deck		
----------	--	--

Ties		
------	--	--

Nails		
-------	--	--

Deck to Girder Bolts		
----------------------	--	--

Concrete Deck	Good	
---------------	------	--

Grout Pockets	Good	
---------------	------	--

Deck Joints	Fair	Evidence that water is getting on 2 deck joints
-------------	------	---

Steel Deck Plate		
------------------	--	--

Gravel Surface		
----------------	--	--

Curb Rail/Blocks/Posts	Poor	Rotten
------------------------	------	--------

Hand Rails/Walkouts		
---------------------	--	--

Hardware	Poor	Loose rail bolts
----------	------	------------------

Overall Deck Condition	Poor	Due to rail condition
------------------------	------	-----------------------

Gravel Depth (mm)		
-------------------	--	--

CK-2241

SPUZZUM 25.4km

2019 Inspection



CBR iPad Offline Ver 0.28

Steel/Concrete

Girders Good

Compo girders

Diaphragms Good

1 welded bay at center

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2241

SPUZZUM 25.4km

2019 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	12.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair
Item Priority

Repair Description

- | | | |
|---|--------|---|
| 1 | High | Replace guardrail, risers and blocks |
| 2 | Medium | Repair damage to top of ballast wall |
| 3 | Medium | Brush and grade approaches, and replace fender logs |

Item	Monitor Description	Frequency
1 Deck joints		Routine Inspection

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Damage noted to ballast wall at road surface



Fender logs



Rail condition

CK-2241

SPUZZUM 25.4km

2019 Inspection



Upstream from Crossing



Approach from Right Bank when facing downstream



Downstream from Crossing



Left Bank Abutment when facing downstream



Superstructure



Evidence that water is getting through some deck joints



Right Bank Abutment when facing downstream