

CK-2267

STAVE 17.8km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude		
49°32'37.89"	-122°17'42.4"		
Crossing Name	Ole Creek		
FSR #	8013	Branch #	1
Road Name	STAVE		
User km	17.8		
Previous Load Rating (tonnes)	10		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Gravel		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	13.5		
Deck Width (m)	5		

Updated Data

Latitude	Longitude		
49°32'37.99"	-122°17'42.4"		
HD Diff. (m)	2.9	Accuracy (m)	5
10 tonnes			

Inspection

Date of Inspection 2019-11-04 1:32:33 PM

Recommended Next Inspection Year 2020

Inspector Name Tyson Miller

Inspection Company FLNRORD

Inspector Comments

Remove and replace

P.Eng Comments

Current load rating of 10 tonnes to continue. Due to the poor condition of the entire structure continue to monitor it while in use, and inspect after heavy precipitation events. Consider cleaning the inlet to increase hydraulic capacity. Post load rating signs. Plan to replace the structure soon.



P.Eng Seal

CK-2267

STAVE 17.8km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

VC left approach

 Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor

None

Posted Load Rating

Not posted

Road Surface Good

Abutment

Log/Timber Cribs Poor

Top face log on left bank cracked horizontally and vertically

Tie Backs Poor

End splitting and rotten

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Poor

Loose lashing

Fill Fair

Riprap Poor

None

Bearings Poor

Left bank top face log cracked resulting in inconsistent bearing

Corrosion Protection

CK-2267

STAVE 17.8km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface **Fair**

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

Pier Deck

CK-2267

STAVE 17.8km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs Fair

Needle Beam Poor Loose and ineffective

Needle Lashing/
Shimming Poor Loose and ineffective

Needle Beam to Crib (m)

NA

Needle Diameter (mm)

NA

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2267

STAVE 17.8km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	0	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	0	Ice	☐		

Comments Inlet 50% plugged

Repairs and Monitoring

Repair
Item Priority Repair Description

1 High Post load rating sign

2 High Replace

3

Item Monitor Description Frequency

1 Failure or washout Annually

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Stringers at surface



Approach from Left Bank when facing downstream



Top crib log at left bank cracked horizontally and vertically



Left Bank Abutment when facing downstream



Upstream Profile



Needle beam not functional



Right Bank Abutment when facing downstream



Stringers