

CK-2304

EAST ANDERSON 6.6km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude		
49°45'2.49"	-121°20'22.5"		
Crossing Name	Side Creek		
FSR #	7972	Branch #	2
Road Name	EAST ANDERSON		
User km	6.6		
Previous Load Rating (tonnes)	0		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Timber - Untreated - Panels		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	16.5		
Deck Width (m)	3.5		

Updated Data

Latitude	Longitude		
49°45'2.03"	-121°20'22.49"		
HD Diff. (m)	14.5	Accuracy (m)	5
0.2			
0 tonnes			

Inspection

Date of Inspection 2019-08-29 8:09:38 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2021


Inspection Company FLNRORD

Inspector Comments

All components rotten, remove entire structure

P.Eng Comments

0 tonnes load rating. Post load rating sign and consider blocking access more securely or removing the entire structure. This structure is not on the existing 7972.02 branch, and rather appears to be on a non-status road. Consider deactivating this structure and removing it from inventory.



2020-01-21

P.Eng Seal

CK-2304

EAST ANDERSON 6.6km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Poor None

Posted Load Rating Not posted

Road Surface Fair Old bushed in road

Abutment

Log/Timber Cribs Poor Rotten

Tie Backs Poor Rotten

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall Poor Rotten

Bracing

Hardware Poor Loose lashing

Fill

Riprap Poor None

Bearings

Corrosion Protection

CK-2304

EAST ANDERSON 6.6km

2019 Inspection

CBR iPad Offline Ver 0.31

**Deck**

Running Surface		Old bushed in road
-----------------	--	--------------------

Running Planks	Poor	Rotten
----------------	------	--------

Sub Deck		
----------	--	--

Ties	Poor	Rotten
------	------	--------

Nails	Poor	Protruding
-------	------	------------

Deck to Girder Bolts		
----------------------	--	--

Concrete Deck		
---------------	--	--

Grout Pockets		
---------------	--	--

Deck Joints		
-------------	--	--

Steel Deck Plate		
------------------	--	--

Gravel Surface		
----------------	--	--

Curb Rail/Blocks/Posts	Poor	Rotten
------------------------	------	--------

Hand Rails/Walkouts		
---------------------	--	--

Hardware		
----------	--	--

Overall Deck Condition	Poor	All components rotten
------------------------	------	-----------------------

Gravel Depth (mm)		
-------------------	--	--

Pier Deck		
-----------	--	--

CK-2304

EAST ANDERSON 6.6km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware Poor

Loose lashing

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

CK-2304

EAST ANDERSON 6.6km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	12.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	High	Remove or replace
---	------	-------------------

2		
---	--	--

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1		
---	--	--

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Stringers



Left abutment downstream scour



Tieback condition



Face log condition



Left Bank Abutment when facing downstream



Upstream right bank wingwall condition



Upstream Profile