

CK-2011
CK-2011

BLUE MOUNTAIN 300 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°14'12.99"	-122°27'43.6"
Crossing Name	Copper Creek
FSR #	5913
Branch #	2
Road Name	BLUE MOUNTAIN 300
User km	0.1
Previous Load Rating (tonnes)	10
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Treated
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	8
Deck Width (m)	4.3

Updated Data

Latitude	Longitude
49°14'12.06"	-122°27'43.07"
HD Diff. (m)	31.0
Accuracy (m)	5
10 tonnes	

Inspection

Date of Inspection 2020-06-11 9:37:54 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2022

Inspection Company

Inspector Comments

P.Eng Comments

The 2 cross ties that have sheared at the downstream girder connection point, approximately 3m from the town bearing location, still have not been replaced. Until these ties are replaced there should NOT be any industrial activity over this bridge. Replace the missing delineators, post bridge ahead signs, remove sediment from deck and brush approaches. The current load rating of 10 tonnes to continue, post load rating signs.



CK-2011
CK-2011

BLUE MOUNTAIN 300 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Fair Old logs

Posted Load Rating Not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good 3 lock blocks per abutment

Caps or Sills Fair Upstream right bank has hairline crack

Piles or Posts

Ballast Wall Good Creosote timbers

Wing Wall

Bracing

Hardware Good

Fill Fair

Riprap Poor None in front of either abutment

Bearings Good

Corrosion Protection

CK-2011
CK-2011

BLUE MOUNTAIN 300 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface

Running Planks Fair

Sub Deck

Ties Poor 2 cracked ties at downstream left bank

Nails Good

Deck to Girder Bolts Good

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor sagging at center span due to failed cross ties

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Poor Due to 2 cracked ties

Gravel Depth (mm)

Pier Deck

CK-2011
CK-2011

BLUE MOUNTAIN 300 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair Painted girders

Diaphragms Fair

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2011
CK-2011

BLUE MOUNTAIN 300 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Major redecking (crossties or laminated deck). m. Priority:High	Replace 2 cracked ties
2 Approach. Add Warning Signs. # of signs. Priority:High	Post rating signs and bridge approach signs at both approaches
3 Approach. Area/sight line brushing. m ² . Priority:Low	Brush approaches
4 Structure. Clean Deck. # of delineators. Priority:Medium	Remove sediment from deck

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Right Bank when facing downstream



Deck



Upstream from Crossing





Downstream from Crossing



Approach from Left Bank when facing downstream



Guard Rail



2 cracked ties just outside downstream girder



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Superstructure



Upstream right bank sill condition