

CK-2031
CK-2031

STATLU 1.7km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°20'47.29"	-122°2'51.9"
Crossing Name	Statlu Creek
FSR #	8241
Branch #	2
Road Name	STATLU
User km	1.7
Previous Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Untreated
Abutment Left	Concrete Cast in Place
Abutment Right	Concrete Cast in Place
Spans	1
Total Length (m)	20.8
Deck Width (m)	5

Updated Data

Latitude	Longitude
49°20'46.6"	-122°2'52.5"
HD Diff. (m)	24.6
Accuracy (m)	5
L100 or 91 tonnes	

Inspection

Date of Inspection 2020-08-25 11:20:12 AM

Inspector Name Tyson Miller


Recommended Next Inspection Year 2021

Inspection Company FLNRORD

Inspector Comments

P.Eng Comments

The CIP abutments are noted to be constructed in 1977 and still appear to be in fair condition. The scour under the right bank CIP appears similar in extent to what it has been over the last number of years; however this needs to be constantly monitored. The log crib/wingwalls, constructed to retain road approach fills, were also constructed in 1977 (43 years old) and are in poor condition. The stability of these require constant monitoring especially when the structure is in use. If this structure is being used for industrial activity then I recommend periodic inspections be completed to determine the stability of the them prior to use. Due to the condition of the log cribs/wingwalls retaining road approach fills, I recommend reducing the load rating to L100 or 91 tonnes and planning for a replacement soon. Reconnect and realign the concrete no post barriers and post load rating signs.



CK-2031
CK-2031

STATLU 1.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

HC left approach

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Unconnected no post barriers

Posted Load Rating 136090

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Fair

CIP both abutments, right bank scoured under face up to 850mm depth

Caps or Sills Fair

Treated timbers

Piles or Posts

Ballast Wall Fair

Old logs

Wing Wall Poor

Open face log crib with significant deterioration

Bracing

Hardware

Fill Fair

Riprap N/A

Bedrock with CIP

Bearings Fair

Corrosion Protection

CK-2031
CK-2031

STATLU 1.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface

Running Planks

Fair

Sub Deck

Fair

Treated

Ties

Fair

Treated, however uneven spacing near right bank

Nails

Fair

Deck to Girder Bolts

Unrated

Not noted at time of inspection

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Good

Treated

Hand Rails/Walkouts

Hardware

Fair

Overall Deck Condition

Fair

Gravel Depth (mm)

Pier Deck

CK-2031
CK-2031

STATLU 1.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Painted girders with corrosion

Diaphragms Fair

Left bank diaphragm corrosion moderate to heavy

Bracing Fair

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2031
CK-2031

STATLU 1.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	2.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	12.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Approach fenders (re-Install). # of units. Priority:Low	Reconnect and realign all no post barriers

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Scour under right bank CIP	Routine Inspection

2	stability of log crib/wingwalls retaining road approach fills	Annually
---	---	----------

3



Approach from Right Bank when facing downstream



Load Rating Sign





Deck



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Upstream left approach barriers



Right Bank Abutment when facing downstream



Superstructure



Left bank diaphragm condition



Scour under right bank CIP extends up to 850mm from face



Left Bank Abutment when facing downstream



Debris, evidence of stream flow height



Upstream right bank wingwall condition



2020 Inspection

CBR iPad Offline Ver 0.33

STATLU 1.7km

CK-2031
CK-2031



Upstream Profile