

CK-2104
CK-2104

HARRISON EAST 6.8km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°23'54.39" Longitude -121°44'49.4"

Crossing Name Slollicum Creek

FSR # 5748 Branch # 1

Road Name HARRISON EAST

User km 6.8

Previous Load Rating (tonnes) 91

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 27.7

Deck Width (m) 6.9

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5499009.6 Accuracy (m)

L100 or 91 tonnes

Inspection

Date of Inspection 2020-06-04 2:59:38 PM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2023

Inspection Company FLNRORD

Inspector Comments

P.Eng Comments

The upstream guardrail was struck and all 14 risers have sustained damage, replace them all and ensure they are properly connected to the W beam. Replace the eroded fill at the downstream left bank location. Replace the missing delineator and brush both approaches. Remove all sediment from the deck. Monitor the lockblocks retaining fill at the downstream right bank. Monitor the old log crib retaining fill at both abutments. The current load rating of L100 or 91 tonnes to continue.



2020-11-25

P.Eng Seal

CK-2104
CK-2104

HARRISON EAST 6.8km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Tight HC and VC both approaches

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating 91000

Road Surface Good

Abutment

Log/Timber Cribs Fair Old log crib under existing structure for fill retention

Tie Backs Poor End splitting and rot noted at ends

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Wing Wall Good Lock blocks downstream right bank - 2nd and 3rd rows are slightly out of alignment and could have been like this since installation - monitor

Bracing Good

Hardware

Fill Fair Old log cribs are retaining fill at both abutments, and the downstream left bank is eroding from a lack of surface drainage

Riprap NA Both abutments set back from the stream and elevated

Bearings Fair

Corrosion Protection Good

CK-2104
CK-2104

HARRISON EAST 6.8km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair sediment collecting on downstream deck edge

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor All 14 upstream risers damaged, but rail still functional

Hand Rails/Walkouts

Hardware Poor Rail bolts connecting Wbeam to risers not functioning at all locations

Overall Deck Condition Poor Due to riser condition along upstream edge

Gravel Depth (mm)

Pier Deck

CK-2104
CK-2104

HARRISON EAST 6.8km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Good 4800mm between girders

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2104
CK-2104

HARRISON EAST 6.8km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	15.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	10	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Area/sight line brushing. m ² . Priority:Low	Brush approaches
2 Structure. Curb Maintenance. # sites. Priority:High	Replace all 14 risers at upstream end
3 Structure. Delineator maintenance. . Priority:Low	Replace missing delineator
4 Approach. Approach fill repair. m ³ . Priority:Medium	Repair fill at down stream left approach
5 High	Remove sediment from deck

6

7

Item	Monitor Description	Frequency
1	lockblocks retaining fill at the downstream right abnk	Routine Inspection
2	old log crib retaining fill at both abutments	Routine Inspection
3		



Approach from Left Bank when facing downstream



Load Rating Sign



Approach from Left Bank when facing downstream



Fill erosion down stream left bank



Guard Rail



Guard Rail



Upstream from Crossing



Downstream from Crossing



Damaged guardrail and risers entire upstream



Upstream guardrail damage



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Superstructure



Lock blocks retaining fill at downstream right bank



Right Bank Abutment when facing downstream



Downstream left bank