

CK-2287
CK-2287

SILVERHOPE 0.6km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°9'30.09" Longitude -121°19'42.6"

Crossing Name Silverhope Creek (structure #
FSR # 8148 Branch # 1

Road Name SILVERHOPE

User km 0.6

Previous Load Rating (tonnes) 41

Structure Class Temporary Bridge

Portable Y

Superstructure Steel Truss/Bailey/Acrow

Deck Type Timber - Untreated

Abutment Left Concrete Lock Blocks

Abutment Right Concrete Lock Blocks

Spans 1

Total Length (m) 20

Deck Width (m) 4.4

Updated Data

Latitude 49°9'30.85" Longitude -121°19'41.91"

HD Diff. (m) 27.1 Accuracy (m) 5

L10 or 9 tonnes

Inspection

Date of Inspection 2020-06-17 10:03:16 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2022

Inspection Company FLNRORD

Inspector Comments

This road has limited usage and likely wilderness status. Monitor the condition of the lock blocks and timber deck.

P.Eng Comments

Replace all timber deck components. Brush approaches. Post bridge ahead signs and replace missing delineators. Limit loading to L10 or 9 tonnes, post load rating signs. Monitor the condition of the lock blocks.



2020-12-03

P.Eng Seal

CK-2287
CK-2287

SILVERHOPE 0.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Fair

Old logs

Posted Load Rating

Not posted

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Fair

3 high x 2 wide lock block columns at each corner - right bank blocks have noted cracking and efflorescence

Caps or Sills

Piles or Posts

Ballast Wall Fair

Wing Wall

Bracing

Hardware

Fill Good

Riprap Good

Bearings Fair

Corrosion Protection

CK-2287
CK-2287

SILVERHOPE 0.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface

Running Planks	Poor	Rotten
----------------	------	--------

Sub Deck	Poor	Rotten
----------	------	--------

Ties	Poor	Rotten
------	------	--------

Nails	Poor	Protruding
-------	------	------------

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts	Poor	Rotten
------------------------	------	--------

Hand Rails/Walkouts

Hardware

Overall Deck Condition	Poor	Rotten
------------------------	------	--------

Gravel Depth (mm)

Pier Deck

CK-2287
CK-2287

SILVERHOPE 0.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair 6 panel Double single acrow

Diaphragms

Bracing Fair Minor deformation with random braces

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2287
CK-2287

SILVERHOPE 0.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	9.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Area/sight line brushing. m². Priority:Medium	Brush approaches
2 Approach. Bridge Ahead Signs. # of signs. Priority:Medium	Post bridge ahead signs
3 Approach. Add Warning Signs. # of signs. Priority:Medium	Post load rating signs
4 Structure. Major redecking (crossties or laminated deck). m. Priority:High	Replace entire deck system
5 Structure. Delineator maintenance. . Priority:Medium	Replacing missing delineators

6

7

Item	Monitor Description	Frequency
1	Lock block condition	Routine Inspection
2		
3		



Approach from Right Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Superstructure



Upstream left bank bearing plate



Downstream Profile



Concrete surfacing at approach



Left Bank Abutment when facing downstream



Downstream right bank lock blocks

CK-2287
CK-2287

SILVERHOPE 0.6km

2020 Inspection

CBR iPad Offline Ver 0.33

