

CK-2452
CK-2452

NORRISH 7.1km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°13'58.5" Longitude -122°8'9.2"

Crossing Name Rose Creek

FSR # 10326 Branch # 1

Road Name NORRISH

User km 7.1

Previous Load Rating (tonnes) 150

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Concrete Cast in Place

Abutment Right Concrete Cast in Place

Spans 1

Total Length (m) 18.3

Deck Width (m) 4.8

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5480583.3 Accuracy (m)

L165 or 150 tonnes

Inspection

Date of Inspection 2020-05-27 9:41 AM

Inspector Name Tyson Miller

Recommended Next Inspection Year 2023

Inspection Company FLNRORD

Inspector Comments

P.Eng Comments

Reattach the upstream right bank bull nose to the concrete barriers. Brush and grade approaches. Monitor the condition of both abutments. The current load rating of L165 or 150 tonnes to continue.



CK-2452
CK-2452

NORRISH 7.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good Upstream right approach bull nose not connected

Posted Load Rating 149700

Road Surface Fair

Abutment

Log/Timber Cribs Fair 3x face logs with up to 50mm sap rot onto top of CIP on left bank

Tie Backs Fair 4x under top face log and 3x under 2nd face log, all with end splits

Bin Wall

Pier

Concrete Fair CIP left bank with vertical crack under the upstream girder - no apparent change from old inspections. Lock blocks on right bank - some have spalls and others have visible cold joints

Caps or Sills Fair Single log sill on top of lock blocks with up to 60mm sap rot

Piles or Posts

Ballast Wall Fair

Wing Wall

Bracing

Hardware Good

Fill Fair

Riprap Poor None in front of either abutment

Bearings Fair

Corrosion Protection

CK-2452
CK-2452

NORRISH 7.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Good

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair wear on wheel path

Grout Pockets Good

Deck Joints Good

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Good

Gravel Depth (mm)

Pier Deck

CK-2452
CK-2452

NORRISH 7.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Painted steel box girders

Diaphragms Fair

2 painted bays

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2452
CK-2452

NORRISH 7.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	15.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments Upstream left bank CIP is scoured and vertical crack directly under upstream girder

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Approach surfacing grading. m. Priority:Low	Grade approaches
2 Approach. Approach fenders (re-Install). # of units. Priority:Low	Reattach upstream right approach bull nose
3 Low	Brush approaches
4	
5	
6	
7	

Item	Monitor Description	Frequency
1	Abutment condition	Every Routine Inspection
2		
3		



Approach from Right Bank when facing downstream



Upstream right approach bull nose



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Scour under upstream left bank CIP



Vertical crack in CIP directly under upstream girder



Left Bank Abutment when facing downstream



Scour under upstream left CIP



Lock block on right bank abutment



Lock block condition at right bank abutment



Lock block condition at right bank abutment



Superstructure