

CK-2369
CK-2369

SPUZZUM 24000 2.3km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°44'9.6" Longitude -121°39'35.3"

Site Status Active

Insp. Status Inspect

Crossing Name side creek

FSR # 8128 Branch # 21

Road Name SPUZZUM 24000

User km 2.3

Previous Load Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Removable

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 27.5

Deck Width (m) 4.9

Updated Data

Latitude 49°44'9.92" Longitude -121°39'35.72"

HD Diff. (m) 13.0 Accuracy (m) 5

Inspection

Date of Inspection 2022-11-02 8:50:46 AM

Inspector Name Cameron VandenBrink, EIT

Recommended Next Inspection 2024

Inspection Company Chartwell Resource Group Ltd

Inspector Comments Serial/ID Plate

P.Eng Comments

Load Rated by: MoF, M.Lowe, RPF, PEng, February 16, 2023
Load Rating: 5 Tonnes GVW
Next Inspection: September 1, 2025
Comments: Load rating only due to guard rail condition. Replace rails prior to next use.



PERMIT TO
PRACTICE: 1003022

CK-2369
CK-2369

SPUZZUM 24000 2.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

HC and vc left approach, HC right approach

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Not posted

Road Surface Fair

Potholes each end

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Good

Ballast Wall Fair Damage at tops of both abutments

Wing Wall

Bracing Good

Hardware

Fill Good

Riprap Good

Bearings Fair Bulging

Corrosion Protection Good

CK-2369
CK-2369

SPUZZUM 24000 2.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface

Potholes each end

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts **Good**

Concrete Deck **Fair** Various damage noted

Grout Pockets

Deck Joints **Fair** Poor- does not appear to have been sealed.

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Fair** Poor-rotten. No work done since 2019 inspection

Hand Rails/Walkouts

Hardware **Poor** Loose rail bolts

Overall Deck Condition **Poor** Due to rail and deck condition.

Gravel Depth (mm)

Pier Deck

CK-2369
CK-2369

SPUZZUM 24000 2.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good Very minor corrosion starting,

Diaphragms Good 6 bolted bays

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

CK-2369
CK-2369

SPUZZUM 24000 2.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	11	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	1.5	lc	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Full Curb Replacement. . Priority:Medium	Guardrail system replacement as called up in previous report.
2 Structure. Concrete structural maintenance. m². Priority:Medium	Deck panels and ballast walls. Add ballast to each approach once complete to limit impacts.
3 Approach. Area/sight line brushing. m². Priority:Low	Brush and grade

4

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Approach from bridge deck of Left bank approach when facing downstream



Upstream from Crossing



Downstream from Crossing



Approach from bridge deck of Right bank approach when facing downstream



Approach from Right Bank when facing downstream



Right bank panel 1 ballast wall and panel damage



Left bank panel 1 ballast wall and panel damage



Structure ID



Deck to girder bolt



Bearing



Superstructure



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Right bank bent bracing



Upstream Profile



2022 Inspection

CBR iPad Offline Ver 0.36

SPUZZUM 24000 2.3km

CK-2369
CK-2369



Downstream Profile