

CK-2441
CK-2441

FIFTEEN MILE 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°28'28.49" Longitude -121°15'39.4"

Site Status Barricaded/Closed

Insp. Status Inspect

Crossing Name Fifteen Mile Creek

FSR # 10452 Branch # 1

Road Name FIFTEEN MILE

User km 1.5

Previous Load Rating (tonnes) 0

Structure Class Temporary Bridge

Portable N

Superstructure Rail Car

Deck Type Timber - Untreated

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 16

Deck Width (m) 5.6

Updated Data

Latitude 49°28'27.74" Longitude -121°15'39.28"

HD Diff. (m) 23.7 Accuracy (m) 4

5 tonnes

Inspection

Date of Inspection 2022-09-28 12:15:28 PM

Inspector Name Tyson Miller

Recommended Next Inspection 2024


Inspection Company MoF

Inspector Comments

Timber deck sufficient for pickup traffic

P.Eng Comments

The Hawker Siddeley railcar subframes are still in fair condition and can be reused for industrial traffic once the timber deck and timber sills have been replaced. Replace the entire timber deck system (cross ties, planks, guardrail and risers) and both abutment timber sills. Ensure the railcar subframes are replaced and fastened to the new timber sills as they were prior to their removal, ensuring the same span. Ensure the cross ties are fastened to the cross tie clips. Brush and grade approaches. Post bridge ahead signs. 5 tonnes load limit until repair items have been completed. Post load rating sign.



PERMIT TO
PRACTICE: 1003022

CK-2441
CK-2441

FIFTEEN MILE 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

HC both approaches

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Concrete no post barriers

Posted Load Rating 0

Not posted

Road Surface Poor

Vegetation growing within subgrade

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

5 lock blocks wide

Caps or Sills Poor

Rotten timber sill

Piles or Posts

Ballast Wall Unrated

Not visible

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection

CK-2441
CK-2441

FIFTEEN MILE 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Vegetation growing within subgrade

Running Planks Poor Rotten

Sub Deck

Ties Poor Rotten

Nails Fair

Deck to Girder Bolts fair difficult to assess

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Rotten

Hand Rails/Walkouts

Hardware

Overall Deck Condition Poor Entire deck system requires replacement

Gravel Depth (mm)

Pier Deck

CK-2441
CK-2441

FIFTEEN MILE 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Fair

2 Hawker Siddeley railcars

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2441
CK-2441

FIFTEEN MILE 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Area/sight line brushing. m². Priority:High	Brush prior to activity
2 Approach. Approach surfacing grading. m. Priority:Medium	
3 Structure. Major redecking (crossties or laminated deck). m. Priority:High	Replace ties and planks prior to industrial activity
4 Substructure. Timber caps and log sills. m². Priority:High	Replace timber sills prior to industrial activity
5 Approach. Bridge Ahead Signs. # of signs. Priority:Medium	Post bridge ahead signs prior to industrial activity

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Approach from Left Bank when facing downstream



Deck





Upstream from Crossing



Downstream from Crossing



Deck



Approach from Right Bank when facing downstream



Timber sill condition at right bank



Left Bank Abutment when facing downstream



Superstructure



Superstructure



Superstructure



Right Bank Abutment when facing downstream



Tie condition



Bearing plate and girder connection



Timber sill condition at left bank



Upstream Profile

DRAWING DE100-03 R.
JUNE 2007.



B.C.T.S.

CHINOOK,
B.C. TIMBER SALES
REPLACEMENT
RAILCAR BRIDGE
ASSEMBLY DETAILS
ROAD. - DE100.
LOCATION 15M. CREEK
DRAWING NO DE10003.
DRAWN H WARGENT. PENG.
DATE MAY 2007