

CK-2260
CK-2260

STAVE 3.5km

2022 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°27'13.79" Longitude -122°13'8.8"

Crossing Name Roaring Creek

FSR # 8013 Branch # 1

Road Name STAVE

User km 3.5

Previous Load Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 21.3

Deck Width (m) 4.9

Updated Data

Latitude Longitude

HD Diff. (m) Accuracy (m)

10 tonnes

Inspection

Date of Inspection 2022-01-24 11:56:03 AM

Recommended Next Inspection Year 2022

Inspector Name Tyson Miller

Inspection Company FLNRORD

Inspector Comments

The woods abutment was damaged (scoured) in the November flood event. Material from under the upstream woods abutment footing has scoured resulting in settlement and rotation. Scour protection (riprap) has been added in front of this footing; however the footing is still exposed and further scour/settlement could occur. This needs to be monitored. A longer bridge is likely required

P.Eng Comments

Limit loading to 10 tonnes, post load rating signs. If a higher rating is required please submit a detailed plan for how the bearing material directly under the upstream woods abutment footing will be reinstated along with how the structure will be monitored during these required crossings. Irregardless of whether or not a higher rating is required, please ensure continuous monitoring of this site while the structure is in use.



P.Eng Seal

CK-2260
CK-2260

STAVE 3.5km

2022 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating Not posted

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Poor

The upstream woods abutment pipe column is no longer vertical. Material from under this footing has been scoured resulting in settlement and rotation.

Ballast Wall Good

The tops of both ballast walls have had recent repairs made

Wing Wall

Bracing Fair

Hardware

Fill Fair

Significant erosion had occurred at the upstream woods abutment in the November flood event. Temporary repairs have been completed to this abutment

Riprap Poor

None in front of woods abutment footings

Bearings Poor

Material from under the the upstream woods abutment precast footing has been scoured. This footing has settled and rotated. The bearing plates at this location are still functioning however; likely under significant stress. Monitor their condition.

Corrosion Protection Fair

CK-2260
CK-2260

STAVE 3.5km

2022 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Fair** Minor damage due to tracked equipment

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

CK-2260
CK-2260

STAVE 3.5km

2022 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Slight misalignment due to settled footing but do not appear damaged.

Diaphragms Good

5 bolted bays

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

CK-2260
CK-2260

STAVE 3.5km

2022 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	15.0	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Add Warning Signs. # of signs. Priority:High	Post load rating signs

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	upstream woods abutment settlement	Continuous while in use

2

3



Approach from Right Bank when facing downstream



Deck



Upstream woods end deck lower in elevation



Approach from Left Bank when facing downstream



Structure ID



Right Bank Abutment when facing downstream



Upstream woods abutment has settled



Superstructure



Upstream from Crossing



Upstream woods abutment



Upstream woods abutment pipe column leans to fill side



Upstream woods footing scour



Upstream woods pipe column condition



Right Bank Abutment when facing downstream