

QC-7838

QC_NEY2000 0.74km

2017 Inspection



CBR iPad Offline Ver

CBR Data

Latitude	Longitude
53°33'11.7"	-132°6'17.5"
Crossing Name	Not Known
FSR #	10324
Branch #	2
Road Name	QC_NEY2000
User km	0.74
Current Load Rating (tonnes)	91
Structure Class	Temporary Bridge
Portable	Y
Superstructure	Steel Box Beam
Deck Type	Steel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	12.2
Deck Width (m)	4.84

Updated Data

Latitude	Longitude
53°33'11.16"	-132°6'17.59"
HD Diff. (m)	16.7
Accuracy (m)	5
4.88	

Inspection

Date of Inspection 2017-09-14 2:15:49 PM

Inspector Name Mitch Lowe

Inspector Comments

Minor issues, but simple repairs can fix some issues.

Recommended Next Inspection Year 2018

Inspection Company Onsite Engineering Ltd

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey, November 7, 2017

Load Rating: 91 Tonnes GVW

Next Inspection: September 1, 2020

Comments:



P.Eng Seal

QC-7838

QC_NEY2000 0.74km

2017 Inspection



CBR iPad Offline Ver

Approach

Alignment Fair

Steep grade onto bridge on river left approach.

Bridge Ahead Signs
Missing
☒ 0
 ☐ 1
 ☐ 2

Brushing Required N

Delineator Missing
Left
☒ 0
 ☐ 1
 ☐ 2
Delineator Missing
Right
☒ 0
 ☐ 1
 ☐ 2

Fender Condition Poor

Approach logs have rolled off to sides.

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribbs Fair

Two high log cribs. Downstream half of river right abutment is not fully supported and is undermined.

Tie Backs Fair

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall Poor

Structure does not have ballast walls.

Wing Wall Fair

Bracing

Hardware

Fill Poor

Fill under right downstream half of abutment has eroded.

Riprap

Bearings Poor

Bearing plates do not fully bear on cribs (up to 4" in some spots). Downstream river right half is poorly cut and structure should be shimmed.

Corrosion Protection

QC-7838

QC_NEY2000 0.74km

2017 Inspection

CBR iPad Offline Ver



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate **Fair**

Gravel Surface

Curb Rail/Blocks/Posts **Fair**

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Fair**

Gravel Depth (mm)

QC-7838

QC_NEY2000 0.74km

2017 Inspection



CBR iPad Offline Ver

Steel/Concrete

Serial/ID Plate TCH-0703 MOF L100 TCH0702 12.192m Mar07 W0356718

Girders Good

Diaphragms N/A

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

QC-7838

QC_NEY2000 0.74km

2017 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	0.6	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	4	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	0.5	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item	Priority	Repair Description
1	Medium	Shim downstream river right half of abutment to ensure structure full bears on cribs.

2

3

Item	Monitor Description	Frequency
1	Monitor downstream half of river right abutment for further progression of erosion.	Routine Inspection

2

3

Sketch
(Select Signature)