

SQ-3105
SQ-3105

FURRY CREEK 02 0km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°34'35.69"	-123°11'50.1"
Crossing Name	Phylis Creek #1
FSR #	8210
Branch #	2
Road Name	FURRY CREEK 02
User km	0
Previous Load Rating (tonnes)	5
Structure Class	Temporary Bridge
Portable	N
Superstructure	Rail Car
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	17.5
Deck Width (m)	4.8

Updated Data

Latitude	Longitude
49°34'36.04"	-123°11'52.42"
HD Diff. (m)	47.8
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-08 11:13:35 AM

Recommended Next Inspection Year

Inspector Name Greg Dohm

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate


Deck has holes and is not an acceptable type of deck for railcar bridges .

Deck has holes on it and is unconventional deck. Requires timber deck replacement before next use.

Downrate to zero tonnes until deck upgraded.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021
Load Rating: 0 tonnes
Next Inspection: 2021
Comments: Close bridge until deck upgraded and holes in deck are repaired.



P.Eng Seal

SQ-3105
SQ-3105

FURRY CREEK 02 0km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Steep approach on woods side

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 10

Road Surface Fair

Abutment

Log/Timber Cribs Fair

Holds back fills. Crib bottom face log heavily undermined but still appears stable at point loads on boulders.

Tie Backs Poor

Applies to crib holding back abutment fills

Bin Wall

Pier

Concrete

Caps or Sills Unrated

Or visible as is behind crib retaining abutments.

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

SQ-3105
SQ-3105

FURRY CREEK 02 0km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Poor

Running Planks

Sub Deck Poor See notes above for railcar bridge superstructure

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Poor Deck has holes and is not an acceptable type of deck for railcar bridges

Gravel Depth (mm)

Pier Deck

SQ-3105
SQ-3105

FURRY CREEK 02 0km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms

Bracing N/A

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3105
SQ-3105

FURRY CREEK 02 0km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance (m)

Ice ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

- | | | |
|---|---|--|
| 1 | Structure. Timber deck maintenance. 1 # of signs. Priority:High | Deck has holes on it and is unconventional deck. Requires timber deck replacement before next use. |
|---|---|--|

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



Deck



Load Rating Sign



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Downstream Profile



Right Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Superstructure



Left Bank Abutment when facing downstream



Downstream from Crossing



Upstream from Crossing



Upstream Profile



Upstream Profile



Bearing