

SQ-3169
SQ-3169

FURRY CREEK 03 0.5km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°33'30.7"	-123°10'53.7"
Crossing Name	No Name
FSR #	8210
Branch #	3
Road Name	FURRY CREEK 03
User km	0.5
Previous Load Rating (tonnes)	20
Structure Class	Temporary Bridge
Portable	N
Superstructure	Rail Car
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	17.2
Deck Width (m)	4.8

Updated Data

Latitude	Longitude
49°33'31.06"	-123°10'53.18"
HD Diff. (m)	15.1
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-08 10:35:49 AM

Inspector Name Greg Dohm

Recommended Next Inspection Year

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Deck has unconventional 2" thick planks over corroding steel transverse purlins. Needs proper timber tie deck. Load rating to be down rated.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021

Load Rating: 5 tonnes

Next Inspection: 2021

Comments: Downrate bridge load rating to 5 tonnes due to type and condition of bridge deck. Deck has unconventional 2" thick planks over corroding steel transverse purlins. Needs proper timber tie deck. Load rating to be down rated. This a private bridge. Ministry will no longer inspect. Industry responsible for inspection in future.



P.Eng Seal

SQ-3169
SQ-3169

FURRY CREEK 03 0.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor Rotting and missing

Posted Load Rating 62

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection Poor Aging rail car

SQ-3169
SQ-3169

FURRY CREEK 03 0.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks Poor unconventional 2" thick planks over corroding steel transverse purlins. Needs proper timber tie deck. Load rating to be down rated.

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair Lashed logs

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair Assuming wood plank deck ok

Gravel Depth (mm)

Pier Deck

SQ-3169
SQ-3169

FURRY CREEK 03 0.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3169
SQ-3169

FURRY CREEK 03 0.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m) .13

High Water ☐

Debris ☐

Estimated Present Water Level Width (m) 5

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance (m) 3

Ice ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1 Structure. Timber deck
maintenance. 1 # of signs.
Priority:High

Replace deck with timber deck

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



2020 Inspection

CBR iPad Offline Ver 0.33

FURRY CREEK 03 0.5km

SQ-3169
SQ-3169



Approach from Right Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Upstream Profile



Right Bank Abutment when facing downstream



Superstructure



Superstructure



Left Bank Abutment when facing downstream



Superstructure



Superstructure



2020 Inspection

CBR iPad Offline Ver 0.33

FURRY CREEK 03 0.5km

SQ-3169
SQ-3169



Downstream Profile



Deck