

SQ-3086
SQ-3086

LILLOOET SOUTH 01 23.9km

2022 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 50°35'43.1" Longitude -123°22'19.5"

Crossing Name Perkins Creek

FSR # 7977 Branch # 1

Road Name LILLOOET SOUTH 01

User km 23.9

Previous Load Rating (tonnes) 63

Structure Class Temporary Bridge

Portable N

Superstructure Rail Car

Deck Type Timber - Untreated

Abutment Left Concrete Lock Blocks

Abutment Right Concrete Lock Blocks

Spans 1

Total Length (m) 17.6

Deck Width (m) 4.8

Updated Data

Latitude 50°35'43.37" Longitude -123°22'18.85"

HD Diff. (m) 15.1 Accuracy (m) 5

Inspection

Date of Inspection 2022-10-19 12:28:48 PM

Recommended Next Inspection Year

Inspector Name Gino Fournier

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Replace full deck components due to rot. Consider downrating structure until completed.


P.Eng Comments

Load Rated by: MOF, Greg Dohm, PEng., Oct. 26, 2022

Load Rating: L45 or 41 tonnes

Next Inspection: 2023

Comments: Downrate load rating to L45 or 41 tonnes due to deteriorating timber deck. Replace full deck components and ideally replace crushing timber sills with treated or cedar timber sills for continued industrial use.



P.Eng Seal

SQ-3086
SQ-3086

LILLOOET SOUTH 01 23.9km

2022 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair Fair for slow speed road

Bridge Ahead Signs Missing ☒ 0 ☐ 1 ☐ 2 It needed due to slow speed

Brushing Required Y

Delineator Missing Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair Left side has no approach logs. Could add some

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete N/A

Caps or Sills Poor Starting to crush. Should consider replacement as deck is replaced

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Good

Riprap Fair

Bearings N/A

Corrosion Protection N/A

SQ-3086
SQ-3086

LILLOOET SOUTH 01 23.9km

2022 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface	Poor	
Running Planks	Poor	Rotting deck and holes appearing
Sub Deck	N/A	
Ties	Poor	Ties sounded and minimum 50% are rotten. Replace all ties with deck and rails
Nails	Poor	Starting to pop with the warm ties
Deck to Girder Bolts	Fair	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	Easily move due to rotten ties and loose bolts.
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Poor	Replacement needed.
Gravel Depth (mm)		
Pier Deck	N/A	

SQ-3086
SQ-3086

LILLOOET SOUTH 01 23.9km

2022 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair Railcar

Diaphragms N/A

Bracing Fair

Under Trussing N/A

Hardware Fair

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3086
SQ-3086

LILLOOET SOUTH 01 23.9km

2022 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.4	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Major redecking (crossties or laminated deck). m. Priority:High	Replace ties, deck and guardrails. Should replace sills Botha sides as well.

2

3


4

5

6

7


Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Sills showing age and crushing