

SQ-3106
SQ-3106

BLACKWATER CREEK 0.1km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 50°31'56.2" Longitude -122°30'32.9"

Site Status Active

Insp. Status Inspect

Crossing Name Blackwater Creek

FSR # 8354 Branch # 1

Road Name BLACKWATER CREEK

User km 0.1

Previous Load Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Concrete Slab Girders

Deck Type Concrete

Abutment Left Concrete Lock Blocks

Abutment Right Concrete Lock Blocks

Spans 1

Total Length (m) 13.1

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5625227.5 Accuracy (m)

Inspection

Date of Inspection 2022-09-28 11:09:28 AM

Inspector Name Forrest Simpson

Recommended Next Inspection 2023


Inspection Company MoF

Inspector Comments Serial/ID Plate

Right bank riprap large and poorly graded. Creek is travelling under upstream corner of riprap. Depending how many rows of lock blocks, Footings at risk of scour if continues to migrate/erode. Underside of girders have hairline cracks running laterally and longitudinally. All girders, multiple places mid span. Monitor both items. Consider increasing inspection frequency y to annual.

P.Eng Comments

Load Rated by: MOF, Greg Dohm, PEng., Oct. 5, 2022
Load Rating: L75 or 68 tonnes
Next Inspection: 2025
Comments:



PERMIT TO
PRACTICE: 1003022

SQ-3106
SQ-3106

BLACKWATER CREEK 0.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **Y**

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete **Good** Lock blocks

Caps or Sills

Piles or Posts

Ballast Wall **Good**

Wing Wall

Bracing

Hardware

Fill **Good**

Riprap **Poor** Right bank large, but poorly grade. Getting Undermined

Bearings **Good**

Corrosion Protection

SQ-3106
SQ-3106

BLACKWATER CREEK 0.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Fair** Surface damage. Rebar exposed. Patch

Grout Pockets

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good** New hss

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Good** Except for patch needed

Gravel Depth (mm)

Pier Deck

SQ-3106
SQ-3106

BLACKWATER CREEK 0.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Fair

Cracks in concrete, see notes.

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3106
SQ-3106

BLACKWATER CREEK 0.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance	1.8	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Concrete structural maintenance. m². Priority:High	Patch deck in multiple places.

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Concrete slab girders for hairline crack growth,	Anually
2	Right bank riprap/abutment forms undermining and scour	Anually

3



Approach from Right Bank when facing downstream



Deck



Deck



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Superstructure



Superstructure



Superstructure



2022 Inspection


CBR iPad Offline Ver 0.36

BLACKWATER CREEK 0.1km

SQ-3106
SQ-3106



Superstructure



Downstream from Crossing



Upstream from Crossing