

SQ-3165
SQ-3165

KAKILA CREEK 60.4km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 50°7'21.1" Longitude -122°31'57.1"

Site Status Active

Insp. Status Inspect

Crossing Name Kakila South Creek

FSR # 8407 Branch # 2

Road Name KAKILA CREEK

User km 60.4

Previous Load Rating (tonnes) 62

Structure Class Major Culvert

Culvert Type Open Bottom

Culvert Material Corrugated Steel

Opening Height (mm) 1800

Opening Width (mm) 4000

Inlet Cover (mm) 700

Outlet Cover (mm) 700

Culvert Gradient % 2

Culvert Length (m) 7.2

Updated Data

Latitude 50°7'20.11" Longitude -122°31'57.89"

HD Diff. (m) 34.5 Accuracy (m) 8

Inspection

Date of Inspection 2022-10-20 1:46:28 PM

Inspector Name Gino Fournier

Recommended Next Inspection

Inspection Company MoF

Inspector Comments

Structure should be replaced and not used by industrial activity until replaced due to poor construction and erosion.


P.Eng Comments

Load Rated by: MOF, Greg Dohm, PEng., Oct. 26, 2022

Load Rating: BCL625 or 63 tonnes

Next Inspection: 2023

Comments: structure footings are beginning to undermine outside of roadway. Further erosion to under roadway will result in closing of crossing. Plan to replace structure and adjacent wood box culvert.



PERMIT TO
PRACTICE: 1003022

SQ-3165
SQ-3165

KAKILA CREEK 60.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2 Not needed. Real slow road

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated None needed for culvert

Posted Load Rating 65

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Poor Erosion of fill under footing and behind structure on outside edges.

Riprap Fair

Bearings

Corrosion Protection

SQ-3165
SQ-3165

KAKILA CREEK 60.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles	N/A	
Bolted Connections	N/A	
Coating	Fair	
Coupled Connections	N/A	
Embedment Materials	N/A	
Fill	Poor	Erosion of fill under footing and behind structure on outside edges.
Floor	Unrated	Open bottom
Footing	Poor	Erosion on right side occurring.
Head Walls	Fair	Locblocks not placed deep enough and being eroded
Inlet	Poor	Too small. Structure should be replaced with bridge
Outlet	Poor	Erosion
Overall	Poor	Due to footing erosion and support to arch by old log culvert.
Rip Rap	Poor	Poor, due to placement on old log structure and vertically stacked.
Roof	Good	
Sidewalls	Poor	Erosion occurring at inlet and outlet
Trash Rack	N/A	
Weirs/Backwater Structures	N/A	
Wing Walls	N/A	

SQ-3165
SQ-3165

KAKILA CREEK 60.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs N/A

Needle Beam N/A

Needle Lashing/
Shimming N/A

Stringer Number	Species	Needle Beam to Crib (m) Peeled	Diameter (mm)	Needle Diameter (mm) Rot Depth (mm)	Condition	Comment
--------------------	---------	-----------------------------------	------------------	---	-----------	---------

SQ-3165
SQ-3165

KAKILA CREEK 60.4km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.1	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	3	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance	1	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Multiplate/culvert maintenance. m³. Priority:High	Replace structure with appropriately sized bridge, likely a slab would work.

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Erosion of structure.	Anually

2

3



Inlet



Inlet of both old log culvert and arch. Arch footing supported by log sill and old culvert supporting riprap



Upstream Profile



Right upstream footing erosion under footing.



2022 Inspection

CBR iPad Offline Ver 0.36

KAKILA CREEK 60.4km

SQ-3165
SQ-3165



Looking at outlet.



Looking at outlet from downstream.