



Associated
Engineering

GLOBAL PERSPECTIVE.
LOCAL FOCUS.

BRIDGE INSPECTION REPORT

GLULAM BRIDGE INSPECTION SUMMARY



Ministry of
Forests and Range
Forest Service

Business Area	Location	Road Name	Project #	Sta. (km)	Easting
Nadina		Morice-Tahisa FSR	9947.02	24.00	Northing
Bridge Name	Site ID	Stream Name	Class.	Inspected By	Inspection Date
	RS-032	Nadina River		D. Chen	30-Sep-08
Superstructure Type	Deck Type	Substructure Type	Live Load Rating		
Glulam	Timber	Timber Piles/ Concrete	Present	41 tonnes	New 41 tonnes
Bridge Length	# Spans	Span Length(s)	Deck Width	Bridge Use	Installation Date
23.3 m	1	22.8 m	4.2 m	Permanent	1963

Reference Drawings

NOTES: Excellent : New or almost new condition and properly installed

Good : Structurally sound, in good repair and have minimal wear

Fair : Structurally sound, but show moderate wear or preliminary indications of rot or corrosion

Poor : Structurally unsound, major items in need of repair or replacement, or bridge load rating should be reduced

Abutment, spans, piers numbered from left bank, facing downstream.

BRIDGE ELEMENT		CONDITION		REMARKS	
Approach Road		Fair		Potholes at woods end approach.	
Alignment		Fair		Horizontal curve at camp end approach.	
Visibility		Fair			
Signage		N/A			
Delineators		Poor		No delineators at both approaches.	
Barriers		N/A		No guide rails at both approaches.	
Overall		Poor			
Timber Deck		Fair		5 - 200x100 untreated wearing planks along each wheel line; pockets of rot noted in 4 planks. 1 plank at camp end is rotten. Drilled, moist near underside. Woods debris and gravel accumulation on deck.	
Ties & Subdeck		Fair		180mm thick creosote treated transversely laminated structural deck. Drilled at 3 locations, moist, initial stages of rot noted.	
Nails		Good			
Deck to Girder Bolts		Good			
Curbs & Blocks		Fair		Typical checking and rub damage along both curb rails. Curb rails do not conform to the current MoF standards.	
Hand Rails		Poor		Minor damage noted on downstream hand rails. 1 rail near woods end broken.	
Hardware		Fair			
Overall		Fair			



Associated
Engineering

GLOBAL PERSPECTIVE,
LOCAL FOCUS.

BRIDGE INSPECTION REPORT

GIULAM BRIDGE INSPECTION SUMMARY



Ministry of
Forests and Range
Forest Service

Business Area	Location	Road Name	Project #	Sta. (km)	Easting	437237
Nadina		Morice-Tahisa FSR	9947.02	24.00	Northing	5973097
Bridge Name	Site ID	Stream Name	Class.	Inspected By	Inspection Date	
	R5-032	Nadina River		D. Chen	30-Sep-08	
ABUTMENT CAMP END	Sill	Good	Creosote treated timber sill, minor end split noted on the downstream edge.			
	Concrete	Good	Minor edge spill noted.			
	Piles / Posts	Good	3 creosote treated soldier piles (1 u/s, 2 d/s). Piles are sound, drilled 1. Concrete base of downstream edge pile exposed, condition has not changed since last inspection.			
	Bulkhead/Wingwalls	Good	Creosote treated timber ballast wall.			
	Fill	Fair	Ballast wall edge pile tieback exposed at approach embankments.			
	Riprap	Good				
ABUTMENT WOODS END	Overall	Good				
	Caps	Good	Creosote treated timber cap beam.			
	Piles / Posts	Good	6 supporting, 8 soldier creosote treated piles (4 per wingwall) come with flashing. All piles are sound, drilled 1 supporting pile and 1 soldier pile.			
	Bracing	Good				
	Bulkhead/Wingwalls	Fair	Creosote treated timber ballast wall and wingwalls. Minor undermining of ballast wall.			
	Fill	Fair	Wingwall edge pile tieback exposed at approach embankments.			
	Riprap	Good				
	Overall	Good				

REPAIR DESCRIPTION AND COST ESTIMATE:

No.	Description	Priority	Cost Estimate
1	Install missing load posting signs (2).	High	
2	Install missing delineators (4).	High	
3	Replace 1 rotten wearing plank.	High	
4	Repair broken downstream camp end hand rail.	High	
5	Regrade approaches.	Low	
		Total	

NOTES: High : Immediate, non-recurring repair to assure public safety
Medium : Ongoing, regular maintenance items to protect capital investment
Low : Minor maintenance items or improvements to extend service life

LIVE LOAD ASSESSMENT: (In accordance with MoFR Requirements)

Vehicle	Vehicle	Comment
Off-Road	41 tonnes	Based on the inspection, there is no reason to reduce the current load rating.
Highway	CL-1 CL-2 CL-3	

COMMENTS:

Monitor undermining of woods end ballast wall. Monitor condition of exposed wingwall edge pile tieback at both approach embankments. Monitor condition of exposed concrete base of camp end ballast wall downstream edge pile. Consider installing guide rails at approaches. Consider upgrading curb rails to conform with the current MoF standards.

SEAL:



Associated
Engineering

GLOBAL PERSPECTIVE.
LOCAL FOCUS.

BRIDGE INSPECTION REPORT

GLULAM BRIDGE INSPECTION SUMMARY



Ministry of
Forests and Range
Forest Service

Business Area	Location	Road Name	Project #	Sta. (km)	Easting
Nadina		Morice-Tahtsa FSR	9947.02	24.00	Northing

437237
5973097



Figure 1-1: Upstream elevation.



Figure 1-2: Downstream elevation.



Figure 1-3: Camp end approach.



Figure 1-4: Woods end approach.



Figure 1-5: Looking upstream.



Figure 1-6: Looking downstream.



Associated
Engineering

GLOBAL PERSPECTIVE.
LOCAL FOCUS.

BRIDGE INSPECTION REPORT

GLULAM BRIDGE INSPECTION SUMMARY



Ministry of
Forests and Range
Forest Service

Business Area	Location	Road Name	Project #	Sta. (km)	Easting
Nadina		Morice-Tahisa FSR	9947.02	24.00	Northing
					437237
					5973097



Figure 1-7: General deck condition.



Figure 1-8: Rotten wearing deck plank.



Figure 1-9: Typical condition underside of the transversely laminated structural deck.



Figure 1-10: Typical edge condition of the transversely laminated structural deck.



Figure 1-11: Typical rub damage on curb rail, rot initiated.



Figure 1-12: Broken rail at camp end downstream corner.



Associated
Engineering

GLOBAL PERSPECTIVE,
LOCAL FOCUS.

BRIDGE INSPECTION REPORT

GLULAM BRIDGE INSPECTION SUMMARY



Ministry of
Forests and Range
Forest Service

Business Area	Location	Road Name	Project #	Sta. (km)	Eastling	Northling
Nadina		Morice-Tahsa FSR	9947.02	24.00		5973097



Figure 1-13: Damaged rail at woods end downstream corner.



Figure 1-15: Downstream exterior girder.




Figure 1-17: Camp end abutment.



Figure 1-14: Upstream exterior girder.



Figure 1-16: Typical unweathered face of girder.



Figure 1-18: Woods end abutment.

Business Area	Location	Road Name	Project #	Sta. (km)	Easting
Nadina		Morice-Tahisa FSR	9947.02	24.00	Northing
					437237
					5973097



Figure 1-19: Typical exposed pile tieback at abutments.



Figure 1-20: Camp end abutment timber sill.



Figure 1-21: Exposed concrete base, camp end abutment downstream ballast wall pile.



Figure 1-22: Minor undermining of the woods end abutment ballast wall.