



BC Ministry of
Forests and Range

Page 2 of 2

Bridge Register
Structure Inventory Data Form
BRIDGES

STRUCTURAL DETAILS

Number of Spans: 1		Needle Beams? ☐ Yes ☒ No																							
Length of Spans (m) [e.g. for a 3-span bridge - 20, 35, 20] 20-3 c-c	Portable Structure? ☐ Yes ☒ No		Portable Superstructure Status: ☐ Installed ☐ Storage																						
Portable Superstructure Storage Location:																									
*Bridge Length (metres): 20	*Superstructure: <table border="0"><tr><td>☐ Compo Girders</td><td>☐ Concrete Box Beam</td></tr><tr><td>☐ Concrete Cast in Place</td><td>☐ Concrete I/T Beam</td></tr><tr><td>☐ Concrete Slab Girders</td><td>☐ Glulam Girder</td></tr><tr><td>☒ Log Stringer</td><td>☐ Other</td></tr><tr><td>☐ Rail Car</td><td>☐ Steel Box Beam</td></tr><tr><td>☐ Steel I-Beam</td><td>☐ Steel Truss/Bailey/Acrow</td></tr><tr><td>☐ Timber-Treated Stringers</td><td>☐ Timber-Untreated Stringers</td></tr></table>			☐ Compo Girders	☐ Concrete Box Beam	☐ Concrete Cast in Place	☐ Concrete I/T Beam	☐ Concrete Slab Girders	☐ Glulam Girder	☒ Log Stringer	☐ Other	☐ Rail Car	☐ Steel Box Beam	☐ Steel I-Beam	☐ Steel Truss/Bailey/Acrow	☐ Timber-Treated Stringers	☐ Timber-Untreated Stringers								
☐ Compo Girders	☐ Concrete Box Beam																								
☐ Concrete Cast in Place	☐ Concrete I/T Beam																								
☐ Concrete Slab Girders	☐ Glulam Girder																								
☒ Log Stringer	☐ Other																								
☐ Rail Car	☐ Steel Box Beam																								
☐ Steel I-Beam	☐ Steel Truss/Bailey/Acrow																								
☐ Timber-Treated Stringers	☐ Timber-Untreated Stringers																								
*Deck Type: <table border="0"><tr><td>☐ Concrete</td><td>☐ Concrete Composite</td></tr><tr><td>☐ Concrete Removable</td><td>☒ Gravel</td></tr><tr><td>☐ Other</td><td>☐ Steel</td></tr><tr><td>☐ Steel Free</td><td>☐ Timber-Treated</td></tr><tr><td>☐ Timber-Treated Panels</td><td>☐ Timber-Untreated</td></tr><tr><td>☐ Timber-Untreated Panels</td><td></td></tr></table>		☐ Concrete	☐ Concrete Composite	☐ Concrete Removable	☒ Gravel	☐ Other	☐ Steel	☐ Steel Free	☐ Timber-Treated	☐ Timber-Treated Panels	☐ Timber-Untreated	☐ Timber-Untreated Panels		*Deck Width (metres): 6.0											
☐ Concrete	☐ Concrete Composite																								
☐ Concrete Removable	☒ Gravel																								
☐ Other	☐ Steel																								
☐ Steel Free	☐ Timber-Treated																								
☐ Timber-Treated Panels	☐ Timber-Untreated																								
☐ Timber-Untreated Panels																									
*Running Surface: <table border="0"><tr><td>☐ Anti-Skid</td><td>☐ Asphalt</td><td>☐ Concrete</td><td>☒ Gravel</td></tr><tr><td>☐ N/A</td><td>☐ Timber Planks</td><td></td><td></td></tr></table>				☐ Anti-Skid	☐ Asphalt	☐ Concrete	☒ Gravel	☐ N/A	☐ Timber Planks																
☐ Anti-Skid	☐ Asphalt	☐ Concrete	☒ Gravel																						
☐ N/A	☐ Timber Planks																								
*Left Abutment: <table border="0"><tr><td>☐ Binwall</td></tr><tr><td>☐ Concrete Cast in Place</td></tr><tr><td>☐ Concrete Lock Blocks</td></tr><tr><td>☒ Concrete Precast</td></tr><tr><td>☐ Crib, Log or Timber</td></tr><tr><td>☐ Other</td></tr><tr><td>☐ Pile-Temporary Materials</td></tr><tr><td>☐ Pile-Permanent Materials</td></tr><tr><td>☐ Sill-Permanent Materials</td></tr><tr><td>☐ Sill-Temporary Materials</td></tr><tr><td>☐ Steel Pipe & Precast Pat</td></tr></table>		☐ Binwall	☐ Concrete Cast in Place	☐ Concrete Lock Blocks	☒ Concrete Precast	☐ Crib, Log or Timber	☐ Other	☐ Pile-Temporary Materials	☐ Pile-Permanent Materials	☐ Sill-Permanent Materials	☐ Sill-Temporary Materials	☐ Steel Pipe & Precast Pat	*Right Abutment: <table border="0"><tr><td>☐ Binwall</td></tr><tr><td>☐ Concrete Cast in Place</td></tr><tr><td>☐ Concrete Lock Blocks</td></tr><tr><td>☐ Concrete Precast</td></tr><tr><td>☒ Crib, Log or Timber</td></tr><tr><td>☐ Other</td></tr><tr><td>☐ Pile-Temporary Materials</td></tr><tr><td>☐ Pile-Permanent Materials</td></tr><tr><td>☐ Sill-Permanent Materials</td></tr><tr><td>☐ Sill-Temporary Materials</td></tr><tr><td>☐ Steel Pipe & Precast Pat</td></tr></table>		☐ Binwall	☐ Concrete Cast in Place	☐ Concrete Lock Blocks	☐ Concrete Precast	☒ Crib, Log or Timber	☐ Other	☐ Pile-Temporary Materials	☐ Pile-Permanent Materials	☐ Sill-Permanent Materials	☐ Sill-Temporary Materials	☐ Steel Pipe & Precast Pat
☐ Binwall																									
☐ Concrete Cast in Place																									
☐ Concrete Lock Blocks																									
☒ Concrete Precast																									
☐ Crib, Log or Timber																									
☐ Other																									
☐ Pile-Temporary Materials																									
☐ Pile-Permanent Materials																									
☐ Sill-Permanent Materials																									
☐ Sill-Temporary Materials																									
☐ Steel Pipe & Precast Pat																									
☐ Binwall																									
☐ Concrete Cast in Place																									
☐ Concrete Lock Blocks																									
☐ Concrete Precast																									
☒ Crib, Log or Timber																									
☐ Other																									
☐ Pile-Temporary Materials																									
☐ Pile-Permanent Materials																									
☐ Sill-Permanent Materials																									
☐ Sill-Temporary Materials																									
☐ Steel Pipe & Precast Pat																									
Comments:																									

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)**GENERAL INFORMATION**

(enter either long/lat or UTM - not both)

Site #	CK-2206	Structure #	CK 2206
FSR Name	North Ainslie CRK	User km	—
Project File ID		Branch	
Longitude: (ddd / mm / ss.s)	50 00 58.0	OR	UTM Zone
Latitude: (ddd / mm / ss.s)	121 22 46.9	UTM Easting	UTM Northing

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G F (P)	CAMP CUT SLOPE FAVELINER - Rd Blocked
Bridge Ahead Signs Missing	0 1 (2)	
Brushing Required	Yes (No)	
Delineator Missing Left	(0) 1 2	
Delineator Missing Right	(0) 1 2	
Fender Condition	E G F (None)	No FENDERS
Posted Load Rating (tonnes)	—	NOT POSTED
Road Surface	E G F (P)	Puddle over structure

ATV ACCESS ONLY

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Crib	E G (F) P N/A	2X F3 CLOSED FACED CRIBS BOTH ABUT
Tie-backs	E G (F) P N/A	3X CAMP, 2X WOODS
Bin Wall	E G F P (N/A)	
Precast Concrete	E G F P (N/A)	
Caps or Sills	E G (F) P	
Piles or Posts	E G F P (N/A)	
Ballast Wall	E (G) F P	
Wing Wall	E G F P (N/A)	
Bracing	E G F P (N/A)	
Hardware	E (G) F P N/A	CRIB LASHED TO TIE BACKS.
Fill	E (G) (F) P	600mm OF FILL
Riprap	E G F P (N/A)	NO RIPRAP
Bearings	E (G) F P	
Corrosion Protection	E G F P (N/A)	

HAVE POCKETS OF ROT. CONK PRESENT

Span 1 of 1 (spans are numbered consecutively starting from the left abutment)

Use "Additional Spans" Sheet for Multiple Spans

DECK

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface	E G (F) P	
Running Planks	E G F P (N/A)	
Sub-deck	E G F P (N/A)	
Ties	E G F P (N/A)	
Nails	E G F P (N/A)	
Deck to Girder Bolts	E G F P (N/A)	
Concrete Deck	E G F P (N/A)	
Grout Pockets	E G F P (N/A)	
Deck Joints	E G F P (N/A)	
Anti-skid Surface	E G F P (N/A)	
Gravel Surface	E G (F) P N/A	600mm OF FILL.
Curb Rail/Blocks/Posts	E G F P	
Handrails/Walkouts	E G F P N/A	VIS. CURB LOG NOT ADEQUATE. ITS FLUSH w/ ROAD SURFACE.
Hardware	E G F P (N/A)	OUTSIDE STRINGERS LASHED.
Overall Deck Condition	E G F P	

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)

GENERAL INFORMATION														
Site # <u>CK 2206</u>					Structure # <u>CK 2206</u>									
SUPERSTRUCTURE (stringers numbered from upstream side of bridge)														
Item		Present Condition (circle)		Comments (a comment is mandatory if condition 'Poor' is selected)										
Log Curbs		E G F <u>P</u> N/A		<u>V/S CURB NOT WORKING</u>										
Needle Beams and Shims		E G F <u>P</u> N/A												
Stringer #	Species	Peeled? (circle)	Diameter (mm) or Width x Depth (mm x mm)	Rot Depth Bottom (mm)	Rot Depth Side (mm)	Rot Depth Top (mm)	Comments							
1	SX	<u>Y</u> N	690				* Generally the old stringers are in a very poor condition. Outside stringers are either failed or rotten. Replace stringers.							
2	SX	<u>Y</u> N	500	70										
3	SX	<u>Y</u> N	560	30										
4	FD	<u>Y</u> <u>N</u>	750	0										
5	SX	<u>Y</u> <u>N</u>	450	0										
6	SX	<u>Y</u> <u>N</u>	520	10										
7	FD	<u>Y</u> <u>N</u>	570	20										
8	SX	<u>Y</u> <u>N</u>	520	0										
9	SX	<u>Y</u> <u>N</u>	630	0										
10	SX	<u>Y</u> <u>N</u>	520	0										
CHANNEL														
Est. Present Water Level Depth (m) <u>0.3</u>			Est. Present Water Level Width (m) <u>2.0</u>			Est. High Water Level Clearance (m) <u>1.4</u>								
HAZARDS (circle yes or no for each item)														
High Water?	Yes	<u>No</u>	Scour?	Yes	<u>No</u>	Ice?	Yes	<u>No</u>	Debris?	Yes	<u>No</u>	Aggradation?	Yes	<u>No</u>
Comments														
REPAIRS (H = High, M = Medium, L = Low)														
#	Priority (circle)	Estimate (\$)	Description											
1	<u>H</u> M L		REPLACE STRUCTURE.											
2	H M L													
3	H M L													
ITEMS TO MONITOR														
#	Description													
1														
2														
PHOTO LOG														
Photo #	Description	Photo #	Description											
	C TO W		D/S											
	FAILED STRINGER X		W TO C											
	CAMP CUT SLOPE		WINDY AREA											
	V/S		COMES ON SKID											
INSPECTOR TO COMPLETE THIS SECTION														
As-built Drawings Checked? Yes <u>No</u>		P Eng Inspection Required? Yes <u>No</u>		Date of Inspection (yyyy/mm/dd) <u>OCT 26 - 2009</u>										
Inspection Company Name <u>Forster Eng + Geo</u>		Inspector's Name (print) <u>Ali Sudeyhi</u>		Inspector's Signature <u>[Signature]</u>										
Comments														
PROFESSIONAL ENGINEER TO COMPLETE THIS SECTION														
Current Load Rating GWV (tonnes): <u>10 t</u>				Date of Next Inspection										
Reviewer Company Name		Reviewed by - PEng's Name (print) <u>L. Stevanovic</u>		Reviewed by - PEng's Signature		Date Reviewed (yyyy/mm/dd)								
				Digitally signed by L. Stevanovic Date: 2010.01.19 16:41:40 -08'00'										
Comments <u>5t load rating. Clean stream debris from D/S broken log stringer. Replace the bridge.</u>														

11 FD 680 0
12 SX 440 0
13 SX 550 60
14 SX 720 30
15 BROKEN + LEAKING INTO STREAM.

CAMP ABUT FROM D/S.