

INACTIVE - ATV ACCESS ONLY

2-?
Sep 2 ③



BC Ministry of
Forests and Range

Page 1 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

GENERAL	
*Structure #	*Site #: CK-2065
*Type/Class: ☐ Permanent Bridge ☒ Temporary Bridge	Crossing Name:
*Forest District: Chilliwack	Management Area:
*Forest Service Road: CHILLIWACK - TAMIAH	Kilometres: 8.3
*Project File ID#: 5127	*Br. 06
Built For: ☐ BC Timber Sales ☐ Operations Division ☐ Other Commercial Users ☐ Road Permit Holder ☐ Road Use Permit Holder	
*Source: ☐ Inherited: Found Structure ☐ Inherited: From Oil & Gas/ ☐ Inherited: Non-Status Road Other Ministry ☐ Inherited: Reallocation ☐ Inherited: Transfers from ☐ New Structure Other Ministries ☐ Replacement Structure 	
Year Built:	Year Added to Inventory:
Current Load Rating GVW (tonnes): <small>(PEng to enter / update this value on structure details screen in CBR)</small>	Design Load Rating GVW (tonnes): <small>(Typically obtained from design drawings)</small>
Design Vehicle Configuration: ☐ BCL625 ☐ CL625 ☐ L100 ☐ L120 ☐ L150 ☐ L165 ☐ L45 ☐ L60 ☐ L75 ☐ L90 ☐ Other	
*Primary User Client Number:	*Client Location Code:
Primary User Name:	
As Built Information on File? ☐ Yes ☐ No	
Installation Cost (\$):	Material Cost (\$):
REPLACEMENT DETAILS	
Original Replacement (year):	Estimated Closure (year):
Light Vehicle Traffic Replacement (year):	*Full Log Haul Traffic Replacement (year): <small>(PEng to review and evaluate inspector's estimate, and to enter /update this value on structure details screen in CBR).</small>
Estimated Replacement Cost (\$):	
Replacement Cost Comments:	

* Denotes Mandatory Information for Corporate Bridge Register

FS1344 HEG Aug 3, 2010

49 01 09.7
121 48 00.7

CK-2065

BC Ministry of
Forests and Range

Page 2 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

STRUCTURAL DETAILS			
Number of Spans: 1	Length of Spans (m) [e.g. for a 3-span bridge – 20, 35, 20] 15.1		
Number of Piers: —	Pier Type: ☐ Concrete ☐ Crib - Timber ☐ Piles - Concrete ☐ Piles - Steel ☐ Piles - Timber Treated ☐ Piles - Timber Untreated ☐ Steel Column on Concrete Pad		
Needle Beams? ☒ Yes ☒ No	Portable Structure? ☐ Yes ☒ No	Portable Superstructure Status: ☐ Installed ☐ Storage	
Portable Superstructure Storage Location:			
*Bridge Length (metres): 15.1	*Superstructure: <div style="display: flex; flex-wrap: wrap;"> <div style="width: 33%;"> ☐ Compo Girders ☐ Concrete Cast in Place ☐ Concrete Slab Girders ☒ Log Stringer ☐ Steel I-Beam ☐ Timber-Treated Stringers </div> <div style="width: 33%;"> ☐ Concrete Box Beam ☐ Concrete I/T Beam ☐ Glulam Girder ☐ Steel Box Beam ☐ Steel Truss/Bailey/Acrow ☐ Timber-Untreated Stringers </div> <div style="width: 33%;"> ☐ Rail Car ☐ Other </div> </div>		
*Deck Type: ☐ Concrete ☐ Concrete Composite ☐ Gravel ☐ Concrete Removable ☐ Concrete - Steel Free ☐ Steel ☐ Timber-Treated ☐ Timber-Untreated ☐ Other ☐ Timber-Treated Panels ☒ Timber-Untreated Panels			*Deck Width (metres): 3.9
*Running Surface: ☐ Anti-Skid ☐ Asphalt ☐ Concrete ☐ Gravel ☐ Not Available ☒ Timber Planks			
*Left Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☒ Steel Pipe & Precast Pad		*Right Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☒ Steel Pipe & Precast Pad	
Comments:			

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)**GENERAL INFORMATION**

(enter either long/lat or UTM below - not both)

*Site #: <u>CK-2065</u>	*Crossing Name:	*Type/Class: ☐ Major Culvert ☐ Woodbox/Lag Culvert	*Project File ID# <u>5127</u>
*Structure #:			*Br. <u>06</u>
*FSR Name:	*Forest District: <u>ChilliWack</u>	*Kilometres: <u>8.3</u>	User km:
Longitude: (ddd / mm / ss.s) <u>49 01 09.7</u>	☒ OR	UTM Zone	UTM Easting
Latitude: (ddd / mm / ss.s) <u>121 48 00.7</u>			UTM Northing

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.; UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G F <u>(P)</u> UR	TIGHT VERTICAL ALIG.
Bridge Ahead Signs Missing	0 1 <u>(2)</u>	
Brushing Required	<u>(Yes)</u> No	
Delinicator Missing Left	0 1 <u>(2)</u>	NOT FUNCTIONAL
Delinicator Missing Right	0 1 <u>(2)</u>	
Fender Condition	E G <u>(F)</u> P None UR	LOGS
Posted Load Rating	(tonnes) or None	NOT POSTED
Road Surface	E G F <u>(P)</u> UR	POTHLES ON APPROACHES

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Cribbs	E G F P <u>(N/A)</u> UR	
Tie-backs	E G F P <u>(N/A)</u> UR	
Bin Wall	E G F P <u>(N/A)</u> UR	
Concrete (cast in place; lock blocks, precast)	E G F P <u>(N/A)</u> UR	
Caps or Sills	E G <u>(F)</u> P N/A UR	100-200mm of ROT ON LOG SILL.
Piles or Posts	E G <u>(F)</u> P N/A UR	LOG SILL ON 3 PILES.
Ballast Wall	E G <u>(F)</u> P N/A UR	
Wing Wall	E G F P <u>(N/A)</u> UR	
Bracing	E <u>(G)</u> F P N/A UR	
Hardware	E G F P <u>(N/A)</u> UR	
Fill	E G <u>(F)</u> P N/A UR	POTHLES ON APPROACHES
Riprap	E G F P <u>(N/A)</u> UR	BEDROCK CONTROLLED
Bearings	E G <u>(F)</u> P N/A UR	
Corrosion Protection	E G F P N/A UR	

Span 1 of (spans are numbered consecutively starting from the left abutment)

Use "Additional Spans" Sheet for Multiple Spans

DECK

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E G F P <u>(N/A)</u> UR	
Running Planks	E G <u>(F)</u> P N/A UR	4" x 10" TIMBER
Sub-deck	E G F P <u>(N/A)</u> UR	
Ties	E G F <u>(P)</u> N/A UR	SAME OF TIES VERY ROTTEN. 200 x 200
Nails	E G <u>(F)</u> P N/A UR	
Deck to Girder Bolts	E G F P <u>(N/A)</u> UR	
Concrete Deck	E G F P <u>(N/A)</u> UR	
Grout Pockets	E G F P <u>(N/A)</u> UR	
Deck Joints	E G F P <u>(N/A)</u> UR	
Steel Deck Plate	E G F P <u>(N/A)</u> UR	
Gravel Surface	E G F P <u>(N/A)</u> UR	
Gravel Deck Depth	metres or N/A	
Curb Rail/Blocks/Posts	E G <u>(F)</u> P UR	LOGS LASHED TO OUTSIDE STRINGERS
Handrails/Walkouts	E G F P <u>(N/A)</u> UR	
Hardware	E G <u>(F)</u> P N/A UR	
Overall Deck Condition	E G <u>(F)</u> UR	

**Routine Condition Bridge Inspection Form**
(for log stringer or timber stringer bridges)

GENERAL INFORMATION														
*Site #: <u>06-2065</u>				*Structure #:										
SUPERSTRUCTURE (stringers numbered from upstream side of bridge)														
Item		Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)										
Log Curbs		E G F P (UR)												
Needle Beams and Shims		E G F (P) N/A UR		<u>X3 - ONLY LASHED TO OUTSIDE STRINGERS.</u>										
Stringer #	Wood Species	Peeled? (circle)	Diameter (mm) or Width x Depth (mm x mm)	Rot Depth Bottom (mm)	Rot Depth Side (mm)	Rot Depth Top (mm)	Comments							
1	CW	(Y) N	590				ROTEN							
2	Fd	Y N	670											
3		Y N	660				ROTEN							
4		Y N	760											
5		Y N	1060				VERY POOR COND - ROTEN							
6		Y N	76											
7		Y N	54				ROTEN							
8		Y N												
9		Y N												
10		Y N												
Stream CHANNEL														
*Est. Present Water Level Depth <u>0.5</u> (m)		*Est. Present Water Level Depth <u>4</u> (m)		*Est. Present Water Level Depth <u>1.6</u> (m)										
HAZARDS (circle yes or no for each item)														
High Water?	Yes	No	Scour?	Yes	No	Ice?	Yes	No	Debris?	Yes	No	Aggradation?	Yes	No
Comments														
REPAIRS: ☐ Recommended ☐ Not required (H = High, M = Medium, L = Low)														
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description											
1	(H) M L		REPLACE STRUCTURE w/ VEHICLE TRAFFIC											
2	H M L													
3	H M L													
*Monitoring Status: ☐ Recommended ☐ Not required														
Monitor Item #	*Monitor Description													
1														
2														
PHOTO LOG														
Photo #	Description	Photo #	Description											
	LEFT TO RIGHT		NEEDLE BEAM											
	RIGHT TO LEFT		RIGHT ABUTMENT											
	FROM UPSTREAM X2		LEFT ABUTMENT											
	ROTEN TIES X2													
INSPECTOR TO COMPLETE THIS SECTION														
As-built Drawings Checked? Yes ☐ No ☒		P Eng Inspection Required? Yes ☐ No ☒		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): (PEng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CDR as necessary).										
*Date of Inspection (yyyy/mm/dd) <u>2010-09-02</u>		*Inspection Company Name <u>Onsite Engineering LTD.</u>		*Inspector's Name (print) <u>Ali Sadehghi</u>										
Inspector's Comments <u>STRINGERS IN VERY POOR CONDITION & CROSS TIES ALSO ROTEN</u>		Inspector's Signature 												
PROFESSIONAL ENGINEER TO COMPLETE THIS SECTION														
Current Load Rating GVW (tonnes): (PEng to update structure details screen in CDR as necessary)			Date of Next Planned Inspection (yyyy/mm/dd)											
<u>zero</u>			<u>Not applicable</u>											
Reviewer Company Name <u>Onsite Engineering LTD</u>		Reviewed by - PE's Name (print) <u>G. Dohm</u>		Reviewed by - PE's Signature 										
Date Reviewed (yyyy/mm/dd) <u>2010/11/17</u>		PEng Reviewer's Comments <u>Close bridge by barricades or remove.</u>												



CK2065 Left to right



CK2065 Right to left



CK2065 Rotten cross tie




CK2065 Rotten cross tie 2




CK2065 From upstream



CK2065 From upstream 2



CK2065 Right abutment



CK2065 Needlebeam



CK2065 Left abutment