

ACTIVE

3

447

 BC Ministry of Forests and Range	Page 1 of 2
	Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

GENERAL	
*Structure #	*Site #: CK-2161
*Type/Class: ☒ Permanent Bridge ☐ Temporary Bridge	Crossing Name:
*Forest District: Chilliwack	Management Area:
*Forest Service Road: HUNTER EAST	Kilometres: 5.8
*Project File ID#: 6086	*Br. 01
Built For: ☒ BC Timber Sales ☐ Operations Division ☐ Other Commercial Users ☐ Road Permit Holder ☐ Road Use Permit Holder	
*Source: ☐ Inherited: Found Structure ☐ Inherited: From Oil & Gas/ ☐ Inherited: Non-Status Road Other Ministry ☐ Inherited: Reallocation ☐ Inherited: Transfers from ☐ New Structure Other Ministries ☐ Replacement Structure	
Year Built:	Year Added to Inventory:
Current Load Rating GVW (tonnes): (PEng to enter / update this value on structure details screen in CBR)	Design Load Rating GVW (tonnes): (Typically obtained from design drawings)
Design Vehicle Configuration: ☐ BCL625 ☐ CL625 ☐ L100 ☐ L120 ☐ L150 ☒ L165 ☐ L45 ☐ L60 ☐ L75 ☐ L90 ☐ Other	
*Primary User Client Number:	*Client Location Code:
Primary User Name:	
As Built Information on File? ☐ Yes ☐ No	
Installation Cost (\$):	Material Cost (\$):
REPLACEMENT DETAILS	
Original Replacement (year):	Estimated Closure (year):
Light Vehicle Traffic Replacement (year):	*Full Log Haul Traffic Replacement (year): (PEng to review and evaluate inspector's estimate, and to enter /update this value on structure details screen in CBR).
Estimated Replacement Cost (\$):	
Replacement Cost Comments:	

* Denotes Mandatory Information for Corporate Bridge Register



BC Ministry of
Forests and Range

Page 2 of 2

Corporate Bridge Register (CBR)
Structure Inventory Data Form "BRIDGES"

STRUCTURAL DETAILS			
Number of Spans:		Length of Spans (m) [e.g. for a 3-span bridge – 20, 35, 20]	
Number of Piers:		Pier Type: ☐ Concrete ☐ Crib - Timber ☐ Piles - Concrete ☐ Piles - Steel ☐ Piles - Timber Treated ☐ Piles - Timber Untreated ☐ Steel Column on Concrete Pad	
Needle Beams? ☐ Yes ☒ No		Portable Structure? ☒ Yes ☐ No	Portable Superstructure Status: ☒ Installed ☐ Storage
Portable Superstructure Storage Location:			
*Bridge Length (metres):	*Superstructure: ☐ Compo Girders ☐ Concrete Box Beam ☐ Rail Car ☐ Concrete Cast in Place ☐ Concrete I/T Beam ☐ Other ☐ Concrete Slab Girders ☐ Glulam Girder ☐ Log Stringer ☒ Steel Box Beam ☐ Steel I-Beam ☐ Steel Truss/Bailey/Acrow ☐ Timber-Treated Stringers ☐ Timber-Untreated Stringers		
*Deck Type: ☐ Concrete ☐ Concrete Composite ☐ Gravel ☐ Concrete Removable ☐ Concrete - Steel Free ☒ Steel ☐ Timber-Treated ☐ Timber-Untreated ☐ Other ☐ Timber-Treated Panels ☐ Timber-Untreated Panels			*Deck Width (metres):
*Running Surface: ☒ Anti-Skid ☐ Asphalt ☐ Concrete ☐ Gravel ☐ Not Available ☐ Timber Planks			
*Left Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☒ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☐ Steel Pipe & Precast Pad		*Right Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☒ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☐ Steel Pipe & Precast Pad	
Comments:			

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION				(enter either long/lat or UTM below - not both)			
*Site #: CK-2161	*Crossing Name:	*Type/Class: ☐ Temporary bridge ☒ Permanent bridge	*Project File ID# 6086				
*Structure #:			*Br. 01				
*FSR Name: HUNTER EAST	*Forest District: Chilliwack	*Kilometres: 1.3	User km: 5.8				
Longitude: (ddd / mm / ss.s) 49 19 34.3	OR	UTM Zone	UTM Easting	UTM Northing			
Latitude: (ddd / mm / ss.s) 121 31 48.							
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.; UR = Unrated							
Item	Present Condition (circle or fill-in)		Comments (a comment is mandatory if condition "Poor" is selected)				
Alignment	E G F (P) UR		TIGHT HORIZONTAL ANGLE ON RIGHT APPROACH.				
Bridge Ahead Signs Missing	0 1 (2)		POOR VISIBILITY				
Brushing Required	Yes (No)						
Delineator Missing Left	0 (1) 2		ON THE RIGHT ABUT.				
Delineator Missing Right	0 (1) 2						
Fender Condition	E (G) F P None UR		NO POST BARRIERS				
Posted Load Rating	— (tonnes) or None		NOT POSTED				
Road Surface	E G (F) P UR						
LEFT/RIGHT ABUTMENTS (as seen facing downstream)							
Item	Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)				
Log/Timber Cribs	E G F P (N/A) UR						
Tie-backs	E G F P (N/A) UR						
Bin Wall	E G F P (N/A) UR						
Concrete (cast in place; lock blocks, precast)	E G F P (N/A) UR		TIMBER ON RIGHT ABUT.				
Caps or Sills	E G F (P) (N/A) UR		TREATED SILL THE BEARING PLATE ON RIGHT ABUT				
Piles or Posts	E G F P N/A UR		DOESN'T BEAR ENTIRELY ON SILL.				
Ballast Wall	E (G) F P N/A UR		100%				
Wing Wall	E G F P (N/A) UR		LEFT SILL IS				
Bracing	E G F P (N/A) UR		ROTATED & SHOWS				
Hardware	E G F P (N/A) UR		SIGNS OF COMPRESSION				
Fill	E G (F) P N/A UR		FAILURE.				
Riprap	E G F (P) N/A UR		RIP RAP STACKED ALMOST VERTICALLY. THE TOE ON LEFT ABUT				
Bearings	E G F (P) N/A UR		BEARING PLATE DOESN'T BEAR ENTIRELY ON SILL.				
Corrosion Protection	E G F P N/A UR		STARTING TO SCORING.				
Span 1 of 1 (spans are numbered consecutively starting from the left abutment)							
Use "Additional Spans" Sheet for Multiple Spans							
DECK							
Item	Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)				
Running Surface (N/A if running surface is gravel or timber planks)	E G (F) P N/A UR						
Running Planks	E G F P (N/A) UR						
Sub-deck	E G F P (N/A) UR						
Ties	E G F P (N/A) UR						
Nails	E G F P (N/A) UR						
Deck to Girder Bolts	E G F P (N/A) UR						
Concrete Deck	E G F P (N/A) UR						
Grout Pockets	E G F P (N/A) UR						
Deck Joints	E G F P (N/A) UR						
Steel Deck Plate	E G (F) P N/A UR		FINE SEDIMENTS ON DECK.				
Gravel Surface	E G F P (N/A) UR						
Gravel Deck Depth	— metres or N/A						
Curb Rail/Blocks/Posts	E (G) F P UR		STEEL.				
Handrails/Walkouts	E G F P (N/A) UR						
Hardware	E (G) F P N/A UR						
Overall Deck Condition	E (G) F P UR						

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION				
*Site #: <u>CL-216</u>		*Structure #:		
SUPERSTRUCTURE				
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)		
Girders	E (G) F P UR	PORTABLE STEEL		
Diaphragms	E G F P N/A UR			
Bracing	E G F P N/A UR	} CAN'T SEE.		
Under-trussing	E G F P N/A UR			
Hardware	E G F P N/A UR			
Welded / Grouted Shear Connectors	E G F P N/A UR			
Stream CHANNEL				
*Est. Present Water Level Depth ____ (m)		*Est. Present Water Level Depth ____ (m)		
HAZARDS (circle yes or no for each item)				
High Water?	Yes (No)	Scour?	Yes (No)	
Ice?	Yes (No)	Debris?	Yes (No)	
Aggradation?				Yes (No)
Comments <u>TBE IF RIP RAP ON LEFT ABUT.</u>				
REPAIRS: ☐ Recommended ☐ Not required (H = High, M = Medium, L = Low)				
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description	
1	H M (L)		REPLACE LEFT ABUT TIMBER SILL.	
2	(H) M L		DELUSATORS + NARROW STRUCTURE SIGNS.	
3	H M L			
*Monitoring Status: ☐ Recommended ☐ Not required				
Monitor Item #	*Monitor Description			
1	RIP RAP AT VERY STEEP ANGLE. FOOTINGS CAN EASILY BE EXPOSED WITHOUT			
2	ADEQUATE RIP RAP			
PHOTO LOG				
Photo #	Description	Photo #	Description	
	Left to Right		BEARING PLATE X 2	
	From Downstream		RIGHT ABUT	
	Right to Left		LEFT ABUT SCOUR	
	LEFT ABUT		LEFT SILL. X 2	
INSPECTOR TO COMPLETE THIS SECTION				
As-built Drawings Checked?	P Eng Inspection Required? Yes (No)		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year):	
Yes (No)			(P Eng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)	
*Date of Inspection (yyyy/mm/dd)	*Inspection Company Name	*Inspector's Name (print)	Inspector's Signature	
2010-08-17	Onsite Engineering Ltd	Ali Sadeghi		
Inspector's Comments				
PROFESSIONAL ENGINEER (P Eng) TO COMPLETE THIS SECTION				
Current Load Rating GWW (tonnes):		Date of Next Planned Inspection (yyyy/mm/dd)		
62		2011/09/01		
(P Eng to update structure details screen in CBR as necessary)				
Reviewer Company Name	Reviewed by - P Eng's Name (print)	Reviewed by - P Eng's Sign	Date Reviewed (yyyy/mm/dd)	
Onsite Engineering LTD	G. Dohm		2010/10/29	
P Eng Reviewer's Comments				
Portable bridge TCH0501. L165 superstructure.				

* Denotes Mandatory Information for Corporate Bridge Register

Bearing support is only partial at one end and is poor. Sill plate is rotting at other end. Riprap needs work. Bridge needs to be reinstalled asap. Continued current rating is provided for short term only to enable continued industrial traffic until re-installation is completed.

FS1337B HEG Aug 3, 2010



CK2161 Left to right



CK2161 Right to left



CK2161 From downstream



CK2161 Structure ID



CK2161 Poor bearing



CK2161 Poor bearing2



CK2161 Left abutment



CK2161 Left abutment scour




CK2161 Left abutment scour 2



CK2161 Right abutment



CK2161 From upstream



CK2161 Structure ID2



CK2161 Rotten sill left abutment



CK2161 Rotten sill left abutment2