

CK 2166

ACTIVE

BC Ministry of
Forests and Range

Page 2 of 2

Bridge Register Structure Inventory Data Form BRIDGES

CK 2166

STRUCTURAL DETAILS

Number of Spans:

1

Needle Beams?

☐ Yes☒ NoLength of Spans (m)
[e.g. for a 3-span bridge
- 20, 35, 20]

16.0

Portable Structure?

☐ Yes☒ NoPortable Superstructure
Status:☐ Installed☐ Storage

Portable Superstructure Storage Location:

*Bridge Length
(metres):

16.0

16.3

*Superstructure:

☐ Compo Girders☐ Concrete Cast in Place☒ Concrete Slab Girders☐ Log Stringer☐ Rail Car☐ Steel I-Beam☐ Timber-Treated Stringers☐ Concrete Box Beam☐ Concrete I/T Beam☐ Glulam Girder☐ Other☐ Steel Box Beam☐ Steel Truss/Bailey/Acrow☐ Timber-Untreated Stringers

*Deck Type:

☒ Concrete☐ Concrete Removable☐ Other☐ Steel Free☐ Timber-Treated Panels☐ Timber-Untreated Panels☐ Concrete Composite☐ Gravel☐ Steel☐ Timber-Treated☐ Timber-Untreated

*Deck Width (metres):

4³

*Running Surface:

☐ Anti-Skid☒ N/A☐ Asphalt☐ Timber Planks☐ Concrete☐ Gravel

*Left Abutment:

☐ Binwall☒ Concrete Cast in Place☐ Concrete Lock Blocks☐ Concrete Precast☐ Crib, Log or Timber☐ Other☐ Pile-Temporary Materials☐ Pile-Permanent Materials☐ Sill-Permanent Materials☐ Sill-Temporary Materials☐ Steel Pipe & Precast Pat

*Right Abutment:

☐ Binwall☒ Concrete Cast in Place☐ Concrete Lock Blocks☐ Concrete Precast☐ Crib, Log or Timber☐ Other☐ Pile-Temporary Materials☐ Pile-Permanent Materials☐ Sill-Permanent Materials☐ Sill-Temporary Materials☐ Steel Pipe & Precast Pat

Comments:

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION				(enter either long/lat or UTM - not both)		
Site #	CK 2166			Structure #		
FSR Name	LOSTCRK FSR			User km	50	Project File ID
Longitude: (ddd / mm / ss.s)	49 18 56.2			OR	UTM Zone	UTM Easting
Latitude: (ddd / mm / ss.s)	122 14 54.5					UTM Northing
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl.						
Item	Present Condition (circle or fill-in)		Comments (a comment is mandatory if condition "Poor" is selected)			
Alignment	E G F <u>P</u>		VERY TIGHT VER. CURVE ON RIGHT APPROACH			
Bridge Ahead Signs Missing	<u>0</u> 1 2					
Brushing Required	Yes <u>No</u>					
Delinicator Missing Left	<u>0</u> 1 2					
Delinicator Missing Right	<u>0</u> 1 2					
Fender Condition	E <u>G</u> F P None		CONCRETE NO POST BARRIERS			
Posted Load Rating (tonnes)	55					
Road Surface	E G <u>P</u>		LARGE POTHOLE ON LEFT APPROACH.			
LEFT/RIGHT ABUTMENTS (as seen facing downstream)						
Item	Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)			
Log/Timber Cribs	E G F P <u>N/A</u>					
Tie-backs	E G F P <u>N/A</u>					
Bin Wall	E G F P <u>N/A</u>					
Precast Concrete	E G F P <u>N/A</u>					
Cap or Sills	E <u>G</u> F P		CONCRETE CRACK IN PLACE.			
Piles or Posts	E G F P <u>N/A</u>					
Ballast Wall	E G <u>P</u>		TREATED TIMBER			
Wing Wall	E G F P <u>N/A</u>					
Bracing	E G F P <u>N/A</u>					
Hardware	E G F P <u>N/A</u>					
Fill	E <u>G</u> F P					
Riprap	E <u>G</u> F P <u>N/A</u>		BEP ROCK CONTROLLED ON LEFT ABUTMENT.			
Bearings	E <u>G</u> F P					
Corrosion Protection	E G F P <u>N/A</u>					
Span 1 of <u>1</u> (spans are numbered consecutively starting from the left abutment)						
Use "Additional Spans" Sheet for Multiple Spans						
DECK						
Item	Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)			
Running Surface	E G <u>F</u> P					
Running Planks	E G F P <u>N/A</u>					
Sub-deck	E G F P <u>N/A</u>					
Ties	E G F P <u>N/A</u>					
Nails	E G F P <u>N/A</u>					
Deck to Girder Bolts	E G F P <u>N/A</u>					
Concrete Deck	E G <u>F</u> P <u>N/A</u>		SOME MELL. DAMAGE TO RUNNING SURFACE			
Grout Pockets	E G F P <u>N/A</u>					
Deck Joints	E G F P <u>N/A</u>					
Anti-skid Surface	E G F P <u>N/A</u>					
Gravel Surface	E G F P <u>N/A</u>					
Curb Rail/Blocks/Posts	E G <u>F</u> P		DAMAGED + ROTTEN RISERS			
Handrails/Walkouts	E G F P <u>N/A</u>					
Hardware	E <u>G</u> F P <u>N/A</u>					
Overall Deck Condition	E G <u>F</u> P					

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION			
Site # <u>CK-2166</u>		Structure #	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E G <u>F</u> P		
Diaphragms	E G F P <u>N/A</u>		
Bracing	E G F P <u>N/A</u>		
Under-trussing	E G F P <u>N/A</u>		
Hardware	E G F P <u>N/A</u>		
Cracks/Checks in Glulam Girders	E G F P <u>N/A</u>		
Concrete	E G <u>F</u> P <u>N/A</u>		
Shear Connectors	E G F P <u>N/A</u>		
Grout Pockets	E G F P <u>N/A</u>		
CHANNEL			
Est. Present Water Level Depth (m) <u>0.2</u>		Est. Present Water Level Width (m) <u>2.5</u>	Est. High Water Level Clearance (m) <u>3.0</u>
HAZARDS (circle yes or no for each item)			
High Water?	Yes <u>No</u>	Scour?	Yes <u>No</u>
Ice?	Yes <u>No</u>	Debris?	Yes <u>No</u>
Aggradation?	Yes <u>No</u>		
Comments			
REPAIRS (H = High, M = Medium, L = Low)			
#	Priority (circle)	Estimate (\$)	Description
1	H M L		
2	H M L		
3	H M L		
ITEMS TO MONITOR			
#	Description		
1	POTHOLES ON RIGHT APPROACH, -> CONTINUOUS EROSION DECK COULD BE DAMAGED.		
2	DOWNSTREAM LEFT ABUTMENT: STEEP FULL SLOPE SIGNIFYING MONITOR.		
PHOTO LOG			
Photo #	Description	Photo #	Description
	LEFT TO RIGHT		FROM DIS
	LEFT ABUT		DAMAGED RAIL
	RIGHT ABUT		PUT HOLE
	FROM DIS		RIGHT TO LEFT
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked? Yes <u>No</u>		P Eng Inspection Required? Yes <u>No</u>	Date of Inspection (yyyy/mm/dd) <u>2010-08-09</u>
Inspection Company Name <u>Onsite Engineering Ltd.</u>		Inspector's Name (print) <u>ALI SADEGH</u>	Inspector's Signature <u>[Signature]</u>
Comments			
PROFESSIONAL ENGINEER (P Eng) TO COMPLETE THIS SECTION			
Current Load Rating GWV (tonnes): <u>55</u>		Date of Next Inspection <u>2013/09/01</u>	
Reviewer Company Name <u>MNRO</u>	Reviewed by - P Eng's Name (print) <u>G. Dohm</u>	Reviewed by - P Eng's Signature <u>[Signature]</u>	Date Reviewed (yyyy/mm/dd) <u>2010/11/30</u>
Comments			



CK2166 Damage rail



CK2166 Left to right



CK2166 potholes



CK2166 Load limit sign



CK2166 From upstream



CK2166 Left abutment



CK2166 From downstream



CK2166 Right abutment



CK2166 Right to left