

(1)

ACTIVE

411
Sep 10



BC Ministry of
Forests and Range

Page 1 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

GENERAL	
*Structure # <u>CK- 2278</u>	*Site #:
*Type/Class: ☒ Permanent Bridge ☐ Temporary Bridge	Crossing Name:
*Forest District: <u>Chilliwack</u>	Management Area:
*Forest Service Road: <u>STAVE RIVER</u>	Kilometres: <u>8.8</u>
*Project File ID#: <u>B013</u>	*Br. <u>01</u>
Built For: ☐ BC Timber Sales ☐ Operations Division ☐ Other Commercial Users ☐ Road Permit Holder ☐ Road Use Permit Holder	
*Source: ☐ Inherited: Found Structure ☐ Inherited: From Oil & Gas/ Other Ministry ☐ Inherited: Non-Status Road ☐ Inherited: Transfers from Other Ministries ☐ Inherited: Reallocation ☐ New Structure ☐ Replacement Structure	
Year Built:	Year Added to Inventory:
Current Load Rating GVW (tonnes): <small>(PEng to enter / update this value on structure details screen in CBR)</small>	Design Load Rating GVW (tonnes): <small>(Typically obtained from design drawings)</small>
Design Vehicle Configuration: ☐ BCL625 ☐ CL625 ☐ L100 ☐ L120 ☐ L150 ☐ L165 ☐ L45 ☐ L60 ☒ L75 ☐ L90 ☐ Other	
*Primary User Client Number:	*Client Location Code:
Primary User Name:	
As Built Information on File? ☐ Yes ☐ No	
Installation Cost (\$):	Material Cost (\$):
REPLACEMENT DETAILS	
Original Replacement (year):	Estimated Closure (year):
Light Vehicle Traffic Replacement (year):	*Full Log Haul Traffic Replacement (year): <small>(PEng to review and evaluate inspector's estimate, and to enter /update this value on structure details screen in CBR).</small>
Estimated Replacement Cost (\$):	
Replacement Cost Comments:	

* Denotes Mandatory Information for Corporate Bridge Register

AL 2278



BC Ministry of
Forests and Range

Page 2 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

STRUCTURAL DETAILS			
Number of Spans: 1	Length of Spans (m) [e.g. for a 3-span bridge – 20, 35, 20] 29.6		
Number of Piers: —	Pier Type: ☐ Concrete ☐ Crib - Timber ☐ Piles - Concrete ☐ Piles - Steel ☐ Piles - Timber Treated ☐ Piles - Timber Untreated ☐ Steel Column on Concrete Pad		
Needle Beams? ☐ Yes ☒ No	Portable Structure? ☐ Yes ☒ No	Portable Superstructure Status: ☐ Installed ☐ Storage	
Portable Superstructure Storage Location:			
*Bridge Length (metres): (30.4) (100')	*Superstructure: ☐ Compo Girders ☐ Concrete Box Beam ☐ Rail Car ☐ Concrete Cast in Place ☐ Concrete I/T Beam ☐ Other ☐ Concrete Slab Girders ☐ Glulam Girder ☐ Log Stringer ☐ Steel Box Beam ☒ Steel I-Beam ☐ Steel Truss/Bailey/Acrow ☐ Timber-Treated Stringers ☐ Timber-Untreated Stringers		
*Deck Type: ☐ Concrete ☐ Concrete Composite ☐ Gravel ☒ Concrete Removable ☐ Concrete - Steel Free ☐ Steel ☐ Timber-Treated ☐ Timber-Untreated ☐ Other ☐ Timber-Treated Panels ☐ Timber-Untreated Panels			*Deck Width (metres): 4.9
*Running Surface: ☐ Anti-Skid ☐ Asphalt ☒ Concrete ☐ Gravel ☐ Not Available ☐ Timber Planks			
*Left Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☒ Steel Pipe & Precast Pad		*Right Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☒ Steel Pipe & Precast Pad	
Comments:			

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION				(enter either long/lat or UTM below -- not both)			
*Site #: 2278	*Crossing Name:	*Type/Class: ☒ Temporary bridge ☒ Permanent bridge	*Project File ID#			*Br.	
*Structure #:							
*FSR Name: STAVE RIVER	*Forest District: Chilliwack	*Kilometres: 8.0	User km:				
Longitude: (ddd / mm / ss.s) 47 28 38.6	OR	UTM Zone	UTM Easting	UTM Northing			
Latitude: (ddd / mm / ss.s) 122 14 20.1							
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated							
Item	Present Condition (circle or fill-in)		Comments (a comment is mandatory if condition "Poor" is selected)				
Alignment	E G <u>(F)</u> P UR						
Bridge Ahead Signs Missing	0 1 <u>(2)</u>						
Brushing Required	Yes <u>(No)</u>						
Delineator Missing Left	<u>(0)</u> 1 2						
Delineator Missing Right	<u>(0)</u> 1 2						
Fender Condition	E G <u>(F)</u> P None UR		DOWN STREAM, RIGHT ABUT NO POST BARRIER NO LONGER IN PLACE DUE TO FILL SLOPE FAILURE				
Posted Load Rating	(tonnes) or <u>(None)</u>		NOT POSTED				
Road Surface	E G <u>(F)</u> P UR						
LEFT/RIGHT ABUTMENTS (as seen facing downstream)							
Item	Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)				
Log/Timber Cribs	E G F P <u>(N/A)</u> UR						
Tie-backs	E G F P <u>(N/A)</u> UR						
Bin Wall	E G F P <u>(N/A)</u> UR						
Concrete (cast in place; lock blocks, precast)	E G F P <u>(N/A)</u> UR						
Caps or Sills	E G F P <u>(N/A)</u> UR						
Piles or Posts	E G <u>(F)</u> P N/A UR		PIPE RISERS, DOWNSTREAM RIGHT ABUT PIPE, EXPOSED AS RIP RAP IS ERODED DUE TO STREAM SPEED.				
Ballast Wall	E G <u>(F)</u> P N/A UR		PRE CAST CONCRETE				
Wing Wall	E G F P <u>(N/A)</u> UR						
Bracing	E G <u>(F)</u> P N/A UR						
Hardware	E G <u>(F)</u> P N/A UR						
Fill	E G <u>(F)</u> P N/A UR						
Riprap	E G <u>(F)</u> P N/A UR		RIP RAP ON RIGHT ABUT ERODING.				
Bearings	E G <u>(F)</u> P N/A UR		RUBBER PADS				
Corrosion Protection	E G <u>(F)</u> P N/A UR						
Span 1 of (spans are numbered consecutively starting from the left abutment)							
Use Additional Spans Sheet for Multiple Spans							
DECK							
Item	Present Condition (circle)		Comments (a comment is mandatory if condition "Poor" is selected)				
Running Surface (N/A if running surface is gravel or timber planks)	E G <u>(F)</u> P N/A UR						
Running Planks	E G F P <u>(N/A)</u> UR						
Sub-deck	E G F P <u>(N/A)</u> UR						
Ties	E G F P <u>(N/A)</u> UR						
Nails	E G F P <u>(N/A)</u> UR						
Deck to Girder Bolts	E G <u>(F)</u> P N/A UR						
Concrete Deck	E G <u>(F)</u> P N/A UR		10 x CONCRETE PANNELS				
Grout Pockets	E G F P <u>(N/A)</u> UR						
Deck Joints	E G <u>(F)</u> P N/A UR		JOINT SEALAND FALLING APART				
Steel Deck Plate	E G F P <u>(N/A)</u> UR						
Gravel Surface	E G F P <u>(N/A)</u> UR						
Gravel Deck Depth	metres or <u>(N/A)</u>						
Curb Rail/Blocks/Posts	E G <u>(F)</u> P UR						
Handrails/Walkouts	E G F P <u>(N/A)</u> UR						
Hardware	E G <u>(F)</u> P N/A UR						
Overall Deck Condition	E G <u>(F)</u> P UR						

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION			
*Bridg # <u>CK-2278</u>		*Structure #	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E G <u>F</u> P UR	2 x STEEL - BEAM L-75	
Diaphragms	E G F P <u>N/A</u> UR		
Bracing	E G <u>F</u> P N/A UR		
Under-trussing	E G F P <u>N/A</u> UR		
Hardware	E G <u>F</u> P N/A UR		
Welded / Grouted Shear Connectors	E G F P N/A UR		
Stream CHANNEL			
*Est. Present Water Level Depth <u>2.0</u> (m)		*Est. Present Water Level Depth <u>2.0</u> (m)	
HAZARDS (circle yes or no for each item)			
High Water?	Yes <u>No</u>	Scour?	Yes <u>No</u>
Ice?	Yes <u>No</u>	Debris?	Yes <u>No</u>
Aggradation?	Yes <u>No</u>		
Comments			
REPAIRS: ☐ Recommended ☐ Not required (H=High, M=Medium, L=Low)			
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	<u>H</u> M L		REINSTALL DOWNSTREAM FENDER
2	<u>H</u> M L		BARK FILL DOWNSTREAM FILL SLOPE
3	H M L		
Monitoring Status: ☐ Recommended ☐ Not required			
Monitor Item #	*Monitor Description		
1	RIGHT ABUT RIP RAP		
2			
PHOTO LOG			
Photo #	Description	Photo #	Description
	LEFT TO RIGHT		FROM DOWNSTREAM
	RIGHT TO LEFT		RIGHT ABUT
	DOWNSTREAM EROSION		LEFT ABUT
	FROM UPSTREAM		UNDERNEATH
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked?	P Eng Inspection Required?	Inspector's Estimate of Full Log Haul Traffic Replacement Date (year):	
Yes <u>No</u>	Yes <u>No</u>	(P Eng to review and evaluate Inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)	
*Date of Inspection (yyyy/mm/dd)	*Inspection Company Name	*Inspector's Name (print)	Inspector's Signature
2010-09-10	On the Edge	Ali Sadeghi	
Inspector's Comments			
RIP RAP ON RIGHT ABUT & FILL SLOPE IS ERODING.			
PROFESSIONAL ENGINEER (P Eng) TO COMPLETE THIS SECTION			
Current Load Rating GWW (tonnes):	Date of Next Planned Inspection (yyyy/mm/dd)		
68	2011/09/01		
Reviewer Company Name	Reviewed by - P Eng's Name (print)	Reviewed by - P Eng's Sign	Date Reviewed (yyyy/mm/dd)
MNRO	G. Dohm		2010/12/07
P Eng Reviewer's Comments			
Repair fill slope failure asap. Also attend to adding riprap to exposed post on pads.			



CK2278 Right to left



CK2278 Left to right



CK2278 scour...



CK22278 From upstream



CK22278 Structure ID



CK22278 From downstream



CK2278 Right abutment



CK2278 Left abutment



CK2278 Underneath