

Sep 3

INACTIVE BARRICADED - DUE TO ROCK SLIDE - BIKE ACCESS ONLY.

BC Ministry of
Forests and Range

Page 1 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

GENERAL	
*Structure #	*Site #: CK-2286
*Type/Class: ☒ Permanent Bridge ☐ Temporary Bridge	Crossing Name:
*Forest District: Chilliwack	Management Area:
*Forest Service Road: TSILEWIT CRK	Kilometres: 17.7
*Project File ID#: 7978	*Br. 01
Built For: ☐ BC Timber Sales ☐ Operations Division ☐ Other Commercial Users ☐ Road Permit Holder ☐ Road Use Permit Holder	
*Source: ☐ Inherited: Found Structure ☐ Inherited: From Oil & Gas/ ☐ Inherited: Non-Status Road Other Ministry ☐ Inherited: Reallocation ☐ Inherited: Transfers from ☐ New Structure Other Ministries ☐ Replacement Structure	
Year Built:	Year Added to Inventory:
Current Load Rating GVW (tonnes): (PEng to enter / update this value on structure details screen in CBR)	Design Load Rating GVW (tonnes): (Typically obtained from design drawings)
Design Vehicle Configuration: ☐ BCL625 ☐ CL625 ☐ L100 ☐ L120 ☐ L150 ☐ L165 ☐ L45 ☐ L60 ☐ L75 ☐ L90 ☐ Other	
*Primary User Client Number:	*Client Location Code:
Primary User Name:	
As Built Information on File? ☐ Yes ☐ No	
Installation Cost (\$):	Material Cost (\$):
REPLACEMENT DETAILS	
Original Replacement (year):	Estimated Closure (year):
Light Vehicle Traffic Replacement (year):	*Full Log Haul Traffic Replacement (year): (PEng to review and evaluate inspector's estimate, and to enter /update this value on structure details screen in CBR).
Estimated Replacement Cost (\$):	
Replacement Cost Comments:	

* Denotes Mandatory Information for Corporate Bridge Register



BC Ministry of
Forests and Range

Page 2 of 2

Corporate Bridge Register (CBR) Structure Inventory Data Form "BRIDGES"

CK-2286

STRUCTURAL DETAILS			
Number of Spans: <u>1</u>	Length of Spans (m) [e.g. for a 3-span bridge – 20, 35, 20] <u>13.3</u>		
Number of Piers: <u>—</u>	Pier Type: ☐ Concrete ☐ Crib - Timber ☐ Piles - Concrete ☐ Piles - Steel ☐ Piles - Timber Treated ☐ Piles - Timber Untreated ☐ Steel Column on Concrete Pad		
Needle Beams? ☐ Yes ☒ No	Portable Structure? ☐ Yes ☒ No	Portable Superstructure Status: ☐ Installed ☐ Storage	
Portable Superstructure Storage Location:			
*Bridge Length (metres): <u>14.0</u>	*Superstructure: ☐ Compo Girders ☐ Concrete Box Beam ☐ Rail Car ☐ Concrete Cast in Place ☐ Concrete I/T Beam ☐ Other ☐ Concrete Slab Girders ☐ Glulam Girder ☐ Log Stringer ☐ Steel Box Beam ☒ Steel I-Beam ☐ Steel Truss/Bailey/Acrow ☐ Timber-Treated Stringers ☐ Timber-Untreated Stringers		
*Deck Type: ☐ Concrete ☐ Concrete Composite ☐ Gravel ☐ Concrete Removable ☐ Concrete - Steel Free ☐ Steel ☐ Timber-Treated ☐ Timber-Untreated ☐ Other ☒ Timber-Treated Panels ☐ Timber-Untreated Panels			*Deck Width (metres): <u>A. 0</u>
*Running Surface: ☐ Anti-Skid ☐ Asphalt ☐ Concrete ☐ Gravel ☐ Not Available ☒ Timber Planks			
*Left Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☒ Steel Pipe & Precast Pad		*Right Abutment: ☐ Binwall ☐ Concrete Cast in Place ☐ Concrete Lock Blocks ☐ Concrete Precast ☐ Crib, Log or Untreated Timber ☐ Other ☐ Pile-Temporary Materials ☐ Pile-Permanent Materials ☐ Sill-Permanent Materials ☐ Sill-Temporary Materials ☒ Steel Pipe & Precast Pad	
Comments:			

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION				(enter either long/lat or UTM below – not both)			
*Site #: <u>CK 2286</u>	*Crossing Name:	*Type/Class: ☐ Temporary bridge ☒ Permanent bridge	*Project File ID# <u>7978</u>				
*Structure #:			*Br. <u>01</u>				
*FSR Name: <u>TSILEUH CRK</u>	*Forest District: <u>Chilliwack</u>	*Kilometres: <u>17.7</u>	User km:				
Longitude: (ddd / mm / ss.s) <u>49 45 08.9</u>	☒ OR ☐ UTM	UTM Zone	UTM Easting	UTM Northing			
Latitude: (ddd / mm / ss.s) <u>121 30 47.6</u>							
LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated							
Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)					
Alignment	E G <u>(P)</u> P UR						
Bridge Ahead Signs Missing	0 1 <u>(2)</u>						
Brushing Required	Yes <u>(No)</u>						
Delineator Missing Left	0 <u>(1)</u> 2						
Delineator Missing Right	<u>(0)</u> 1 2						
Fender Condition	E G <u>(P)</u> P None UR	<u>LOG</u>					
Posted Load Rating	(tonnes) or <u>(None)</u>	<u>NOT POSTED</u>					
Road Surface	E G <u>(P)</u> P UR	<u>SMALL PATCHES ON APPROACHES</u>					
LEFT/RIGHT ABUTMENTS (as seen facing downstream)							
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)					
Log/Timber Cribbs	E G F P <u>(N/A)</u> UR						
Tie-backs	E G F P <u>(N/A)</u> UR						
Bin Wall	E G F P <u>(N/A)</u> UR						
Concrete (cast in place; lock blocks, precast)	E G F P <u>(N/A)</u> UR						
Caps or Sills	E G F P <u>(N/A)</u> UR						
Piles or Posts	E <u>(G)</u> F P <u>(N/A)</u> UR	<u>TIMBER</u>					
Ballast Wall	E G <u>(F)</u> P <u>(N/A)</u> UR	<u>OLD LOGS SOME ROT.</u>					
Wing Wall	E <u>(G)</u> F P <u>(N/A)</u> UR						
Bracing	E <u>(G)</u> F P <u>(N/A)</u> UR						
Hardware	E <u>(G)</u> F P <u>(N/A)</u> UR						
Fill	E G <u>(P)</u> P <u>(N/A)</u> UR						
Riprap	E <u>(G)</u> F P <u>(N/A)</u> UR	<u>WELL RIPRAPED.</u>					
Bearings	E <u>(G)</u> F P <u>(N/A)</u> UR						
Corrosion Protection	E G <u>(P)</u> P <u>(N/A)</u> UR						
Span 1 of 1 (spans are numbered consecutively starting from the left abutment) Use "Additional Spans" Sheet for Multiple Spans							
DECK							
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)					
Running Surface (N/A if running surface is gravel or timber planks)	E <u>(G)</u> F P <u>(N/A)</u> UR						
Running Planks	E <u>(G)</u> F P <u>(N/A)</u> UR	<u>TIMBER 4" x 12"</u>					
Sub-deck	E <u>(G)</u> F P <u>(N/A)</u> UR	<u>TIMBER TREATED (4" x ?)</u>					
Ties	E <u>(G)</u> F P <u>(N/A)</u> UR	<u>TIMBER TREATED (8" x 12")</u>					
Nails	E <u>(G)</u> F P <u>(N/A)</u> UR						
Deck to Girder Bolts	E G F P <u>(N/A)</u> UR						
Concrete Deck	E G F P <u>(N/A)</u> UR						
Grout Pockets	E G F P <u>(N/A)</u> UR						
Deck Joints	E G F P <u>(N/A)</u> UR						
Steel Deck Plate	E G F P <u>(N/A)</u> UR						
Gravel Surface	E G F P <u>(N/A)</u> UR						
Gravel Deck Depth	metres or <u>(N/A)</u>						
Curb Rail/Blocks/Posts	E <u>(G)</u> F P UR						
Handrails/ Walkouts	E G F P <u>(N/A)</u> UR						
Hardware	E <u>(G)</u> F P <u>(N/A)</u> UR						
Overall Deck Condition	E <u>(G)</u> F P UR	<u>SMALL AMOUNT OF DEBRIS ON RUNNING SURFACE</u>					

**Routine Condition Bridge Inspection Form**
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION			
*Site #: CK - 2286		*Structure #:	
SUPERSTRUCTURE			
Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)	
Girders	E (G) F P UR	2x STEEL 1-BEAMS - WEATH STEEL	
Diaphragms	E G F P (N/A) UR		
Bracing	E (G) F P (N/A) UR		
Under-trussing	E G F P (N/A) UR		
Hardware	E (G) F P (N/A) UR		
Welded / Grouted Shear Connectors	E G F P (N/A) UR		
Stream CHANNEL			
*Est. Present Water Level Depth 0.3 (m)		*Est. Present Water Level Depth 3 (m)	*Est. Present Water Level Depth 3+ (m)
HAZARDS (circle yes or no for each item)			
High Water?	Yes (No)	Scour?	Yes (No)
Ice?	Yes (No)	Debris?	Yes (No)
Aggradation?	Yes (No)		
Comments			
REPAIRS: ☐ Recommended ☐ Not required (H = High, M = Medium, L = Low)			
Repair Item #	*Priority (circle)	*Estimate (\$)	*Repair Description
1	H M L		
2	H M L		
3	H M L		
*Monitoring Status: ☐ Recommended ☐ Not required			
Monitor Item #	*Monitor Description		
1			
2			
PHOTO LOG			
Photo #	Description	Photo #	Description
	RIGHT TO LEFT		UNDERNEATH
	LEFT TO RIGHT		LEFT ABUT.
	FROM UPSIDE DOWN		FROM DOWNSTREAM.
	RIGHT ABUT.		
INSPECTOR TO COMPLETE THIS SECTION			
As-built Drawings Checked? Yes (No)		P Eng Inspection Required? Yes (No)	
		Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): (P Eng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)	
*Date of Inspection (yyyy/mm/dd)	*Inspection Company Name	*Inspector's Name (print)	Inspector's Signature
2011-09-03	Onsite Engineering Ltd	Ali Sadeghi	
Inspector's Comments			
THIS SITE CAN NOT BE ACCESSED WITH AN ATV. ONLY VIA BIKE. DUE TO NUMBER OF CUTSLOPE FAILURES WITH VERY NARROW GAPS BETWEEN BOULDER			
PROFESSIONAL ENGINEER (PEng) TO COMPLETE THIS SECTION			
Current Load Rating GVW (tonnes): 68		Date of Next Planned Inspection (yyyy/mm/dd) 2012/09/01	
(PEng to update structure details screen in CBR as necessary)			
Reviewer Company Name	Reviewed by - PEng's Name (print)	Reviewed by - PEng's Signature	Date Reviewed (yyyy/mm/dd)
Onsite Engineering LTD MNRO	G. Dohm		2011/06/30
PEng Reviewer's Comments			
Barricaded due to rock slide - not accessible			

* Denotes Mandatory Information for Corporate Bridge Register except by motor bike.

L75 design vehicle or 68 tonnes.



CK2286 Right to left



CK2286 Left to right



CK2286 Right abutment



CK2286 Underneath



CK2286 Left abutment



CK2286 From upstream



CK2286 From downstream